



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2020 RENAULT MEGANE

PE | 79,645 KM

VIN: VF1LRREX8LR564376

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Running Lights

This car has a Running lights



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort










Power driver seat

Basic Details

| | | | |
|--|-------------------|---|-----------------------|
|  Kilometers | 79645 |  Specs | Yes |
|  Engine | 1.6L |  Option Type | Basic |
|  Transmission | Automatic |  Drive | Front Wheel Drive |
|  Body Type | SEDAN |  Fuel | Petrol |
|  Wheel Type | Steel Wheels |  Exterior Color | Exterior Color Silver |
|  Interior Trim | Fabric Trim |  Number of Airbags | 2 Airbags |
|  Seating Capacity | 5 Seats |  Number of keys | 2 Keys |
|  VIN number | VF1LRREX8LR564376 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | | |
|---|--|---|---|
|  Exteriors | | | |
| Fog Light Front | |  |  |
| Running Lights | | | |
| Halogen Headlights | |  | |
|  Comfort & Convenience | | | |
| Cruise Control | |  |  |
| Steering Mounted Audio Controls | | | |
| Rear Defogger | |  |  |
| Central Armrest | | | |



Entertainment

Bluetooth Player



USB player



Safety & Security

Airbag Driver Front



ABS



Central Locking



Child Safety Locking






150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior



Doors condition

| | | | |
|---|---|---|---|
| Front left door Handle: Paint Chip-off < 5mm |  | Front right door |  |
| Rear left door Panel: Scratch < 50mm |  | Rear right door Panel: Light Scuffing < 50mm, Low Visual Dent < 30mm |  |

Fenders Condition

| | | | |
|--|---|--------------|---|
| Left Fender Condition: Paint Chip-off < 5mm, Scratch < 50mm |  | Right Fender |  |
|--|---|--------------|---|


Quarter Panels Condition

| | | | |
|---|---|---|---|
| Left Quarter Panel Condition: Scratch < 50mm |  | Right Quarter Panel Condition: Dent < 30mm, Paint Chip-off < 5mm |  |
|---|---|---|---|


Front Bumper Condition

| | |
|--------------|---|
| Front Bumper |  |
|--------------|---|


Rear Bumper Condition

| | |
|---|---|
| Rear Bumper Rear Bumper: Light Scuffing < 80mm |  |
|---|---|

Hood Condition

| | |
|--------------------------------------|---|
| Hood Bonnet: Paint Chip-off < 5mm |  |
|--------------------------------------|---|

Trunk Condition

| | |
|---|---|
| Trunk Door Trim: Light Scuffing < 50mm |  |
|---|---|

Trunk conditon

| | |
|-------|---|
| Trunk |  |
|-------|---|

Roof Condition

| | |
|------|---|
| Roof |  |
|------|---|

| | | | |
|------------------------------|---|--|---|
| Pillars Condition | | | |
| Left A Pillar | ✓ | Right A Pillar | ✓ |
| Left A to B Pillar Beading | ✓ | Right A to B Pillar Beading | ✓ |
| Right A to B Pillar | ✓ | Left B Pillar | ✓ |
| Left B Pillar Trim | ✓ | Left B to C Pillar Beading | ✓ |
| Right C Pillar Trim | ✓ | Right B to C Pillar | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar | ✓ |
| Running Board Condition | | | |
| Left Running Board | ✓ | Right Running Board | ⚠ |
| | | Rear Right Floor Trim: Light Scuffing < 80mm | |
| Windshield Condition | | | |
| Front Windshield | ✓ | Rear Windshield | ✓ |
| Structural Assessment | | | |
| Chassis Condition | ✓ | Radiator Support | ✓ |
| Apron | ✓ | Boot Floor | ✓ |
| Firewall Condition | ✓ | Cowl Top | ✓ |
| Head Light Support Condition | ✓ | | |
| Cowl Top | | | |
| Cowl Top | ✓ | | |
| Rear View Mirror Condition | | | |
| Left Hand Side Mirror | ✓ | Left Side Mirror | ✓ |
| Right Side Mirror | ✓ | Right Hand Side Mirror | ✓ |
| Alloy Wheel/ Rim | | | |
| Spare Alloy/ Rim Condition | ✓ | | |
| Wheel Arch | ✓ | Wheel cover | ⚠ |
| | | Front Right: Face/ Scuffs < 50mm | |
| Antenna | ✓ | Grill Condition | ⚠ |
| | | Light Scuffing < 50mm | |
| Monogram | ✓ | Window Glass | ✓ |

| | | |
|------------------|---|--|
| Wiper | ✓ | |
| Panel Condition | | |
| Rear Trunk Panel | ! | |
| Scratch < 50mm | | |

Engine & Transmission

| | | |
|--------------------------------|---|----------------------|
| Engine | | |
| Engine Body | ✓ | Engine Performance ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System ✓ |
| Radiator Condition | ✓ | Radiator Coolant ✓ |
| Battery | | |
| Battery Terminal & Tightness | ✓ | |
| Fuel System | | |
| Fuel Tank | ✓ | |
| Transmission Operation | | |
| Gear Shifting | ✓ | Drive Axle ✓ |
| Transmission Fluid | ✓ | |

Steering, Suspension & Brakes

| | | |
|------------------------|---|-------------------------|
| Steering | | |
| Steering wheel | ✓ | |
| Brake System | | |
| Parking Brake | ✓ | Brake Master Cylinder ✓ |
| Brake Disc & Brake Pad | ✓ | Brake Fluid ✓ |
| Pedals | ✓ | |
| Suspension | | |
| Shock Absorbers | ✓ | |

Electricals, Controls & Lights

| | | |
|------|--|--|
| Keys | | |
|------|--|--|

| | | | |
|---------------------------|---|-----------------------------------|---|
| Master Key | ✓ | Spare Key(s) | ✓ |
| Door Locks | | | |
| Child Safety Locking | ✓ | | |
| Dashboard | | | |
| Instrument Panel | ✓ | | |
| Airbags | | | |
| Airbags | ✓ | | |
| Controls | ✓ | Cruise Control | ✓ |
| Infotainment Display | ✓ | Engine Sensors | ✓ |
| OBD Connector | ✓ | Music System | ✓ |
| Lights | | | |
| Headlight | ✓ | Interior Lights | ✓ |
| Tail Light Cluster | ✓ | Turn Signal Lights | ✓ |
| Daylight Running Lights | | License Plate Light | ✓ |
| Right DRL: Low Brightness | ! | | |
| Fog Lights | ✓ | | |
| Air Conditioning | | | |
| AC Cooling | ✓ | AC Switch | ✓ |
| AC System Leaks | ✓ | Center AC Vent | ! |
| | | Adjuster Clip Crack/Fair Use Wear | |
| Front Right AC Vent | ✓ | Heater | ✓ |
| Rear Defogger | ✓ | USB Charging Port | ✓ |
| Power/ Manual Windows | ✓ | | |

Interiors & Luggage

| | | | |
|--------------------------------|---|--|---|
| Dashboard And Instrument Panel | ✓ | Central Console | ! |
| | | Cigarette Lighter: Cigarette Lighter Missing | |
| Cup Holder | ✓ | Glove Box | ✓ |

| | | | |
|--|---|----------------------|---|
| Steering Wheel | ! | Sunvisor | ✓ |
| Steering Wheel Fair Use Wear | | | |
| Seat Upholstery | ! | Manual Seat Movement | ✓ |
| Rear Right Seat: Leather/ Fabric Fair Use Wear | | | |
| Seat Belts | ✓ | Head Rest | ✓ |
| Door Controls And Trim | ✓ | Grab Handle | ✓ |
| Carpet | ! | Headliner | ✓ |
| Trunk Floor Carpet: Wear & Tear < 80mm | | | |
| Rear View Mirror | ✓ | Toolkit | ✓ |

Tyres

| | | | |
|----------------------------|------|---------------------------|------|
| Tyres Condition | | | |
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre | ✓ | | |
| Tyres Depth (Remaining) | | | |
| LHS Front Tyre | <75% | LHS Rear Tyre | <85% |
| RHS Front Tyre | <75% | RHS Rear Tyre | <85% |
| Spare Tyre | <90% | | |



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE