



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2021 MAZDA 3

EVOLVE | 35,870 KM

VIN: JM7BPAS76M1114076

Car highlights



Great condition

Car has low imperfections



Cruise control

Cruise control to drive with ease & comfort



Apple play
















Enjoy your drive with apple play



Amazing Comfort










Power driver seat



Basic Details

 Kilometers	35870	 Specs	Yes
 Engine	2.0L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Fabric Trim	 Number of Airbags	7 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	JM7BPAS76M1114076		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Climate Control AC		Cruise Control	
Rear Armrest with cupholder		Steering Mounted Audio Controls	
Rear Defogger		Central Armrest	
Steering Column Adjuster			
 Safety & Security			

Parking Sensors Rear	✓	Reverse Camera	✓
Traction Control	✓	Airbag Curtain Shield	✓
Airbag Knees	✓	Airbag Driver Front	✓
ABS	✓	Central Locking	✓
Child Safety Locking	✓		
 Entertainment			
Bluetooth Player	✓	Apple Play	✓
Android Auto Play	✓	Infotainment System	✓
USB player	✓		
 Exteriors			
LED Headlights	✓		

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 



Exterior

Doors condition

Front left door		Front right door	
-----------------	---	------------------	---

Rear left door		Rear right door	
----------------	---	-----------------	---

Fenders Condition

Left Fender		Right Fender	
		Condition: Light Scuffing < 50mm, Paint Chip-off < 5mm	

Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
--------------------	---	---------------------	---

Front Bumper Condition

Front Bumper	
--------------	---

Rear Bumper Condition

Rear Bumper	
-------------	---

Hood Condition

Hood	
------	---

Trunk Condition

Trunk	
-------	---

Trunk conditon

Trunk	
-------	---

Roof Condition

Roof	
------	---

Pillars Condition

Left A Pillar		Right A Pillar	
---------------	---	----------------	---

Left A to B Pillar Beading		Right A to B Pillar Beading	
----------------------------	---	-----------------------------	---

Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Grill Condition	✓	Monogram	✓
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel	✓		



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Cruise Control	✓
Heads Up Display	✓	Infotainment Display	✓
OBD Connector	✓	Navigation System	!
		Condition: Available - SD Card Missing	
Music System	✓		
Sunroof Operation			
Sunroof	✓		
Camera	✓		
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	License Plate Light	✓
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓		
Rear Defogger	✓	USB Charging Port	✓
Power/ Manual Windows	✓		

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisor	✓

Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<65%	LHS Rear Tyre	<65%
RHS Front Tyre	<65%	RHS Rear Tyre	<65%
Spare Tyre	<45%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE