



### RTA Standards

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

### 1 Months Warranty

Enjoy peace of mind for your car purchase

### Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.





**2015 MITSUBISHI LANCER EX**

**GLX | 180,713 KM**

VIN: JMYSTCY4AFU740061

### **Car highlights**



#### **Great Parking Assistance**

Reverse Camera



#### **Bluetooth**

Enjoy your drive with bluetooth



#### **Music System**
















Enjoy your drive with music system



#### **Amazing Comfort**










Power driver seat

Basic Details

 Kilometers	180713	 Specs	Yes
 Engine	2.0L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Steel Wheels	 Exterior Color	Exterior Color Silver
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	JMYSTCY4AFU740061		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

<div> Safety &amp; Security</div>					
Reverse Camera		<div></div>	Traction Control		<div></div>
Airbag Driver Front		<div></div>	ABS		<div></div>
Central Locking		<div></div>	Child Safety Locking		<div></div>
<div><div></div>Comfort &amp; Convenience</div>					
Rear Defogger		<div></div>			



## Entertainment

Bluetooth Player



Infotainment System



## Exteriors

Halogen Headlights



# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

#### Front left door

Moulding: Paint Chip-off < 5mm



#### Front right door

Moulding: Paint Chip-off < 5mm, Light Scuffing < 50mm



#### Rear left door

Frame: Scratch < 50mm, Paint Chip-off < 5mm



#### Rear right door

Frame: Light Scuffing < 50mm



### Fenders Condition

#### Left Fender

Condition: Dent < 30mm, Scratch < 50mm, Paint Chip-off < 5mm



#### Right Fender

Right Fender: Dent < 30mm, Scratch < 50mm, Paint Chip-off < 5mm



### Quarter Panels Condition

#### Left Quarter Panel

Condition: Dent < 30mm, Scratch < 50mm, Paint Chip-off < 5mm



#### Right Quarter Panel

Condition: Dent < 30mm, Scratch < 50mm, Paint Chip-off < 5mm



### Front Bumper Condition

#### Front Bumper



### Rear Bumper Condition

#### Rear Bumper

Rear Bumper: Chip< 8mm



### Hood Condition

#### Hood

Bonnet: Low Visibility Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm



### Trunk Condition

#### Trunk



### Trunk conditon

#### Trunk



### Roof Condition

Roof	✓		
Pillars Condition			
Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	!	Left B Pillar	!
Low Visual Dent < 30mm		Condition: Dent < 30mm	
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	!
		Dent < 30mm	
Running Board Condition			
Left Running Board	✓	Right Running Board	!
		Front Right Sill Trim: Light Scuffing < 80mm	
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Wheel cover	✓
Antenna	✓	Grill Condition	!
		Light Scuffing < 50mm	

Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel			
Dent < 30mm	!		

## Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

## Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			
Shock Absorbers	✓		

## Electricals, Controls & Lights

Keys			
Master Key	✓		
Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Infotainment Display	✓
Engine Sensors	✓	OBD Connector	✓
Navigation System		Music System	✓
Condition: Available - Google Map Only	!		
Camera	✓		
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Turn Signal Lights	✓
License Plate Light	✓	Fog Lights	✓
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Power/ Manual Windows	✓		

## Interiors & Luggage

Dashboard And Instrument Panel			
Dashboard Upholstery: Minor Scuffing/ Disfiguration/ Melted	!	Central Console	✓
Cup Holder	✓	Glove Box	✓



Steering Wheel	✓	Sunvisor Left: Sunvisor LHS Minor Disfiguration, Sunvisor RHS Minor Disfiguration	⚠
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim Front Left Door: Light Scuffing	⚠	Grab Handle	✓
Carpet	✓	Headliner Front Left: Light Smudge/Disfiguration	⚠
Rear View Mirror	✓	Toolkit	✓

## Tyres

### Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
---------------------------	---	--------------------------	---

Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
----------------------------	---	---------------------------	---

Spare Tyre	✓
------------	---

### Tyres Depth (Remaining)

LHS Front Tyre	<85%	LHS Rear Tyre	<85%
----------------	------	---------------	------

RHS Front Tyre	<85%	RHS Rear Tyre	<85%
----------------	------	---------------	------

Spare Tyre	<55%
------------	------



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE