



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2016 AUDI A3

30 TFSI | 103,259 KM

VIN: WAUUYCFF1GA110516

Car highlights



Supercharger/turbocharger

This car has a Supercharger/turbocharger



Cruise control

Cruise control to drive with ease & comfort



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort










Power driver seat



Basic Details

| | | | |
|--|-------------------|---|----------------------|
|  Kilometers | 103259 |  Specs | Yes |
|  Engine | 1.4L |  Option Type | Basic |
|  Transmission | Automatic |  Drive | Front Wheel Drive |
|  Body Type | HATCHBACK |  Fuel | Petrol |
|  Wheel Type | Alloy Wheels |  Exterior Color | Exterior Color White |
|  Interior Trim | Leather Trim |  Number of Airbags | 7 Airbags |
|  Seating Capacity | 5 Seats |  Number of keys | 2 Keys |
|  VIN number | WAUUYCFF1GA110516 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | | |
|--|---|----------------------|---|
|  Comfort & Convenience | | | |
| Climate Control AC |  | Cruise Control |  |
| Steering Mounted Audio Controls |  | Rear Defogger |  |
| Central Armrest |  | Automatic Headlights |  |
| Steering Column Adjuster |  | | |
|  Exteriors | | | |

| | | | |
|--|---|----------------------|---|
| Fog Light Front | ✓ | Running Lights | ✓ |
| Rear Bumper Spoiler | ✓ | HID Headlights | ✓ |
|  Safety & Security | | | |
| Parking Sensors Front | ✓ | Parking Sensors Rear | ✓ |
| Reverse Camera | ✓ | Traction Control | ✓ |
| Airbag Curtain Shield | ✓ | Airbag Knees | ✓ |
| Airbag Driver Front | ✓ | ABS | ✓ |
| Central Locking | ✓ | Child Safety Locking | ✓ |
|  Entertainment | | | |
| Bluetooth Player | ✓ | Infotainment System | ✓ |





150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

| | | | |
|-----------------|---|---|---|
| Front left door |  | Front right door Panel: Paint Chip-off < 5mm |  |
| Rear left door |  | Rear right door Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm |  |

Fenders Condition

| | | | |
|-------------|---|--------------|---|
| Left Fender |  | Right Fender |  |
|-------------|---|--------------|---|

Quarter Panels Condition

| | | | |
|--------------------|--|---------------------|--|
| Left Quarter Panel |  | Right Quarter Panel |  |
|--------------------|--|---------------------|--|

Front Bumper Condition

| | |
|--------------|---|
| Front Bumper |  |
|--------------|---|

Rear Bumper Condition

| | |
|------------------------------------|---|
| Rear Bumper |  |
| Rear Bumper: Light Scuffing < 80mm | |

Hood Condition

| | |
|------------------------------|---|
| Hood |  |
| Bonnet: Paint Chip-off < 5mm | |







Trunk Condition

| | |
|-------|---|
| Trunk |  |
|-------|---|

Trunk conditon

| | |
|-------|---|
| Trunk |  |
|-------|---|

Pillars Condition

| | | | |
|----------------------------|---|-----------------------------|---|
| Left A Pillar |  | Right A Pillar |  |
| Left A to B Pillar Beading |  | Right A to B Pillar Beading |  |
| Right A to B Pillar |  | Left B Pillar |  |

| | | | |
|--|---|------------------------------|---|
| Left B Pillar Trim | ✓ | Left B to C Pillar Beading | ✓ |
| Right C Pillar Trim | ✓ | Right B to C Pillar | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar | ✓ |
| Running Board Condition | | | |
| Left Running Board | ✓ | Right Running Board | ✓ |
| Windshield Condition | | | |
| Front Windshield | | | |
| Condition: Driver Side/Stone Chip Mark<5mm, Passenger Side/Stone Chip Mark<8mm | ! | Rear Windshield | ✓ |
| Structural Assessment | | | |
| Chassis Condition | ✓ | Apron | ✓ |
| Boot Floor | ✓ | Firewall Condition | ✓ |
| Cowl Top | | Head Light Support Condition | ✓ |
| Beading: Crack/Fair Use Wear<50mm | ! | | |
| Cowl Top | | | |
| Cowl Top | ✓ | | |
| Rear View Mirror Condition | | | |
| Left Hand Side Mirror | ✓ | Left Side Mirror | ✓ |
| Right Side Mirror | ✓ | | |
| Alloy Wheel/ Rim | | | |
| Left Front Alloy/ Rim | ✓ | Left Rear Alloy/ Rim | ✓ |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ✓ |
| Spare Alloy/ Rim Condition | ✓ | | |
| Wheel cover | ✓ | Antenna | ✓ |
| Grill Condition | | Monogram | ✓ |
| Light Scuffing < 50mm | ! | | |
| Window Glass | ✓ | Wiper | ✓ |
| Panel Condition | | | |
| Rear Trunk Panel | ✓ | | |



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Turbocharger/ Supercharger



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Buttons Faded

Door Locks

Child Safety Locking



| | | | |
|--|---|---------------------------|---|
| Dashboard | | | |
| Instrument Panel | ✓ | | |
| Airbags | | | |
| Airbags | ✓ | | |
| Controls | ✓ | Cruise Control | ✓ |
| Infotainment Display | ✓ | OBD Connector | ✓ |
| Navigation System | ! | Music System | ✓ |
| Condition: Available - SD Card Missing | | | |
| Camera | ✓ | | |
| Lights | | | |
| Headlight | | Interior Lights | ✓ |
| Left Washer: Not Working | ! | | |
| Tail Light Cluster | ✓ | Daylight Running Lights | ! |
| | | Right DRL: Low Brightness | |
| License Plate Light | ✓ | Fog Lights | ✓ |
| Air Conditioning | | | |
| AC Cooling | ✓ | AC Switch | ✓ |
| AC System Leaks | ✓ | Center AC Vent | ✓ |
| Front Right AC Vent | ✓ | Heater | ✓ |
| Rear Blower Switch | ✓ | | |
| Rear Defogger | ✓ | USB Charging Port | ✓ |
| Power/ Manual Windows | ✓ | | |

Interiors & Luggage

| | | | |
|--------------------------------|---|--|---|
| Dashboard And Instrument Panel | ✓ | Central Console | ! |
| | | Cigarette Lighter: Cigarette Lighter Missing | |
| Cup Holder | ✓ | Glove Box | ✓ |
| Steering Wheel | ! | Sunvisor | ✓ |
| Steering Wheel Fair Use Wear | | | |

Seat Upholstery

Driver Seat: Minor Smudge/ Cracks, Minor
Fair Wear/Fade off



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim



Grab Handle



Carpet



Headliner



Rear View Mirror



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<75%

LHS Rear Tyre

<75%

RHS Front Tyre

<75%

RHS Rear Tyre

<75%

Spare Tyre

<45%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE