



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2021 NISSAN ALTIMA

SV | 44,285 KM

Car highlights



Manufacturer warranty

Till 09/06/2026 or 1,50,000 km (Not Verified)



Adaptive cruise control

Adaptive cruise control to drive with ease & comfort



Apple play

Enjoy your drive with apple play



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	44285	 Specs	Yes
 Engine	2.5L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Blue
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	1N4BL4A94MN347107		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Safety & Security			
Adaptive cruise control		Parking Sensors Rear	
Reverse Camera		Blind Spot Monitor	
Collision Warning System		Traction Control	
Airbag Driver Front		ABS	
Central Locking		Child Safety Locking	



Comfort & Convenience

Climate Control AC	✓	Cruise Control	✓
Rear Armrest with cupholder	✓	Steering Mounted Audio Controls	✓
Rear Defogger	✓	Central Armrest	✓
Remote Engine Start	✓	Automatic Headlights	✓
Steering Column Adjuster	✓		



Exteriors

Fog Light Front	✓	Halogen Headlights	✓
-----------------	---	--------------------	---



Entertainment

Bluetooth Player	✓	Apple Play	✓
Android Auto Play	✓	USB Charging Port	✓
Infotainment System	✓	USB player	✓

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front left door



Front right door

Panel: Low Visibility Dent < 30mm, Light



Scuffing < 50mm

Rear left door



Rear right door

Panel: Paint Chip-off < 5mm, Light Scuffing <



50mm

Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood



Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	
		Condition: Light Scuffing < 80mm, Low Visual	!
		Dent < 50mm	
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Antenna	✓	Grill Condition	
		Light Scuffing < 50mm	!
Monogram	✓	Window Glass	✓

Wiper



Panel Condition

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel			
Airbags			
Airbags			
Controls		Cruise Control	
Infotainment Display		OBD Connector	
Radar (If Equipped)		Music System	
Sunroof Operation			
Sunroof			
Lights			
Headlight		Interior Lights	
Tail Light Cluster		License Plate Light	
Fog Lights			
Air Conditioning			
AC Cooling			
AC Temperature: Temp in Idling/Drive < 14°C		AC Switch	
AC System Leaks		Center AC Vent	
Front Right AC Vent		Heater	
Rear Blower Switch			
Parking Sensors		Rear Defogger	
USB Charging Port		Power/ Manual Windows	

Interiors & Luggage

Dashboard And Instrument Panel		Central Console	
Cup Holder		Glove Box	
Steering Wheel		Sunvisor	
Seat Upholstery		Manual Seat Movement	

Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<65%	LHS Rear Tyre	<65%
RHS Front Tyre	<65%	RHS Rear Tyre	<65%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE