



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2018 MITSUBISHI MONTERO SPORT GLS TOP | 38,736 KM

VIN: MMEMC71X8JH007890

Car highlights



Low Mileage

This car has been driven less than 15,000 km a year



Adaptive cruise control

Adaptive cruise control to drive with ease & comfort



Bluetooth


Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat

Basic Details



Specs and features


The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Safety & Security			
Adaptive cruise control	✓	Parking Sensors Front	✓
Parking Sensors Rear	✓	Reverse Camera	✓
Blind Spot Monitor	✓	Collision Warning System	✓
Traction Control	✓	Airbag Curtain Shield	✓
Airbag Knees	✓	Airbag Driver Front	✓


ABS	✓	Central Locking	~
Child Safety Locking	~		
© Comfort & Convenience			
Climate Control AC	✓	Cruise Control	~
Rear Armrest with cupholder	~	Steering Mounted Audio Controls	•
Power Folding Mirrors	✓	Rear Defogger	✓
Central Armrest	✓		
Exteriors			
Fog Light Front	~	Roof Rails	~
Running Lights	~	Rear Bumper Spoiler	~
Halogen Headlights	~		
Performance			
Paddle Shift	~	Hill Descent Control	~
Differential Locks	~		
□ Entertainment			
Bluetooth Player	~	USB Charging Port	~
Infotainment System	✓	USB player	✓

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Wheel cover	✓	Antenna	✓
Grill Condition Light Scuffing < 50mm	(!)	Monogram	✓
Window Glass	✓	Wiper	✓
Panel Condition			



Dashboard And Instrument Panel



Central Console

(!)

Box: Minor Crack/Fair Use Wear/ Scuffing

Cup Holder	✓	Glove Box	•
Steering Wheel	•	Sunvisor	•
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	~
Carpet	•	Headliner Rear Left: Smudge/Disfiguration	(!)
Rear View Mirror	✓	Toolkit	✓
Tyres			
Tyres Condition			
Tyres Condition Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	•
	✓	Left Hand Side Rear Tyre Right Hand Side Rear Tyre	
Left Hand Side Front Tyre			
Left Hand Side Front Tyre Right Hand Side Front Tyre			✓✓
Left Hand Side Front Tyre Right Hand Side Front Tyre Spare Tyre	<85%		<85%
Left Hand Side Front Tyre Right Hand Side Front Tyre Spare Tyre Tyres Depth (Remaining)	<85% <85%	Right Hand Side Rear Tyre	<85% <85%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE