



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2015 KIA SPORTAGE

EX | 130,787 KM

## Car highlights



### Panoramic Roof

This car has a panoramic roof



### Cruise control

Cruise control to drive with ease & comfort



### Bluetooth

Enjoy your drive with bluetooth



### Amazing Comfort

Power driver seat

## Basic Details

|  |                          |   |                              |
|--|--------------------------|---|------------------------------|
|  Kilometers       | <b>130787</b>            |  Specs             | <b>Yes</b>                   |
|  Engine           | <b>2.4L</b>              |  Option Type       | <b>Semi Loaded</b>           |
|  Transmission     | <b>Automatic</b>         |  Drive             | <b>All Wheel Drive</b>       |
|  Body Type        | <b>SUV</b>               |  Fuel              | <b>Petrol</b>                |
|  Wheel Type       | <b>Alloy Wheels</b>      |  Exterior Color    | <b>Exterior Color Silver</b> |
|  Interior Trim    | <b>Fabric Trim</b>       |  Number of Airbags | <b>2 Airbags</b>             |
|  Seating Capacity | <b>5 Seats</b>           |  Number of keys    | <b>1 Keys</b>                |
|  VIN number      | <b>KNAPC8127F7623987</b> |   |                              |

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|  <b>Exteriors</b>                 |   |                             |   |
|--|---|-----------------------------|---|
| Fog Light Front  |  | Roof Rails                  |  |
| Running Lights   |  | Rear Bumper Spoiler         |  |
| Halogen Headlights   |  |                             |   |
|  <b>Comfort &amp; Convenience</b> |   |                             |   |
| Cruise Control   |  | Rear Armrest with cupholder |  |

|                                 |   |                       |   |
|---------------------------------|---|-----------------------|---|
| Steering Mounted Audio Controls |   | Power Folding Mirrors |   |
| Rear Defogger                   |  | Central Armrest       |  |
| Automatic Headlights            |  |                       |   |



### Safety & Security

|                      |   |                      |   |
|----------------------|---|----------------------|---|
| Navigation           |  | Parking Sensors Rear |  |
| Reverse Camera       |  | Airbag Driver Front  |  |
| ABS                  |  | Central Locking      |  |
| Child Safety Locking |  |                      |   |



### Performance

|                    |   |  |
|--------------------|---|--|
| Differential Locks |  |  |
|--------------------|---|--|



### Entertainment

|                  |   |                     |   |
|------------------|---|---------------------|---|
| Bluetooth Player |  | Infotainment System |  |
| USB player       |  |                     |   |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## 🚗 Exterior

Doors condition

Front left door



Front right door



Panel: Low Visibility Dent < 30mm, Light

Scuffing < 50mm, Paint Chip-off < 5mm

Rear left door



Rear right door



Panel: Scratch < 50mm, Dent < 30mm

Frame: Light Scuffing < 50mm

Fenders Condition

Left Fender



Right Fender



Right Fender: Paint Chip-off < 5mm

Quarter Panels Condition

Left Quarter Panel

Condition: Dent < 30mm, Paint Chip-off < 5mm



Right Quarter Panel



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper

Rear Bumper: Dent < 50mm, Light Scuffing < 80mm



Hood Condition

Hood

Bonnet: Low Visibility Dent < 30mm, Paint Chip-off < 5mm



Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

|  |   |   |
|--|---|---|
| Roof   |   |   |
| Roof Moulding Condition: Colour fade                     | ! |   |
| Pillars Condition  |   |   |
| Left A Pillar  | ✓ | Right A Pillar  |
| Left A to B Pillar Beading<br>Beading Crack/ Tear > 5mm  | ! | Right A to B Pillar Beading                             |
| Right A to B Pillar                                      | ✓ | Left B Pillar<br>Condition: Dent < 30mm, Scratch < 50mm |
| Left B Pillar Trim                                       | ✓ | Left B to C Pillar Beading                              |
| Right C Pillar Trim                                      | ✓ | Right B to C Pillar                                     |
| Right B to C Pillar Beading<br>Beading Crack/ Tear > 5mm | ! | Left C Pillar   |
| Running Board Condition                                  |   |   |
| Left Running Board                                       | ✓ | Right Running Board<br>Condition: Light Scuffing < 80mm |
| Windshield Condition                                     |   |   |
| Front Windshield   | ✓ | Rear Windshield   |
| Structural Assessment                                    |   |   |
| Chassis Condition  | ✓ | Radiator Support  |
| Apron  | ✓ | Boot Floor  |
| Firewall Condition                                       | ✓ | Cowl Top  |
| Head Light Support Condition                             | ✓ |   |
| Cowl Top   |   |   |
| Cowl Top   | ✓ |   |
| Rear View Mirror Condition                               |   |   |
| Left Hand Side Mirror                                    | ✓ | Left Side Mirror  |
| Right Side Mirror<br>Body: Scratch < 50mm                | ! | Right Hand Side Mirror                                  |
| Alloy Wheel/ Rim   |   |   |
| Left Front Alloy/ Rim                                    | ✓ | Left Rear Alloy/ Rim<br>Rim: Alloy Face/ Scuff < 50mm   |
| Right Front Alloy/ Rim                                   | ✓ | Right Rear Alloy/ Rim                                   |
| Spare Alloy/ Rim Condition                               | ✓ |   |

|                  |   |                       |   |
|------------------|---|-----------------------|---|
| Wheel Arch       | ✓ | Wheel cover           | ✓ |
| Antenna          | ✓ | Grill Condition       | ! |
|                  |   | Light Scuffing < 50mm |   |
| Monogram         | ✓ | Window Glass          | ✓ |
| Wiper            | ✓ |                       |   |
| Panel Condition  |   |                       |   |
| Rear Trunk Panel |   |                       | ! |
| Dent > 30mm      |   |                       |   |

## ⌚ Engine & Transmission

|                                |   |                    |   |
|--------------------------------|---|--------------------|---|
| Engine                         |   |                    |   |
| Engine Body                    | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System     | ✓ |
| Radiator Condition             | ✓ | Radiator Coolant   | ✓ |
| Battery                        |   |                    |   |
| Battery Terminal & Tightness   | ✓ |                    |   |
| Fuel System                    |   |                    |   |
| Fuel Cap                       | ✓ | Fuel Tank          | ✓ |
| Transmission Operation         |   |                    |   |
| Gear Shifting                  | ✓ | Drive Axle         | ✓ |
| 4*4 Condition (If Applicable)  | ✓ | Transmission Fluid | ✓ |

## ⌚ Steering, Suspension & Brakes

|                       |   |                        |   |
|-----------------------|---|------------------------|---|
| Steering              |   |                        |   |
| Steering wheel        | ✓ |                        |   |
| Brake System          |   |                        |   |
| Brake Master Cylinder | ✓ | Brake Disc & Brake Pad | ✓ |
| Brake Fluid           | ✓ |                        |   |
| Pedals                | ✓ |                        |   |

Suspension

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Music System



Sunroof Operation

Sunroof



Lights

Headlight



Left: Light Scuff Marks < 50mm

Interior Lights



Tail Light Cluster

Left Tail Lamp: Light Scuffing < 50mm, Crack



/ Fair Use Wear < 5mm

Turn Signal Lights



Daylight Running Lights



License Plate Light



Fog Lights

Right Fog Light: Condensation In Lamps



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Fair Use Wear

Heater



Rear Blower Switch



Parking Sensors



Rear Defogger



USB Charging Port



Power/ Manual Windows



## Interiors & Luggage

Dashboard And Instrument Panel



Central Console



Box: Minor Crack/Fair Use Wear/ Scuffing

Cup Holder



Glove Box



Steering Wheel



Sunvisor



Steering Wheel Fair Use Wear

Seat Upholstery



Manual Seat Movement



Driver Seat: Minor Fair Wear/Fade off

Seat Belts



Head Rest



Door Controls And Trim



Grab Handle



Front Left Door: Light Scuffing

Carpet



Headliner



Rear View Mirror



Toolkit



## Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Life remaining

LHS Front Tyre

<85%

LHS Rear Tyre

<75%

RHS Front Tyre

<85%

RHS Rear Tyre

<75%

Spare Tyre

<65%



**A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE