



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2015 HYUNDAI ACCENT

GLS | 60,302 KM

VIN: KMHCT41B1FU817955

Car highlights



Sunroof

This car has a sunroof



Amazing Comfort

Power driver seat



Tilt Steering wheel

Tilt steering wheel for extra comfort

Basic Details

 Kilometers	60302	 Specs	Yes
 Engine	1.4L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Grey
 Interior Trim	Fabric Trim	 Number of Airbags	1 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	KMHCT41B1FU817955		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience	
Sunroof	
Steering Mounted Audio Controls	
 Exteriors	
Fog Light Front	
 Safety & Security	

Parking Sensors Rear



Entertainment

USB Charging Port



Infotainment System



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front left door



Front right door



Handle: Paint Chip-off < 5mm

Rear left door



Rear right door



Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm

Fenders Condition

Left Fender



Right Fender



Condition: Low Visual Dent < 30mm, Paint Chip-off < 5mm

Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Light Scuffing < 80mm, Crack/

Misaligned

Hood Condition

Hood



Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition			
VIN Plate: minor imperfection	!	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim		Left Rear Alloy/ Rim	
Rim: Alloy Face/ Scuff < 50mm	!	Rim: Alloy Edge/ Scuff < 80mm	!
Right Front Alloy/ Rim		Right Rear Alloy/ Rim	
Rim: Alloy Face/ Scuff < 50mm	!	Rim: Alloy Face/ Scuff < 50mm	!
Spare Alloy/ Rim Condition	✓		
Wheel cover	✓	Antenna	✓

Grill Condition	✓	Monogram	✓
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel			✓

⌚ Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

🌐 Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			
Shock Absorbers	✓		

⚡ Electricals, Controls & Lights

Keys

Master Key  Spare Key(s) 

Door Locks

Child Safety Locking 

Dashboard

Instrument Panel 

Airbags

Airbags 

Controls  Infotainment Display 

Engine Sensors  OBD Connector 

Music System 

Sunroof Operation

Sunroof 

Lights

Headlight  Interior Lights 

Tail Light Cluster  Turn Signal Lights 

License Plate Light  Fog Lights 

Air Conditioning

AC Cooling  AC Switch 

AC System Leaks  Center AC Vent 

Front Right AC Vent  Heater 

Color Faded

Parking Sensors  Rear Defogger 

USB Charging Port  Power/ Manual Windows 

Interiors & Luggage

Dashboard And Instrument Panel  Central Console 

Glove Box		Steering Wheel Color Faded	
Sunvisor Left: Sunvisor LHS Minor Disfiguration, Sunvisor RHS Minor Disfiguration		Seat Upholstery Driver Seat: Minor Smudge/ Cracks	
Manual Seat Movement		Seat Belts	
Head Rest		Door Controls And Trim Front Left Door: Light Scuffing	
Grab Handle		Carpet	
Headliner		Rear View Mirror	
Toolkit			

Tyres

Tyres Condition

Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			

Tyres Depth (Remaining)

LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE