



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2019 HYUNDAI ELANTRA

GLS | 66,352 KM

VIN: KMHD741F2KU764544

### Car highlights



#### **Sunroof**

This car has a sunroof



#### **Cruise control**

Cruise control to drive with ease & comfort



#### **Bluetooth**

Enjoy your drive with bluetooth



#### **Amazing Comfort**

Power driver seat

## Basic Details

 Kilometers	<b>66352</b>	 Specs	<b>Yes</b>
 Engine	<b>2.0L</b>	 Option Type	<b>Semi Loaded</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Front Wheel Drive</b>
 Body Type	<b>SEDAN</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color Grey</b>
 Interior Trim	<b>Fabric Trim</b>	 Number of Airbags	<b>2 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>2 Keys</b>
 VIN number	<b>KMHD741F2KU764544</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>	
Cruise Control	
Steering Mounted Audio Controls	
Rear Defogger	
Automatic Headlights	
 <b>Safety &amp; Security</b>	

Parking Sensors Rear	✓	Reverse Camera	✓
Traction Control	✓	Airbag Driver Front	✓
ABS	✓	Central Locking	✓
Child Safety Locking	✓		

 **Exteriors**

Running Lights	✓	LED Headlights	✓
----------------	---	----------------	---

 **Entertainment**

Bluetooth Player	✓	USB Charging Port	✓
Infotainment System	✓	USB player	✓

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## 🚗 Exterior

Doors condition

Front left door



Front right door



Panel: Low Visibility Dent < 30mm, Light

Scuffing < 50mm

Rear left door



Rear right door



Panel: Scratch < 50mm

Panel: Paint Chip-off < 5mm

Fenders Condition

Left Fender



Right Fender



Condition: Paint Chip-off < 5mm

Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Condition: Dent < 30mm

Condition: Scratch < 50mm, Paint Chip-off <

5mm

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Dent < 50mm, Light Scuffing < 80mm

Hood Condition

Hood



Bonnet: Paint Chip-off < 5mm

Trunk Condition

Trunk



Door Trim: Light Scuffing < 50mm

Trunk conditon

Trunk



Roof Condition

Roof



#### Pillars Condition

Left A Pillar		Right A Pillar	
Left A to B Pillar Beading		Right A to B Pillar Beading	
Right A to B Pillar		Left B Pillar	
Left B Pillar Trim		Left B to C Pillar Beading	
Right C Pillar Trim		Right B to C Pillar	
Right B to C Pillar Beading		Left C Pillar	

#### Running Board Condition

Left Running Board		Right Running Board	
Rear Left Sill Trim: Scratch < 80mm			

#### Sunroof Glass Condition (If Equipped)

Sun Roof Glass	
----------------	--

#### Windshield Condition

Front Windshield		Rear Windshield	
------------------	--	-----------------	--

#### Structural Assessment

Chassis Condition		Radiator Support	
-------------------	--	------------------	--

Apron		Boot Floor	
-------	--	------------	--

Firewall Condition		Cowl Top	
--------------------	--	----------	--

Head Light Support Condition	
------------------------------	--

#### Cowl Top

Cowl Top	
----------	--

#### Rear View Mirror Condition

Left Hand Side Mirror		Left Side Mirror	
-----------------------	--	------------------	--

Right Side Mirror		Right Hand Side Mirror	
-------------------	--	------------------------	--

#### Alloy Wheel/ Rim

Left Front Alloy/ Rim		Left Rear Alloy/ Rim	
-----------------------	--	----------------------	--

Right Front Alloy/ Rim		Right Rear Alloy/ Rim	
------------------------	--	-----------------------	--

Spare Alloy/ Rim Condition	
----------------------------	--

Wheel cover		Antenna	
Grill Condition		Monogram	
Light Scuffing < 50mm			
Window Glass		Wiper	
Panel Condition			
Rear Trunk Panel			
Scratch < 50mm			

---

## Engine & Transmission

Engine			
Engine Body		Engine Performance	
Engine Oil (Condition & Level)		Exhaust System	
Radiator Condition		Radiator Coolant	
Battery			
Battery Terminal & Tightness			
Fuel System			
Fuel Cap		Fuel Tank	
Transmission Operation			
Gear Shifting		Drive Axle	
Transmission Fluid			

---

## Steering, Suspension & Brakes

Steering			
Steering wheel			
Brake System			
Parking Brake		Brake Master Cylinder	
Brake Disc & Brake Pad		Brake Fluid	
Pedals			
Suspension			
Shock Absorbers			

## Electricals, Controls & Lights

### Keys

Master Key



Spare Key(s)



### Door Locks

Child Safety Locking



### Dashboard

Instrument Panel



Dash Light Operation: Not Working

### Airbags

Airbags



### Controls



Cruise Control



### Infotainment Display



Engine Sensors



### OBD Connector



Music System

Steering Mounted Audio Controls: Not



Working Properly

### Sunroof Operation

Sunroof



### Lights

Headlight



Left: Light Scuff Marks < 50mm

Interior Lights



Tail Light Cluster



Turn Signal Lights



Daylight Running Lights



Right DRL: Low Brightness

License Plate Light



### Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Crack/Fair Use Wear

Front Right AC Vent



Heater



Rear Blower Switch



Parking Sensors



Rear Defogger



USB Charging Port



Power/ Manual Windows



## **Interiors & Luggage**

Dashboard And Instrument Panel



Central Console



Box: Minor Crack/Fair Use Wear/ Scuffing

Cup Holder



Glove Box



Steering Wheel



Steering Wheel Fair Use Wear

Sunvisor



Seat Upholstery

Passenger Seat: Minor Leather/Fabric Fair Use Wear/Tears



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim

Front Left Door: Light Scuffing



Grab Handle



Carpet



Headliner



Rear View Mirror



Toolkit



## **Tyres**

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

&lt;75%

LHS Rear Tyre

&lt;75%

RHS Front Tyre

&lt;65%

RHS Rear Tyre

&lt;75%

Spare Tyre

&lt;55%



**A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE