



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2019 TOYOTA LAND CRUISER GXR | 97,733 KM

VIN: JTMHX01J3K5097478

Car highlights



Power packed

Engine size of 4.6 Litres & 8.0 cylinders



Cruise control

Cruise control to drive with ease & comfort



Bluetooth


Enjoy your drive with bluetooth



Amazing Comfort


Power driver seat

Basic Details



Specs and features


The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.




Fog Light Front	~	Roof Rails	~
Running Lights	✓	Rear Bumper Spoiler	~
Trailer Hook / Coupling	✓	LED Headlights	✓
Halogen Headlights	✓		
Safety & Security			
Navigation	~	Parking Sensors Front	•
Parking Sensors Rear	✓	Reverse Camera	~
Traction Control	✓	Airbag Driver Front	•
ABS	✓	Central Locking	•
Child Safety Locking	✓		
Performance			
Differential Locks	•	Crawl Function	•
⊈ ■ Entertainment			
Bluetooth Player	•	Infotainment System	•
USB player			

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition Front Windshield Condition: Passenger Side/Stone Chip Mark<8mm	!	Rear Windshield	•
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim Rim: Alloy Edge/ Scuff < 80mm	(!)	Left Rear Alloy/ Rim Rim: Alloy Edge/ Scuff < 80mm	(!)
Right Front Alloy/ Rim Rim: Alloy Edge/ Scuff < 80mm	!	Right Rear Alloy/ Rim Rim: Alloy Edge/ Scuff < 80mm	(!)
Spare Alloy/ Rim Condition	✓		
Antenna	•	Grill Condition Light Scuffing < 50mm	(!)
Monogram	•	Window Glass	•



Door Locks			
Child Safety Locking	~		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	Engine Sensors	✓
OBD Connector	✓	Navigation System	✓
Music System	✓		
Sunroof Operation			
Sunroof	✓		
Camera	✓		
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Daylight Running Lights	✓
License Plate Light	✓	Fog Lights	✓
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓	Rear Left AC Vent	✓
Rear Defogger	✓	USB Charging Port	✓
Power/ Manual Windows	✓		

Dashboard And Instrument Panel	✓	Central Console Cigarette Lighter: Cigarette Lighter Missing	(!)
Glove Box	✓	Steering Wheel Steering Wheel Fair Use Wear	(!)
Sunvisor	✓	Seat Upholstery	✓
Manual Seat Movement	✓	Seat Belts	•
Head Rest	✓	Door Controls And Trim	✓
Grab Handle	✓	Carpet	•
Headliner	✓	Rear View Mirror	•
Toolkit			
TOOKIL			
Tyres			
Tyres	•	Left Hand Side Rear Tyre	✓
Tyres Condition	**	Left Hand Side Rear Tyre Right Hand Side Rear Tyre	⋄
Tyres Tyres Condition Left Hand Side Front Tyre	***		⋄
Tyres Tyres Condition Left Hand Side Front Tyre Right Hand Side Front Tyre	***		✓
Tyres Tyres Condition Left Hand Side Front Tyre Right Hand Side Front Tyre Spare Tyre	<85%		<90%
Tyres Tyres Condition Left Hand Side Front Tyre Right Hand Side Front Tyre Spare Tyre Life remaining	<85% <85%	Right Hand Side Rear Tyre	<90%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE