



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2019 MITSUBISHI MONTERO SPORT

SIGNATURE | 37,761 KM

VIN: MMEMC71X4KH013753

Car highlights



Low Mileage

This car has been driven less than 15,000 km
a year



Cruise control

Cruise control to drive with ease & comfort



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort










Power driver seat
















Basic Details

 Kilometers	37761	 Specs	Yes
 Engine	3.0L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Four Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Black
 Interior Trim	Leather Trim	 Number of Airbags	2 Airbags
 Seating Capacity	7 Seats	 Number of keys	2 Keys
 VIN number	MMEMC71X4KH013753		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Climate Control AC		Cruise Control	
Rear Armrest with cupholder		Steering Mounted Audio Controls	
Power Folding Mirrors		Rear Defogger	
Central Armrest			
 Exteriors			

Fog Light Front		Running Lights	
Halogen Headlights			
 Performance			
Paddle Shift		Hill Descent Control	
Differential Locks			
 Safety & Security			
Parking Sensors Rear		Reverse Camera	
Traction Control		Airbag Driver Front	
ABS		Central Locking	
Child Safety Locking			
 Entertainment			
Rear Seat Entertainment		Bluetooth Player	
Infotainment System		USB player	

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door



Front right door

Handle: Light Scuffing < 50mm



Rear left door

Inner Handle: Handle Light Scuffing/Faded



Rear right door

Panel: Light Scuffing < 50mm



Fenders Condition

Left Fender



Right Fender

Condition: Light Scuffing < 50mm



Quarter Panels Condition

Left Quarter Panel

Condition: Light Scuffing<50mm



Right Quarter Panel



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper

Rear Bumper: Dent < 50mm, Light Scuffing < 80mm



Hood Condition

Hood

Bonnet: Paint Chip-off < 5mm, Light Scuffing < 50mm



Trunk Condition

Trunk



Trunk conditon

Trunk





































Roof Condition

Roof



Pillars Condition

Left A Pillar		Right A Pillar	
Left A to B Pillar Beading		Right A to B Pillar Beading	
Right A to B Pillar		Left B Pillar	
Left B Pillar Trim		Left B to C Pillar Beading	
Right C Pillar Trim		Right B to C Pillar	
Right B to C Pillar Beading		Left C Pillar	
Running Board Condition			
Left Running Board		Right Running Board	
Left Foot Board: Light Scuffing < 80mm		Right Foot Board: Light Scuffing < 80mm	
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass			
Windshield Condition			
Front Windshield		Rear Windshield	
Condition: Passenger Side/Stone Chip Mark<8mm			
Structural Assessment			
Chassis Condition		Radiator Support	
Apron		Boot Floor	
Firewall Condition		Cowl Top	
Head Light Support Condition			
Cowl Top			
Cowl Top			
Rear View Mirror Condition			
Left Hand Side Mirror		Left Side Mirror	
Body: Light Scuffing < 50mm, Chip < 5mm			
Right Side Mirror		Right Hand Side Mirror	
Alloy Wheel/ Rim			
Left Front Alloy/ Rim		Left Rear Alloy/ Rim	
Right Front Alloy/ Rim		Right Rear Alloy/ Rim	
Spare Alloy/ Rim Condition			

Wheel cover		Antenna	
Grill Condition Chrome Fair Use Wear < 30mm		Monogram	
Window Glass		Wiper	
Panel Condition Rear Trunk Panel Scratch < 50mm			

Engine & Transmission

Engine			
Engine Body		Engine Performance	
Engine Oil (Condition & Level)		Exhaust System	
Radiator Condition		Radiator Coolant	
Battery			
Battery Terminal & Tightness			
Fuel System			
Fuel Cap		Fuel Tank	
Transmission Operation			
Gear Shifting		Drive Axle	
4*4 Condition (If Applicable)		Transmission Fluid	

Steering, Suspension & Brakes

Steering			
Steering wheel			
Brake System			
Parking Brake		Brake Master Cylinder	
Brake Disc & Brake Pad		Brake Fluid	
Pedals			
Suspension			
Shock Absorbers			



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Navigation System



Music System



Sunroof Operation

Sunroof



Camera



Lights

Headlight

Left: Low Brightness lamps



Interior Lights



Tail Light Cluster



Daylight Running Lights



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch



Rear Left AC Vent



Rear Defogger



USB Charging Port



Rear Entertainment



Power/ Manual Windows



Interiors & Luggage

Dashboard And Instrument Panel



Central Console



Cup Holder



Glove Box



Steering Wheel



Sunvisor



Seat Upholstery



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim



Grab Handle



Carpet



Headliner



Rear View Mirror



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<75%

LHS Rear Tyre

<75%

RHS Front Tyre

<75%

RHS Rear Tyre

<75%

Spare Tyre

No spare

tyre



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE