



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2018 AUDI Q5 45 TFSI QUATTRO | 59,722 KM

VIN: WA1ZZZFY4J2204394

Car highlights



Supercharger/turbocharger

This car has a Supercharger/turbocharger



Cruise control

Cruise control to drive with ease & comfort



Bluetooth


Enjoy your drive with bluetooth



Amazing Comfort


Power driver seat

Basic Details



Specs and features


The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.



Performance			
Paddle Shift	✓		
Safety & Security			
Parking Sensors Front	✓	Parking Sensors Rear	•
Reverse Camera	~	Traction Control	•
Airbag Curtain Shield	•	Airbag Driver Front	V
ABS	✓	Central Locking	•
Child Safety Locking	✓		
Exteriors			
Roof Rails	~	Running Lights	•
Rear Bumper Spoiler	~	HID Headlights	•
□ ■ Entertainment			
Bluetooth Player	✓	Infotainment System	•
USB player	<u> </u>		

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	•
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim Rim: Alloy Edge/ Scuff < 80mm	!	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Wheel cover	✓
Antenna	✓	Grill Condition	✓
Monogram	✓	Window Glass	•
Wiper	✓		

Electricals, Controls & Lights

Keys

Master Key	✓	Spare Key(s)	✓
Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Cruise Control	•
Infotainment Display	✓	Engine Sensors	✓
OBD Connector	✓	Music System	✓
Camera	✓		
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Turn Signal Lights	✓
Daylight Running Lights	✓	License Plate Light	✓
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓		
Rear Defogger	~	USB Charging Port	•
Power/ Manual Windows	✓		
Interiors & Luggage			
Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Glove Box	✓

Steering Wheel Fair Use Wear	(!)	Sunvisor	✓
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
Carpet	✓	Headliner	✓
Rear View Mirror	~	Toolkit	✓
Tyres			
Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Right Hand Side Front Tyre Spare Tyre		Right Hand Side Rear Tyre	•
		Right Hand Side Rear Tyre	
Spare Tyre	<75%	Right Hand Side Rear Tyre LHS Rear Tyre	<75%
Spare Tyre Tyres Depth (Remaining)	<75% <65%		<75% <65%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE