



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2016 HONDA ACCORD**

**LX B | 158,695 KM**

VIN: LUCCR2623G3405457

## **Car highlights**



### **Sunroof**

This car has a sunroof



### **Cruise control**

Cruise control to drive with ease & comfort



### **Music System**
















Enjoy your drive with music system



### **Amazing Comfort**










Power driver seat



Basic Details

 Kilometers	158695	 Specs	Yes
 Engine	2.4L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Maroon
 Interior Trim	Fabric Trim	 Number of Airbags	8 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	LUCCR2623G3405457		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Cruise Control		Rear Armrest with cupholder	
Steering Mounted Audio Controls		Rear Defogger	
Central Armrest			
 <b>Safety &amp; Security</b>			
Parking Sensors Rear		Traction Control	

Airbag Driver Front	✓	ABS	✓
Central Locking	✓	Child Safety Locking	✓
 <b>Exteriors</b>			
Running Lights	✓	Halogen Headlights	✓
 <b>Entertainment</b>			
Infotainment System	✓	USB player	✓




# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



Passed 

## Exterior

### Doors condition

Front left door		Front right door	
Handle: Paint Chip-off < 5mm		Handle: Paint Chip-off < 5mm	
Rear left door		Rear right door	
Handle: Scratch < 50mm, Paint Chip-off < 5mm		Handle: Paint Chip-off < 5mm	

### Fenders Condition

Left Fender		Right Fender	
Condition: Scratch < 50mm, Paint Chip-off < 5mm, Dent < 30mm		Right Fender: Dent < 30mm, Paint Chip-off < 5mm	

### Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
Condition: Dent < 30mm, Paint Chip-off < 5mm, Scratch < 50mm		Condition: Dent < 30mm, Scratch < 50mm, Paint Chip-off < 5mm	

### Front Bumper Condition

Front Bumper 

### Rear Bumper Condition

Rear Bumper 

### Hood Condition

Hood  
Bonnet: Paint Chip-off < 5mm, Light Scuffing < 50mm 

### Trunk Condition

Trunk 

### Trunk conditon

Trunk 

### Roof Condition

Roof 

## Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar



Left B Pillar



Light Scuffing < 50mm

Condition: Dent < 30mm, Scratch < 50mm

Left B Pillar Trim



Left B to C Pillar Beading



Right C Pillar Trim



Right B to C Pillar



Light Scuffing < 80mm

Right B to C Pillar Beading



Left C Pillar



## Running Board Condition

Left Running Board



Right Running Board



Rear Left Sill Trim: Scratch < 80mm

Condition: Light Scuffing < 80mm

## Sunroof Glass Condition (If Equipped)

Sun Roof Glass



## Windshield Condition

Front Windshield

Condition: Driver Side/Stone Chip



Rear Windshield



Mark<5mm, Passenger Side/Stone Chip

Mark<8mm

## Structural Assessment

Chassis Condition



Radiator Support



Apron



Boot Floor



Firewall Condition



Cowl Top



Beading: Crack/Fair Use Wear<50mm

Head Light Support Condition



Cowl Top

Cowl Top



## Rear View Mirror Condition

Left Hand Side Mirror



Left Side Mirror



Right Side Mirror



Right Hand Side Mirror



## Alloy Wheel/ Rim

Left Front Alloy/ Rim



Left Rear Alloy/ Rim



Rim: Alloy Edge/ Scuff < 80mm

Rim: Alloy Face/ Scuff < 50mm

Right Front Alloy/ Rim	⚠	Right Rear Alloy/ Rim	⚠
Rim: Alloy Face/ Scuff < 50mm		Rim: Alloy Edge/ Scuff < 80mm, Alloy Face/ Scuff < 50mm	
Spare Alloy/ Rim Condition	⚠		
Rim: Alloy Face/ Scuff < 50mm			
Grill Condition	✓	Monogram	✓
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel			
Scratch < 50mm	⚠		

## 🔧 Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

## 🚗 Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		

Suspension

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display

Infotainment Display: Display Low Brightness



Engine Sensors



OBD Connector



Music System



Sunroof Operation

Sunroof



Lights

Headlight

Left: Light Scuff Marks < 50mm



Interior Lights



Tail Light Cluster



Turn Signal Lights



Daylight Running Lights



License Plate Light



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch



Rear Defogger



USB Charging Port





Power/ Manual Windows



## Interiors & Luggage

Dashboard And Instrument Panel



Central Console

Box: Minor Color Low Brightness



Cup Holder



Glove Box



Steering Wheel

Steering Wheel Fair Use Wear



Sunvisor



Seat Upholstery

Driver Seat: Minor Smudge/ Cracks



Manual Seat Movement



Seat Belts

Driver Seat: Smudge



Head Rest



Door Controls And Trim

Front Left Door: Light Scuffing



Grab Handle



Carpet

Front Left Floor Mat: Smudge/Burn/Crack



Headliner

Front Left: Light Scuffing



Rear View Mirror



Toolkit



## Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<75%

LHS Rear Tyre

<85%

RHS Front Tyre

<85%

RHS Rear Tyre

<55%

Spare Tyre

<85%



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE