



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2018 RENAULT CAPTUR

LE | 110,785 KM

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Reverse Camera, Parking Sensors Rear



Android Auto
















Enjoy your drive with Android Auto



Amazing Comfort











Power driver seat

Basic Details

| | | | |
|--|-------------------|---|----------------------|
|  Kilometers | 110785 |  Specs | Yes |
|  Engine | 1.6L |  Option Type | Fully Loaded |
|  Transmission | Automatic |  Drive | Front Wheel Drive |
|  Body Type | SUV |  Fuel | Petrol |
|  Wheel Type | Alloy Wheels |  Exterior Color | Exterior Color Brown |
|  Interior Trim | Fabric Trim |  Number of Airbags | 4 Airbags |
|  Seating Capacity | 5 Seats |  Number of keys | 2 Keys |
|  VIN number | VF12RRJR3JW545820 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | | |
|--|---|--------------------------|---|
|  Comfort & Convenience | | | |
| Climate Control AC |  | Cruise Control |  |
| Steering Mounted Audio Controls |  | Power Folding Mirrors |  |
| Rear Defogger |  | Central Armrest |  |
| Automatic Headlights |  | Steering Column Adjuster |  |
|  Exteriors | | | |














| | | | |
|--|---|----------------------|---|
| Fog Light Front | ✓ | Running Lights | ✓ |
| Rear Bumper Spoiler | ✓ | LED Headlights | ✓ |
|  Safety & Security | | | |
| Navigation | ✓ | Parking Sensors Rear | ✓ |
| Reverse Camera | ✓ | Airbag Driver Front | ✓ |
| ABS | ✓ | Central Locking | ✓ |
| Child Safety Locking | ✓ | | |
|  Entertainment | | | |
| Bluetooth Player | ✓ | Android Auto Play | ✓ |
| Infotainment System | ✓ | USB player | ✓ |

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

| | | | |
|---|---|--|--|
| Doors condition | | | |
| Front left door |  | Front right door Panel: Low Visibility Dent < 30mm, Paint Chip-off < 5mm |  |
| Rear left door |  | Rear right door Panel: Low Visual Dent < 30mm |  |
| Fenders Condition | | | |
| Left Fender |  | | |
| Quarter Panels Condition | | | |
| Left Quarter Panel Trim: Light Scuffing<80mm |  | Right Quarter Panel Condition: Chip |  |
| Front Bumper Condition | | | |
| Front Bumper |  | | |
| Rear Bumper Condition | | | |
| Rear Bumper Rear Bumper: Dent < 50mm, Light Scuffing < 80mm |  | | |
| Hood Condition | | | |
| Hood Bonnet: Low Visibility Dent < 30mm, Paint Chip-off < 5mm |  | | |
| Trunk Condition | | | |
| Trunk Door Trim: Light Scuffing < 50mm |  | | |
| Trunk conditon | | | |
| Trunk |  | | |
| Roof Condition | | | |
| Roof |  | | |

| | | | |
|--|---|------------------------------|---|
| Pillars Condition | | | |
| Left A Pillar | ✓ | Right A Pillar | ✓ |
| Left A to B Pillar Beading | ✓ | Right A to B Pillar Beading | ✓ |
| Right A to B Pillar | ✓ | Left B Pillar | ✓ |
| Left B Pillar Trim | ✓ | Left B to C Pillar Beading | ✓ |
| Right C Pillar Trim | ✓ | Right B to C Pillar | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar | ✓ |
| Running Board Condition | | | |
| Left Running Board | ✓ | Right Running Board | ✓ |
| Windshield Condition | | | |
| Front Windshield | | | |
| Condition: Driver Side/Stone Chip Mark<5mm, Passenger Side/Stone Chip Mark<8mm | ! | Rear Windshield | ✓ |
| Structural Assessment | | | |
| Chassis Condition | ✓ | Apron | ✓ |
| Boot Floor | ✓ | Firewall Condition | ✓ |
| Cowl Top | | Head Light Support Condition | ✓ |
| Beading: Crack/Fair Use Wear<50mm | ! | | |
| Cowl Top | | | |
| Cowl Top | ✓ | | |
| Rear View Mirror Condition | | | |
| Left Hand Side Mirror | ✓ | Left Side Mirror | ✓ |
| Right Side Mirror | ✓ | | |
| Alloy Wheel/ Rim | | | |
| Left Rear Alloy/ Rim | ✓ | Spare Alloy/ Rim Condition | ✓ |
| Wheel cover | ✓ | Antenna | ✓ |
| Grill Condition | | Monogram | ✓ |
| Scuffing > 50mm | ! | | |
| Window Glass | ✓ | Wiper | ! |
| | | Operation: Cover Missing | |

Panel Condition

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

| | | | |
|--------------------------------|---|-------------------------|---|
| Instrument Panel | ✓ | | |
| Airbags | | | |
| Airbags | ✓ | | |
| Controls | ✓ | Cruise Control | ✓ |
| Infotainment Display | ✓ | OBD Connector | ✓ |
| Navigation System | ✓ | Music System | ✓ |
| Camera | ✓ | | |
| Lights | | | |
| Headlight | | | |
| Left: Light Scuff Marks < 50mm | ! | Interior Lights | ✓ |
| Tail Light Cluster | ✓ | Daylight Running Lights | ✓ |
| License Plate Light | ✓ | Fog Lights | ✓ |
| Air Conditioning | | | |
| AC Cooling | ✓ | AC Switch | ✓ |
| AC System Leaks | ✓ | Center AC Vent | ✓ |
| Front Right AC Vent | ✓ | Heater | ✓ |
| Rear Defogger | ✓ | USB Charging Port | ✓ |
| Power/ Manual Windows | ✓ | | |

Interiors & Luggage

| | | | |
|--|---|--|---|
| Dashboard And Instrument Panel | ✓ | Central Console Box: Minor Color Low Brightness | ! |
| Cup Holder | ✓ | Glove Box | ✓ |
| Steering Wheel Steering Wheel Fair Use Wear | ! | Sunvisor Left: Sunvisor LHS Disfiguration | ! |
| Seat Upholstery | ✓ | Manual Seat Movement | ✓ |
| Seat Belts | ✓ | Head Rest | ✓ |

| | | | |
|--------------------------------|---|-------------|---|
| Door Controls And Trim | ⓘ | Grab Handle | ✓ |
| Rear Left Door: Light Scuffing | | | |
| Carpet | ✓ | Headliner | ✓ |
| Rear View Mirror | ✓ | Toolkit | ✓ |

Tyres

| | | | |
|----------------------------|------|---------------------------|------|
| Tyres Condition | | | |
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre | ✓ | | |
| Tyres Depth (Remaining) | | | |
| LHS Front Tyre | <55% | LHS Rear Tyre | <65% |
| RHS Front Tyre | <55% | RHS Rear Tyre | <65% |
| Spare Tyre | <45% | | |



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE