



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2019 HYUNDAI TUCSON**

**GL | 74,389 KM**

VIN: TMAJ28134KJ758821

### **Car highlights**



#### **Cruise control**

Cruise control to drive with ease & comfort



#### **Great Parking Assistance**

Reverse Camera, Parking Sensors Rear



#### **Bluetooth**
















Enjoy your drive with bluetooth



#### **Amazing Comfort**

Power driver seat




Basic Details

 Kilometers	74389	 Specs	Yes
 Engine	2.0L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	TMAJ28134KJ758821		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

<div> Exteriors</div>			
Fog Light Front	<div></div>	Roof Rails	<div></div>
Running Lights	<div></div>	Rear Bumper Spoiler	<div></div>
Halogen Headlights	<div></div>		
<div> Comfort &amp; Convenience</div>			
Cruise Control	<div></div>	Rear Armrest with cupholder	<div></div>

Steering Mounted Audio Controls	✓	Power Folding Mirrors	✓
Central Armrest	✓		
 <b>Safety &amp; Security</b>			
Parking Sensors Rear	✓	Reverse Camera	✓
Traction Control	✓	Airbag Driver Front	✓
ABS	✓	Central Locking	✓
Child Safety Locking	✓		
 <b>Performance</b>			
Hill Descent Control	✓		
 <b>Entertainment</b>			
Bluetooth Player	✓	USB Charging Port	✓
Infotainment System	✓	USB player	✓

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



Passed 

## Exterior

### Doors condition

Front left door		Front right door Panel: Light Scuffing < 50mm	
Rear left door		Rear right door Panel: Light Scuffing < 50mm	

### Fenders Condition

Left Fender		Right Fender Right Fender: Scratch < 50mm, Paint Chip-off < 5mm	
-------------	---	--	---


### Quarter Panels Condition

Left Quarter Panel Trim: Light Scuffing<80mm		Right Quarter Panel Condition: Scratch < 50mm	
---	---	--	---

### Front Bumper Condition

Front Bumper	
--------------	---

### Rear Bumper Condition

Rear Bumper Rear Bumper: Light Scuffing < 80mm	
---	---

### Hood Condition

Hood	
------	---

### Trunk Condition

Trunk Door Trim: Light Scuffing < 50mm	
---	---

### Trunk conditon

Trunk	
-------	---

### Roof Condition

Roof	
------	---

### Pillars Condition

Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading Beading Crack/ Tear > 5mm	!	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim Rim: Alloy Edge/ Scuff < 80mm	!	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Wheel cover	✓
Antenna	✓	Grill Condition Light Scuffing < 50mm	!

Monogram



Window Glass



Wiper



## Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Cap



Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



## Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Cruise Control Cruise Control Switch: Buttons Faded	!
Infotainment Display	✓	Engine Sensors	✓
OBD Connector	✓	Music System AUX Input: Not Working	!
Camera	✓		
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Daylight Running Lights	✓
License Plate Light	✓	Fog Lights	✓
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch Knob Restricted Movement	!		
Rear Defogger Extensive Wear Of Strip	!	USB Charging Port	✓
Power/ Manual Windows	✓		

## Interiors & Luggage

Dashboard And Instrument Panel Dashboard And Instrument Panel: Light Scuffing/Crack	!	Central Console Box: Minor Crack/Fair Use Wear/ Scuffing	!
---	---	---	---



Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisor	✓
Seat Upholstery Passenger Seat: Minor Smudge/Cracks	!	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim Front Left Door: Light Scuffing	!	Grab Handle	✓
Carpet	✓	Headliner Front Left: Light Smudge/Disfiguration, Light Scuffing	!
Rear View Mirror	✓	Toolkit	✓

## Tyres

### Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<75%	LHS Rear Tyre	<85%
RHS Front Tyre	<75%	RHS Rear Tyre	<85%
Spare Tyre	<65%		



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE