



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2016 NISSAN MAXIMA

SV | 111,093 KM

VIN: 1N4AA6AP6GC419775

Car highlights



Moonroof

This car has a moonroof



Cruise control

Cruise control to drive with ease & comfort



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort











Power driver seat


Basic Details

| | | | |
|--|-------------------|---|--------------------|
|  Kilometers | 111093 |  Specs | Yes |
|  Engine | 3.5L |  Option Type | Semi Loaded |
|  Transmission | Automatic |  Drive | Front Wheel Drive |
|  Body Type | SEDAN |  Fuel | Petrol |
|  Wheel Type | Alloy Wheels |  Exterior Color | Exterior Color Red |
|  Interior Trim | Leather Trim |  Number of Airbags | 8 Airbags |
|  Seating Capacity | 5 Seats |  Number of keys | 2 Keys |
|  VIN number | 1N4AA6AP6GC419775 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | | |
|--|---|---------------------------------|---|
|  Comfort & Convenience | | | |
| Climate Control AC |  | Cruise Control |  |
| Rear Armrest with cupholder |  | Steering Mounted Audio Controls |  |
| Rear Defogger |  | Central Armrest |  |
| Remote Engine Start |  | Automatic Headlights |  |
|  Exteriors | | | |

| | | | |
|--|---|-----------------------|---|
| Fog Light Front | ✓ | Running Lights | ✓ |
| Halogen Headlights | ✓ | | |
|  Safety & Security | | | |
| Navigation | ✓ | Parking Sensors Front | ✓ |
| Parking Sensors Rear | ✓ | Reverse Camera | ✓ |
| Traction Control | ✓ | Airbag Curtain Shield | ✓ |
| Airbag Driver Front | ✓ | ABS | ✓ |
| Central Locking | ✓ | Child Safety Locking | ✓ |
|  Entertainment | | | |
| Bluetooth Player | ✓ | USB Charging Port | ✓ |
| Infotainment System | ✓ | USB player | ✓ |

150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition



| | | | |
|-----------------|---|--|---|
| Front left door |  | Front right door |  |
| | | Panel: Low Visibility Dent < 30mm, Paint Chip-off < 5mm, Light Scuffing < 50mm | |

| | | | |
|--|---|---|---|
| Rear left door |  | Rear right door |  |
| Panel: Dent < 30mm, Paint Chip-off < 5mm | | Panel: Low Visual Dent < 30mm, Paint Chip-off < 5mm | |

Fenders Condition

| | | | |
|-----------------------------------|---|---------------------------------|---|
| Left Fender |  | Right Fender |  |
| Condition: Low Visual Dent < 30mm | | Condition: Paint Chip-off < 5mm | |

Quarter Panels Condition

| | | | |
|--------------------|---|--|---|
| Left Quarter Panel |  | Right Quarter Panel |  |
| | | Condition: Low Visual Dent < 30mm, Light Scuffing<50mm | |


Front Bumper Condition

| | |
|--------------|---|
| Front Bumper |  |
|--------------|---|

Rear Bumper Condition

| | |
|---|---|
| Rear Bumper |  |
| Rear Bumper: Light Scuffing < 80mm, Acid Marks/ Bird Dropping < 8mm | |

Hood Condition

| | |
|---|---|
| Hood |  |
| Bonnet: Paint Chip-off < 5mm, Light Scuffing < 50mm | |

Trunk Condition

| | |
|-------|---|
| Trunk |  |
|-------|---|

Trunk conditon

| | |
|-------|---|
| Trunk |  |
|-------|---|

Roof Condition

| | | | |
|---|---|----------------------------------|---|
| Roof | | | |
| Roof Moulding Condition: Minor Rubber Beading Fair Use Wear | ! | | |
| Pillars Condition | | | |
| Left A Pillar | ! | Right A Pillar | ✓ |
| Condition: minor imperfection | | | |
| Left A to B Pillar Beading | ✓ | Right A to B Pillar Beading | ✓ |
| Right A to B Pillar | ✓ | Left B Pillar | ✓ |
| Left B Pillar Trim | ✓ | Left B to C Pillar Beading | ✓ |
| Right C Pillar Trim | ✓ | Right B to C Pillar | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar | ! |
| | | Scratch < 50mm | |
| Running Board Condition | | | |
| Left Running Board | ! | Right Running Board | ! |
| Condition: Scratch < 80mm | | Condition: Light Scuffing < 80mm | |
| Sunroof Glass Condition (If Equipped) | | | |
| Sun Roof Glass | ✓ | | |
| Windshield Condition | | | |
| Front Windshield | ✓ | Rear Windshield | ✓ |
| Structural Assessment | | | |
| Chassis Condition | ✓ | Radiator Support | ✓ |
| Apron | ✓ | Boot Floor | ✓ |
| Firewall Condition | ✓ | Cowl Top | ✓ |
| Head Light Support Condition | ✓ | | |
| Cowl Top | | | |
| Cowl Top | ✓ | | |
| Rear View Mirror Condition | | | |
| Left Hand Side Mirror | ✓ | Left Side Mirror | ✓ |
| Right Side Mirror | | Right Hand Side Mirror | ✓ |
| Body: Paint Chip-off < 5mm | ! | | |
| Alloy Wheel/ Rim | | | |
| Left Front Alloy/ Rim | ✓ | Left Rear Alloy/ Rim | ✓ |

| | | | |
|----------------------------|---|-----------------------|---|
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ✓ |
| Spare Alloy/ Rim Condition | ✓ | | |
| Antenna | ✓ | Grill Condition | ✓ |
| Monogram | ✓ | Window Glass | ✓ |
| Wiper | ✓ | | |
| Panel Condition | | | |
| Rear Trunk Panel | | | |
| Scratch < 50mm | ! | | |

Engine & Transmission

| | | | |
|--------------------------------|---|--------------------|---|
| Engine | | | |
| Engine Body | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System | ✓ |
| Radiator Condition | ✓ | Radiator Coolant | ✓ |
| Battery | | | |
| Battery Terminal & Tightness | ✓ | | |
| Fuel System | | | |
| Fuel Cap | ✓ | Fuel Tank | ✓ |
| Transmission Operation | | | |
| Gear Shifting | ✓ | Drive Axle | ✓ |
| Transmission Fluid | ✓ | | |

Steering, Suspension & Brakes

| | | | |
|------------------------|---|-----------------------|---|
| Steering | | | |
| Steering wheel | ✓ | | |
| Brake System | | | |
| Parking Brake | ✓ | Brake Master Cylinder | ✓ |
| Brake Disc & Brake Pad | ✓ | Brake Fluid | ✓ |
| Pedals | ✓ | | |

Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Navigation System



Music System



Sunroof Operation

Sunroof



Camera



Lights

Headlight

Left: Light Scuff Marks < 50mm



Interior Lights



Tail Light Cluster



Turn Signal Lights



Daylight Running Lights



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



| | | | |
|-----------------------|---|-------------------|---|
| Front Right AC Vent | ✓ | Heater | ✓ |
| Rear Blower Switch | ✓ | | |
| Rear Defogger | ✓ | USB Charging Port | ✓ |
| Power/ Manual Windows | ✓ | Seat Heaters | ✓ |



Interiors & Luggage

| | | | |
|--|---|---------------------------------|---|
| Dashboard And Instrument Panel | | | |
| Dashboard Upholstery: Minor Scuffing/ Disfiguration/ Melted | ! | Central Console | ✓ |
| Cup Holder | ✓ | Glove Box | ✓ |
| Steering Wheel | | | |
| Steering Wheel Fair Use Wear | ! | Sunvisor | ✓ |
| Seat Upholstery | | | |
| Driver Seat: Minor Smudge/ Cracks | ! | Manual Seat Movement | ✓ |
| Seat Belts | | | |
| Driver Seat: Smudge | ! | Head Rest | ✓ |
| Door Controls And Trim | | | |
| Front Left Door: Fair Use Wear, Light Scuffing/ Disfiguration | ! | Grab Handle | ✓ |
| Carpet | ✓ | Headliner | ! |
| | | Front Left: Crack/Fair Use Wear | |
| Rear View Mirror | ✓ | Toolkit | ✓ |



Tyres

| | | | |
|----------------------------|------|---------------------------|------|
| Tyres Condition | | | |
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre | ✓ | | |
| Tyres Depth (Remaining) | | | |
| LHS Front Tyre | <75% | LHS Rear Tyre | <65% |
| RHS Front Tyre | <75% | RHS Rear Tyre | <75% |

Spare Tyre

<65%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE