



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2015 LEXUS GX460

PREMIER | 136,356 KM

VIN: JTJJM7FX5F5115739

Car highlights



Power packed

Engine size of 4.6 Litres & 8.0 cylinders



Cruise control

Cruise control to drive with ease & comfort



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat, Memory Seats

Basic Details

 Kilometers	136356	 Specs	Yes
 Engine	4.6L	 Option Type	Basic
 Transmission	Automatic	 Drive	Four Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Gold
 Interior Trim	Leather Trim	 Number of Airbags	10 Airbags
 Seating Capacity	7 Seats	 Number of keys	1 Keys
 VIN number	JTJJM7FX5F5115739		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Safety & Security			
360 degree Camera		Navigation	
Parking Sensors Front		Parking Sensors Rear	
Reverse Camera		Traction Control	
Front Camera		Side Camera	
Airbag Curtain Shield		Airbag Knees	

Airbag Driver Front		ABS	
Central Locking		Child Safety Locking	



Comfort & Convenience

Climate Control AC		Cruise Control	
Memory Seats		Rear Armrest with cupholder	
Steering Mounted Audio Controls		Power Folding Mirrors	
Cool Box		Rear Defogger	
Central Armrest		Automatic Headlights	
Steering Column Adjuster			



Exteriors

Fog Light Front		Roof Rails	
Running Lights		Rear Bumper Spoiler	
Halogen Headlights		HID Headlights	



Performance

Hydraulic Suspensions		Differential Locks	
Crawl Function			



Entertainment

Bluetooth Player		Infotainment System	
USB player			

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front left door



Front right door

Panel: Light Scuffing < 50mm, Paint Chip-off !
< 5mm

Rear left door



Rear right door

Panel: Light Scuffing < 50mm, Paint Chip-off !
< 5mm

Fenders Condition

Left Fender

Condition: Light Scuffing < 50 mm, Paint
Chip-off < 5mm



Right Fender

Condition: Light Scuffing < 50mm, Paint Chip-
off < 5mm !

Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood

Bonnet: Light Scuffing < 50mm, Paint Chip-off !
< 5mm

Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar		Right A Pillar	
Left A to B Pillar Beading		Right A to B Pillar Beading	
Right A to B Pillar		Left B Pillar	
Left B Pillar Trim		Left B to C Pillar Beading	
Right C Pillar Trim		Right B to C Pillar	
Right B to C Pillar Beading		Left C Pillar	

Running Board Condition

Left Running Board		Right Running Board	
--------------------	--	---------------------	--

Sunroof Glass Condition (If Equipped)

Sun Roof Glass	
----------------	--

Windshield Condition

Front Windshield		Rear Windshield	
------------------	--	-----------------	--

Structural Assessment

Chassis Condition		Radiator Support	
Apron		Boot Floor	
Firewall Condition		Cowl Top	
Head Light Support Condition			

Cowl Top

Cowl Top	
----------	--

Rear View Mirror Condition

Left Hand Side Mirror		Left Side Mirror	
Right Side Mirror			

Alloy Wheel/ Rim

Left Front Alloy/ Rim		Left Rear Alloy/ Rim	
Right Front Alloy/ Rim		Right Rear Alloy/ Rim	

Spare Alloy/ Rim Condition

Wheel cover		Antenna	
-------------	--	---------	--

Grill Condition	✓	Monogram	✓
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel			✓

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
4*4 Condition (If Applicable)	✓	Transmission Fluid	✓

Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			
Shock Absorbers	✓		

Electricals, Controls & Lights

Keys

Master Key 

Door Locks

Child Safety Locking 

Dashboard

Instrument Panel 

Airbags

Airbags 

Controls

Cruise Control 

Infotainment Display 

Engine Sensors 

OBD Connector 

Navigation System 

Music System 

Sunroof Operation

Sunroof 

Camera 

Lights

Headlight 

Interior Lights 

Tail Light Cluster 

Daylight Running Lights 

License Plate Light 

Fog Lights 

Air Conditioning

AC Cooling 

AC Switch 

AC System Leaks 

Center AC Vent 

Front Right AC Vent 

Heater 

Rear Blower Switch 

Rear Left AC Vent 

Rear Defogger 

USB Charging Port 

Power/ Manual Windows 

Memory Seats 



Interiors & Luggage

Dashboard And Instrument Panel		Central Console Box: Minor Crack/Fair Use Wear/ Scuffing	
Cup Holder		Glove Box	
Steering Wheel		Sunvisor	
Seat Upholstery		Manual Seat Movement	
Driver Seat: Minor Leather/ Fabric Fair Use Wear/ Tears		Rear Seat: minor imperfection	
Seat Belts		Head Rest	
Door Controls And Trim		Grab Handle	
Carpet		Headliner	
Rear View Mirror		Toolkit	

Tyres

Tyres Condition

Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			

Tyres Depth (Remaining)

LHS Front Tyre	<75%	LHS Rear Tyre	<85%
RHS Front Tyre	<75%	RHS Rear Tyre	<85%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE