



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2017 BMW 430i**

**M SPORT | 111,918 KM**

**VIN: WBA4N710XHK518608**

## **Car highlights**



### **Supercharger/turbocharger**

This car has a Supercharger/turbocharger



### **Adaptive cruise control**

Adaptive cruise control to drive with ease & comfort



### **Bluetooth**

Enjoy your drive with bluetooth



### **Amazing Comfort**

Power driver seat, Memory Seats

## Basic Details

 Kilometers	<b>111918</b>	 Engine	<b>2.0L</b>
 Option Type	<b>Semi Loaded</b>	 Transmission	<b>Automatic</b>
 Drive	<b>Rear Wheel Drive</b>	 Body Type	<b>COUPE</b>
 Fuel	<b>Petrol</b>	 Wheel Type	<b>Alloy Wheels</b>
 Exterior Color	<b>Exterior Color Black</b>	 Interior Trim	<b>Leather Trim</b>
 Number of Airbags	<b>6 Airbags</b>	 Seating Capacity	<b>4 Seats</b>
 Number of keys	<b>2 Keys</b>	 VIN number	<b>WBA4N710XHK518608</b>

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Heads up Display		Climate Control AC	
Cruise Control		Memory Seats	
Rear Armrest with cupholder		Steering Mounted Audio Controls	
Power Folding Mirrors		Rear Defogger	
Central Armrest		Automatic Headlights	
 <b>Safety &amp; Security</b>			

Adaptive cruise control	✓	360 degree Camera	✓
Lane Departure Warning System	✓	Navigation	✓
Parking Sensors Front	✓	Parking Sensors Rear	✓
Reverse Camera	✓	Blind Spot Monitor	✓
Traction Control	✓	Front Camera	✓
Side Camera	✓	Airbag Curtain Shield	✓
Airbag Driver Front	✓	ABS	✓
Central Locking	✓	Child Safety Locking	✓

#### **Exteriors**

Fog Light Front	✓	Running Lights	✓
LED Headlights	✓		

#### **Performance**

Paddle Shift	✓	
--------------	---	--

#### **Entertainment**

Bluetooth Player	✓	Infotainment System	✓
USB player	✓		

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## 🚗 Exterior

Doors condition

Front left door



Handle: Paint Chip-off < 5mm

Front right door



Handle: Light Scuffing < 50mm

Rear left door



Fenders Condition

Left Fender

Right Fender

Condition: Light Scuffing < 50 mm, Paint



Chip-off < 5mm

Condition: Light Scuffing < 50mm, Low Visual



Dent < 30mm

Quarter Panels Condition

Left Quarter Panel

Right Quarter Panel

Condition: Paint Chip-off < 5mm, Scratch <



50mm

Condition: Low Visual Dent < 30mm



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Chip< 8mm

Hood Condition

Hood



Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Running Board Condition			
Left Running Board	!	Right Running Board	
Front Left Sill Trim: Scratch < 80mm		Front Right Sill Trim: Low Visual Dent < 50mm, Light Scuffing < 80mm	!
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	!	Right Hand Side Mirror	✓
Body: Scratch < 50mm			
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	!	Left Rear Alloy/ Rim	✓
Rim: Alloy Edge/ Scuff < 80mm			
Right Front Alloy/ Rim	!	Right Rear Alloy/ Rim	!
Rim: Alloy Edge/ Scuff < 80mm		Rim: Alloy Face/ Scuff < 50mm	
Antenna	✓	Grill Condition	
		Light Scuffing < 50mm	!

Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel			
Acid Marks/ Bird Dropping < 5mm	!		

## Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Gear shift	✓
Drive Axle	✓	Transmission Fluid	✓

## Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			
Shock Absorbers	✓		

## Electricals, Controls & Lights

### Keys

Master Key



Spare Key(s)



Dashboard

Instrument Panel



Airbags

Airbags



Cruise Control



Heads Up Display



Infotainment Display



Engine Sensors



OBD Connector



Radar (If Equipped)



Navigation System



Music System



Sunroof Operation

Sunroof



Lights

Headlight



Interior Lights



Tail Light Cluster



Turn Signal Lights



Daylight Running Lights



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch



Parking Sensors



Rear Defogger



USB Charging Port



Power/ Manual Windows



## Memory Seats



## Interiors & Luggage

Dashboard And Instrument Panel



Central Console



Box: Minor Crack/Fair Use Wear/ Scuffing

Cup Holder



Glove Box



Steering Wheel



Sunvisor



### Seat Upholstery

Driver Seat: Minor Leather/ Fabric Fair Use  
Wear/ Tears



Manual Seat Movement



Seat Belts



Head Rest



### Door Controls And Trim

Front Left Door: Light Scuffing/ Disfiguration



Carpet



Headliner



Rear View Mirror



Toolkit



## Tyres

### Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



### Tyres Depth (Remaining)

LHS Front Tyre

<65%

LHS Rear Tyre

<65%

RHS Front Tyre

<65%

RHS Rear Tyre

<55%

Spare Tyre

No spare  
tyre



**A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE