



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





## 2014 LAND ROVER RANGE ROVER SPORT

HSE | 146,983 KM

### Car highlights



#### **Panoramic Roof**

This car has a panoramic roof



#### **Cruise control**

Cruise control to drive with ease & comfort



#### **Bluetooth**
















Enjoy your drive with bluetooth



#### **Amazing Comfort**












Power driver seat, Memory Seats





Basic Details

 Kilometers	146983	 Specs	Yes
 Engine	3.0L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Four Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Black
 Interior Trim	Leather Trim	 Number of Airbags	10 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	SALWA2VF4EA350886		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Climate Control AC		Cruise Control	
Memory Seats		Rear Armrest with cupholder	
Steering Mounted Audio Controls		Soft Door Close	
Power Folding Mirrors		Power Tailgate/ Power Trunk	
Cool Box		Rear Defogger	

Central Armrest	✓	Automatic Headlights	✓
Steering Column Adjuster	✓		
 <b>Exteriors</b>			
Fog Light Front	✓	Running Lights	✓
Rear Bumper Spoiler	✓	HID Headlights	✓
 <b>Safety &amp; Security</b>			
Navigation	✓	Parking Sensors Front	✓
Parking Sensors Rear	✓	Reverse Camera	✓
Blind Spot Monitor	✓	Traction Control	✓
Airbag Curtain Shield	✓	Airbag Driver Front	✓
ABS	✓	Central Locking	✓
Child Safety Locking	✓		
 <b>Performance</b>			
Paddle Shift	✓	Hydraulic Suspensions	✓
Hill Descent Control	✓		
 <b>Entertainment</b>			
Bluetooth Player	✓	Infotainment System	✓
USB player	✓		

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

Front left door		Front right door Panel: Light Scuffing < 50mm	
Rear left door		Rear right door Panel: Light Scuffing < 50mm	

### Fenders Condition

Left Fender		Right Fender Right Fender: Mud flap missing/ damaged	
-------------	---	---	---


### Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
--------------------	--	---------------------	--


### Front Bumper Condition

Front Bumper	
--------------	---

### Rear Bumper Condition

Rear Bumper	
Rear Bumper: Light Scuffing < 80mm	

### Hood Condition

Hood	
Bonnet: Low Visibility Dent < 30mm, Light Scuffing < 50mm	

### Trunk Condition

Trunk	
-------	---

### Trunk conditon

Trunk	
-------	---

### Roof Condition

Roof	
------	---

### Pillars Condition

Left A Pillar		Right A Pillar	
---------------	---	----------------	---

Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield			
Condition: Driver Side/Stone Chip Mark<5mm, Passenger Side/Stone Chip Mark<8mm	!	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Rear Alloy/ Rim	✓	Spare Alloy/ Rim Condition	✓
Wheel cover	✓	Antenna	✓
Grill Condition		Monogram	!
Light Scuffing < 50mm	!	Light Scuffing < 50mm	!
Window Glass	✓	Wiper	✓

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Gear shift	✓
Drive Axle	✓	4*4 Condition (If Applicable)	✓
Transmission Fluid	✓		

## **Steering, Suspension & Brakes**

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			
Shock Absorbers	✓		

## **Electricals, Controls & Lights**













Keys			
Master Key	✓		
Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		

Airbags			
Airbags	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	OBD Connector	✓
Radar (If Equipped)	✓	Navigation System	✓
Music System	✓		
Sunroof Operation			
Sunroof	✓		
Camera	✓		
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster		Daylight Running Lights	✓
Left Tail Lamp: Crack / Fair Use Wear > 5mm	!		
License Plate Light	✓	Fog Lights	✓
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Left AC Vent			
RHS Crack/Fair Use Wear	!		
Rear Defogger		USB Charging Port	!
Extensive Wear Of Strip	!	Rear: Dummy Cap Missing	!
Power/ Manual Windows	✓	Memory Seats	✓

## Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	!
		Box: Minor Crack/Fair Use Wear/ Scuffing	
Cup Holder	✓	Glove Box	✓



Steering Wheel	Steering Wheel Fair Use Wear		Sunvisor	
			Left: Sunvisor LHS Minor Crack/Fair Use Wear, Sunvisor LHS Vanity Mirror Light Not Working, Sunvisor RHS Vanity Mirror Light Not Working, Sunvisor RHS Minor Crack/Damage, Sunvisor RHS Color Low Brightness	
Seat Upholstery	Driver Seat: Minor Smudge/ Cracks, Minor Leather/ Fabric Fair Use Wear/ Tears		Manual Seat Movement	
Seat Belts			Head Rest	
Door Controls And Trim	Front Left Door: Light Scuffing		Grab Handle	
Carpet			Headliner	
Rear View Mirror			Toolkit	

## Tyres

Tyres Condition				
Left Hand Side Front Tyre		Left Hand Side Rear Tyre		
Right Hand Side Front Tyre		Right Hand Side Rear Tyre		
Spare Tyre				
Life remaining				
LHS Front Tyre	<45%	LHS Rear Tyre	<55%	
RHS Front Tyre	<45%	RHS Rear Tyre	<55%	
Spare Tyre	<65%			



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE