



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2016 AUDI A6**

**35 TFSI | 123,396 KM**

## **Car highlights**



### **Supercharger/turbocharger**

This car has a Supercharger/turbocharger



### **Cruise control**

Cruise control to drive with ease & comfort



### **Bluetooth**
















Enjoy your drive with bluetooth



### **Amazing Comfort**











Power driver seat, Memory Seats


















Basic Details

 Kilometers	123396	 Specs	Yes
 Engine	1.8L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Leather Trim	 Number of Airbags	6 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	WAUACCFC9GN128939		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Climate Control AC		Cruise Control	
Memory Seats		Steering Mounted Audio Controls	
Power Folding Mirrors		Rear Defogger	
Central Armrest		Automatic Headlights	
Steering Column Adjuster			

 <b>Performance</b>			
Paddle Shift			
 <b>Safety &amp; Security</b>			
Parking Sensors Front			Parking Sensors Rear 
Traction Control			Airbag Curtain Shield 
Airbag Driver Front			ABS 
Central Locking			Child Safety Locking 
 <b>Exteriors</b>			
Running Lights			HID Headlights 
 <b>Entertainment</b>			
Bluetooth Player			Infotainment System 





# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

Front left door		Front right door Panel: Paint Chip-off < 5mm	
Rear left door		Rear right door Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm	

### Fenders Condition

Left Fender		Right Fender	
-------------	---	--------------	---


### Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel Condition: Scratch < 50mm	
--------------------	--	--	--

### Front Bumper Condition

Front Bumper	
--------------	---

### Rear Bumper Condition

Rear Bumper	
Rear Bumper: Light Scuffing < 80mm	

### Hood Condition

Hood	
Bonnet: Paint Chip-off < 5mm	

### Trunk Condition

Trunk	
-------	---

### Trunk conditon

Trunk	
-------	---

### Roof Condition

Roof	
------	---

### Pillars Condition

Left A Pillar		Right A Pillar	
---------------	---	----------------	---

Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	!	Right B to C Pillar	✓
Fair Use Wear			
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	!
		Condition: Light Scuffing < 80mm	
Windshield Condition			
Front Windshield			
Condition: Driver Side/Stone Chip	!	Rear Windshield	✓
Mark<5mm, Passenger Side/Stone Chip			
Mark<8mm			
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim		Left Rear Alloy/ Rim	!
Rim: Alloy Edge/ Scuff < 80mm, Alloy Face/	!	Rim: Alloy Face/ Scuff < 50mm, Alloy Edge/	
Scuff < 50mm		Scuff < 80mm	
Right Front Alloy/ Rim		Right Rear Alloy/ Rim	
Rim: Alloy Edge/ Scuff < 80mm, Alloy Face/	!	Rim: Alloy Face/ Scuff < 50mm, Alloy Edge/	!
Scuff < 50mm		Scuff < 80mm	
Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Wheel cover	✓

Antenna	✓	Grill Condition Light Scuffing < 50mm	⚠
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel	✓		

## 🔧 Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Gear shift	✓
Drive Axle	✓	Transmission Fluid	✓

## 🚗 Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls

Horn: Colour Low Brightness



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Navigation System

Condition: Available - SD Card Missing



Music System



Lights

Headlight



Interior Lights



Tail Light Cluster



Daylight Running Lights

Right DRL: Low Brightness



License Plate Light



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent

Colour Faded



Front Right AC Vent



Heater



Rear Blower Switch

Crack



Rear Defogger



USB Charging Port

Rear: Dummy Cap Missing





Power/ Manual Windows



Memory Seats



## Interiors & Luggage

Dashboard And Instrument Panel

Dashboard And Instrument Panel: Light  
Scuffing/Crack



Central Console

Arm Rest: Fair Use Wear



Cup Holder



Glove Box



Steering Wheel

Steering Wheel Fair Use Wear



Sunvisor

Left: Sunvisor LHS Minor Smudge, Sunvisor  
RHS Minor Smudge



Seat Upholstery

Driver Seat: Minor Smudge/ Cracks, Minor  
Leather/ Fabric Fair Use Wear/ Tears



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim

Rear Right Door: Crack/ Fair Use Wear



Grab Handle



Carpet



Headliner

Front Left: Light Smudge/Disfiguration



Rear View Mirror



Toolkit



## Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<45%

LHS Rear Tyre

<55%

RHS Front Tyre

<45%

RHS Rear Tyre

<55%

Spare Tyre

<45%



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE