



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2020 BMW 520i

EXCLUSIVE | 81,700 KM

VIN: WBAJA1A07LWW33762

Car highlights



Supercharger/turbocharger

This car has a Supercharger/turbocharger



Cruise control

Cruise control to drive with ease & comfort



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort












Power driver seat, Memory Seats & more

Basic Details

 Kilometers	81700	 Specs	Yes
 Engine	2.0L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Rear Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Leather Trim	 Number of Airbags	6 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	WBAJA1A07LWW33762		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Climate Control AC		Cruise Control	
Memory Seats		Rear Armrest with cupholder	
Steering Mounted Audio Controls		Power Folding Mirrors	
Power Head Rest		Rear Defogger	
Central Armrest		Automatic Headlights	



Exteriors

Fog Light Front



Running Lights



HID Headlights



Safety & Security

Parking Sensors Front



Parking Sensors Rear



Reverse Camera



Traction Control



Airbag Curtain Shield



Airbag Driver Front



ABS



Central Locking



Child Safety Locking



Entertainment

Bluetooth Player



Infotainment System



USB player



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition



Front left door		Front right door	
		Handle: Paint Chip-off < 5mm	

Rear left door		Rear right door	
----------------	---	-----------------	---

Fenders Condition

Left Fender		Right Fender	
Condition: Light Scuffing < 50 mm		Condition: Light Scuffing < 50mm	

Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
		Condition: Low Visual Dent < 30mm, Chip<5mm	

Front Bumper Condition

Front Bumper	
--------------	---

Rear Bumper Condition

Rear Bumper	
-------------	---

Hood Condition

Hood	
Bonnet: Paint Chip-off < 5mm	

Trunk Condition

Trunk	
-------	---

Trunk conditon

Trunk	
-------	---

Roof Condition

Roof	
------	---

Pillars Condition

Left A Pillar		Right A Pillar	
---------------	---	----------------	---

Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board Condition: Scratch < 80mm	!	Right Running Board	✓
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim Rim: Alloy Edge/ Scuff < 80mm	!
Wheel cover	✓	Antenna	✓
Grill Condition	✓	Monogram	✓

Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel	✓		

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			
Shock Absorbers	✓		

Electricals, Controls & Lights

Keys			
------	--	--	--

Master Key	✓	Spare Key(s)	✓
Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	Engine Sensors	✓
OBD Connector	✓	Music System	✓
Sunroof Operation			
Sunroof	✓		
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Turn Signal Lights	✓
Daylight Running Lights	✓	License Plate Light	✓
Fog Lights	✓		
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓		
Parking Sensors	✓	Rear Defogger	✓
USB Charging Port	✓	Power/ Manual Windows	✓
Memory Seats	✓		



Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisor	✓
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓

Tyres Depth (Remaining)

LHS Front Tyre	<65%	LHS Rear Tyre	<55%
RHS Front Tyre	<65%	RHS Rear Tyre	<55%
Spare Tyre	No spare tyre		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE