



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



**2018 NISSAN PATROL  
SE PLATINUM | 142,838 KM**

VIN: JN8BY2NY5J9119854

**Car highlights**



**Great condition**

Car has low imperfections



**Cruise control**

Cruise control to drive with ease & comfort



**Bluetooth**

Enjoy your drive with bluetooth



**Amazing Comfort**

Power driver seat, Memory Seats

## Basic Details

 Kilometers	<b>142838</b>	 Specs	<b>Yes</b>
 Engine	<b>4.0L</b>	 Option Type	<b>Semi Loaded</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Four Wheel Drive</b>
 Body Type	<b>SUV</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color Silver</b>
 Interior Trim	<b>Leather Trim</b>	 Number of Airbags	<b>8 Airbags</b>
 Seating Capacity	<b>8 Seats</b>	 Number of keys	<b>2 Keys</b>
 VIN number	<b>JN8BY2NY5J9119854</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Safety & Security			
360 degree Camera		Navigation	
Parking Sensors Front		Parking Sensors Rear	
Reverse Camera		Traction Control	
Front Camera		Side Camera	
Airbag Curtain Shield		Airbag Driver Front	

ABS		Central Locking	
Child Safety Locking			
<b>Comfort &amp; Convenience</b>			
Climate Control AC		Cruise Control	
Memory Seats		Rear Armrest with cupholder	
Steering Mounted Audio Controls		Power Folding Mirrors	
Power Tailgate/ Power Trunk		Cool Box	
Rear Defogger		Central Armrest	
Remote Engine Start		Automatic Headlights	
Steering Column Adjuster			
<b>Exteriors</b>			
Fog Light Front		Roof Rails	
Running Lights		Rear Bumper Spoiler	
Trailer Hook / Coupling		LED Headlights	
Halogen Headlights			
<b>Entertainment</b>			
Rear Seat Entertainment		Bluetooth Player	
USB Charging Port		Infotainment System	
USB player			
<b>Performance</b>			
Hill Descent Control		Differential Locks	

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## 🚗 Exterior

Doors condition

Front left door



Front right door



Rear left door



Rear right door



Fenders Condition

Left Fender



Condition: Paint Chip-off

Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood



Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar		Left B Pillar	
Left B Pillar Trim		Left B to C Pillar Beading	
Right C Pillar Trim		Right B to C Pillar	
Right B to C Pillar Beading		Left C Pillar	
Running Board Condition			
Left Running Board		Right Running Board	
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass			
Windshield Condition			
Front Windshield		Rear Windshield	
Structural Assessment			
Chassis Condition		Apron	
Boot Floor		Firewall Condition	
Cowl Top		Head Light Support Condition	
Beading: Crack/Fair Use Wear<50mm			
Cowl Top			
Cowl Top			
Rear View Mirror Condition			
Left Hand Side Mirror		Left Side Mirror	
Right Side Mirror			
Alloy Wheel/ Rim			
Left Front Alloy/ Rim		Left Rear Alloy/ Rim	
Right Front Alloy/ Rim		Right Rear Alloy/ Rim	
Spare Alloy/ Rim Condition			
Antenna		Grill Condition	
Monogram		Window Glass	
Wiper			
Panel Condition			

Rear Trunk Panel



## Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



4\*4 Condition (If Applicable)



Transmission Fluid



## Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags		
Airbags	✓	
Controls	✓	Cruise Control
Heads Up Display	✓	Infotainment Display
OBD Connector	✓	Navigation System
Music System	✓	
Sunroof Operation		
Sunroof	✓	
Camera	✓	
Lights		
Headlight	✓	Interior Lights
Tail Light Cluster	✓	Daylight Running Lights
License Plate Light	✓	Fog Lights
Air Conditioning		
AC Cooling	✓	AC System Leaks
Center AC Vent	✓	Front Right AC Vent
Heater	!	Rear Blower Switch
Heater Not Working RHS		
Rear Left AC Vent	✓	
Rear Defogger	✓	USB Charging Port
Rear Entertainment	✓	Power/ Manual Windows
Memory Seats	✓	

## **Interiors & Luggage**

Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Glove Box	✓

Sunvisor		Seat Upholstery	
Manual Seat Movement		Seat Belts	
Head Rest		Door Controls And Trim	
Grab Handle		Carpet	
Headliner		Rear View Mirror	
Toolkit			

## Tyres

### Tyres Condition

Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			
Tyres Depth (Remaining)			
LHS Front Tyre	<85%	LHS Rear Tyre	<85%
RHS Front Tyre	<85%	RHS Rear Tyre	<75%
Spare Tyre	<75%		



**A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE