



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 6 Months Warranty

This car comes with 6 months or 10,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2022 TOYOTA COROLLA

XLI | 60,011 KM

VIN: RKLBB0BEXN0039037

## Car highlights



### Good Tyre Condition

Tyre age less than 2 years



### Cruise control

Cruise control to drive with ease & comfort



### Apple play

Enjoy your drive with apple play



### Amazing Comfort

Power driver seat

## Basic Details

 Kilometers	<b>60011</b>	 Specs	<b>Yes</b>
 Engine	<b>1.6L</b>	 Option Type	<b>Basic</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Front Wheel Drive</b>
 Body Type	<b>SEDAN</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color Silver</b>
 Interior Trim	<b>Fabric Trim</b>	 Number of Airbags	<b>4 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>3 Keys</b>
 VIN number	<b>RKLBB0BEXN0039037</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Exteriors</b>	
Fog Light Front	
 <b>Comfort &amp; Convenience</b>	
Cruise Control	
Rear Defogger	
 <b>Safety &amp; Security</b>	

Parking Sensors Rear	✓	Traction Control	✓
Airbag Driver Front	✓	ABS	✓
Central Locking	✓	Child Safety Locking	✓

🔊 **Entertainment**

Bluetooth Player	✓	Apple Play	✓
Android Auto Play	✓	Infotainment System	✓
USB player	✓		

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## 🚗 Exterior

Doors condition

Front left door



Front right door



Panel: Paint Chip-off < 5mm

Rear left door



Panel: Scratch < 50mm, Paint Chip-off < 5mm

Rear right door



Panel: Low Visual Dent < 30mm, Light

Scuffing < 50mm, Paint Chip-off < 5mm

Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Light Scuffing < 80mm

Hood Condition

Hood



Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	!	Left Rear Alloy/ Rim	!
Rim: Alloy Edge/ Scuff < 80mm		Rim: Alloy Edge/ Scuff < 80mm	
Right Front Alloy/ Rim	!	Right Rear Alloy/ Rim	!
Rim: Alloy Edge/ Scuff < 80mm		Rim: Alloy Edge/ Scuff < 80mm	
Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Wheel cover	✓
Grill Condition	!	Monogram	✓
Light Scuffing < 50mm			
Window Glass	✓	Wiper	✓
Panel Condition			

Rear Trunk Panel



## Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Cap



Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



## Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



## Dashboard

Instrument Panel



## Airbags

Airbags



## Controls



Cruise Control



## Infotainment Display



Engine Sensors



## OBD Connector



Music System



## Lights

Headlight



Interior Lights



Tail Light Cluster



Left Tail Lamp: Light Scuffing < 50mm

License Plate Light



Fog Lights



## Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch



Parking Sensors



Rear Defogger



USB Charging Port



Power/ Manual Windows



## Interiors & Luggage

Dashboard And Instrument Panel



Central Console

Cigarette Lighter: Cigarette Lighter Missing



Cup Holder



Glove Box



Steering Wheel



Sunvisor



Seat Upholstery



Manual Seat Movement



Seat Belts



Head Rest



## Door Controls And Trim

Rear Left Door: Light Scuffing



Grab Handle



Carpet



Headliner



Rear View Mirror



Toolkit



## Tyres

### Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



### Tyres Depth (Remaining)

LHS Front Tyre

<55%

LHS Rear Tyre

<75%

RHS Front Tyre

<55%

RHS Rear Tyre

<75%

Spare Tyre

<65%



**A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE