



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2019 BMW X3**

**XDRIVE 30I EXCLUSIVE | 79,584 KM**

**VIN: WBATR9A09KLC63076**

## **Car highlights**



### **Panoramic Roof**

This car has a panoramic roof



### **Cruise control**

Cruise control to drive with ease & comfort



### **Apple play**

Enjoy your drive with apple play



### **Amazing Comfort**

Power driver seat, Memory Seats

## Basic Details

 Kilometers	<b>79584</b>	 Specs	<b>Yes</b>
 Engine	<b>2.0L</b>	 Option Type	<b>Semi Loaded</b>
 Transmission	<b>Automatic</b>	 Drive	<b>All Wheel Drive</b>
 Body Type	<b>SUV</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color White</b>
 Interior Trim	<b>Leather Trim</b>	 Number of Airbags	<b>8 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>2 Keys</b>
 VIN number	<b>WBATR9A09KLC63076</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Climate Control AC		Cruise Control	
Memory Seats		Rear Armrest with cupholder	
Steering Mounted Audio Controls		Power Folding Mirrors	
Power Tailgate/ Power Trunk		Rear Defogger	
Central Armrest		MagSafe Wireless	

## Charging

Automatic Headlights



### Exteriors

Fog Light Front



Roof Rails



Running Lights



Rear Bumper Spoiler



LED Headlights



### Safety & Security

Navigation



Parking Sensors Front



Parking Sensors Rear



Auto Park Assist



Reverse Camera



Traction Control



Airbag Curtain Shield



Airbag Driver Front



ABS



Central Locking



Child Safety Locking



### Performance

Paddle Shift



Hill Descent Control



### Entertainment

Bluetooth Player



Apple Play



Android Auto Play



Infotainment System



USB player



# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## 🚗 Exterior

Doors condition

Front left door



Front right door



Panel: Paint Chip-off < 5mm

Rear left door



Rear right door



Panel: Light Scuffing < 50mm

Fenders Condition

Left Fender



Right Fender



Condition: Paint Chip-off < 5mm

Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Condition: Chip<5mm

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood



Bonnet: Paint Chip-off < 5mm

Trunk Condition

Trunk



Door Trim: Light Scuffing < 50mm

Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	!
Right B to C Pillar Beading	✓	Low Visual Dent < 50mm	
		Left C Pillar	!
		Scratch < 50mm	
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	
		Rim: Alloy Face/ Scuff < 50mm, Alloy Edge/ Scuff < 80mm	!
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	
		Rim: Alloy Face/ Scuff < 50mm, Alloy Edge/ Scuff < 80mm	!
Wheel cover	✓	Antenna	✓

Grill Condition	!	Monogram	✓
Light Scuffing < 50mm			
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel	✓		

---

## ⌚ Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Gear shift	✓
Drive Axle	✓	4*4 Condition (If Applicable)	✓
Transmission Fluid	✓		

---

## ⌚ Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Navigation System



Music System



Sunroof Operation

Sunroof



Camera



Lights

Headlight



Interior Lights



Tail Light Cluster

Left Tail Lamp: Light Scuffing < 50mm



Turn Signal Lights



Daylight Running Lights



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch 

Fair Use Wear

Rear Defogger 

Extensive Wear Of Strip

USB Charging Port 

Power/ Manual Windows 

Memory Seats 

## **Interiors & Luggage**

Dashboard And Instrument Panel 

Central Console 

Cup Holder 

Glove Box 

Steering Wheel 

Steering Wheel Fair Use Wear

Sunvisor 

Seat Upholstery 

Manual Seat Movement 

Seat Belts 

Head Rest 

Door Controls And Trim 

Rear Left Door: Crack/Fair Use Wear

Grab Handle 

Carpet 

Headliner 

Rear View Mirror 

Toolkit 

## **Tyres**

Tyres Condition

Left Hand Side Front Tyre 

Left Hand Side Rear Tyre 

Right Hand Side Front Tyre 

Right Hand Side Rear Tyre 

Tyres Depth (Remaining)

LHS Front Tyre <85%

LHS Rear Tyre <85%

RHS Front Tyre <75%

RHS Rear Tyre <75%

Spare Tyre No spare

tyre



**A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE