



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2015 CHEVROLET TRAX**

**LTZ | 66,942 KM**

VIN: KL1JJ7E53FB117221

## Car highlights



### **Sunroof**

This car has a sunroof



### **Cruise control**

Cruise control to drive with ease & comfort



### **Bluetooth**
















Enjoy your drive with bluetooth



### **Amazing Comfort**











Power driver seat





## Basic Details

|  |                          |   |                             |
|--|--------------------------|---|-----------------------------|
|  Kilometers       | <b>66942</b>             |  Specs             | <b>Yes</b>                  |
|  Engine           | <b>1.8L</b>              |  Option Type       | <b>Fully Loaded</b>         |
|  Transmission     | <b>Automatic</b>         |  Drive             | <b>All Wheel Drive</b>      |
|  Body Type        | <b>SUV</b>               |  Fuel              | <b>Petrol</b>               |
|  Wheel Type       | <b>Alloy Wheels</b>      |  Exterior Color    | <b>Exterior Color White</b> |
|  Interior Trim    | <b>Leather Trim</b>      |  Number of Airbags | <b>6 Airbags</b>            |
|  Seating Capacity | <b>5 Seats</b>           |  Number of keys    | <b>1 Keys</b>               |
|  VIN number      | <b>KL1JJ7E53FB117221</b> |   |                             |

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|  |   |                             |   |
|--|---|-----------------------------|---|
|  <b>Exteriors</b>                 |   |                             |   |
| Fog Light Front  |  | Roof Rails                  |  |
| Rear Bumper Spoiler  |  | Halogen Headlights          |  |
|  <b>Comfort &amp; Convenience</b> |   |                             |   |
| Cruise Control   |  | Rear Armrest with cupholder |  |
| Steering Mounted Audio Controls  |  | Rear Defogger               |  |

|  |   |                       |   |
|--|---|-----------------------|---|
| Central Armrest  |   | Remote Engine Start   |   |
| Automatic Headlights   |  |                       |   |
|  <b>Safety &amp; Security</b> |   |                       |   |
| Parking Sensors Rear   |  | Reverse Camera        |  |
| Traction Control   |  | Airbag Curtain Shield |  |
| Airbag Driver Front  |  | ABS                   |  |
| Central Locking  |  | Child Safety Locking  |  |
|  <b>Entertainment</b>         |   |                       |   |
| Bluetooth Player   |  | Infotainment System   |  |
| USB player   |  |                       |   |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## Exterior

### Doors condition

Front left door



Front right door



Rear left door



Rear right door



Inner Handle: minor imperfection

### Fenders Condition

Left Fender



Right Fender



### Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



### Front Bumper Condition

Front Bumper



### Rear Bumper Condition

Rear Bumper



Rear Bumper: Dent < 50mm

### Hood Condition

Hood



Bonnet: Low Visibility Dent < 30mm

### Trunk Condition

Trunk



### Trunk condition

Trunk



### Roof Condition

Roof



### Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



|                                       |   |  |   |
|---------------------------------------|---|--|---|
| Right A to B Pillar                   | ✓ | Left B Pillar  | ✓ |
| Left B Pillar Trim                    | ✓ | Left B to C Pillar Beading                             | ✓ |
| Right C Pillar Trim                   | ✓ | Right B to C Pillar                                    | ✓ |
| Right B to C Pillar Beading           | ✓ | Left C Pillar<br>Scratch < 50mm                        | ! |
| Running Board Condition               |   |  |   |
| Left Running Board                    | ✓ | Right Running Board                                    | ✓ |
| Sunroof Glass Condition (If Equipped) |   |  |   |
| Sun Roof Glass                        | ✓ |  |   |
| Windshield Condition                  |   |  |   |
| Front Windshield                      | ✓ | Rear Windshield<br>minor imperfection                  | ! |
| Structural Assessment                 |   |  |   |
| Chassis Condition                     | ✓ | Radiator Support                                       | ✓ |
| Apron                                 | ✓ | Boot Floor   | ✓ |
| Firewall Condition                    | ✓ | Cowl Top   | ✓ |
| Head Light Support Condition          | ✓ |  |   |
| Cowl Top                              |   |  |   |
| Cowl Top                              | ✓ |  |   |
| Rear View Mirror Condition            |   |  |   |
| Left Hand Side Mirror                 | ✓ | Left Side Mirror                                       | ✓ |
| Right Side Mirror                     | ✓ |  |   |
| Alloy Wheel/ Rim                      |   |  |   |
| Left Front Alloy/ Rim                 | ✓ | Left Rear Alloy/ Rim                                   | ✓ |
| Right Front Alloy/ Rim                | ✓ | Right Rear Alloy/ Rim<br>Rim: Alloy Face/ Scuff < 50mm | ! |
| Spare Alloy/ Rim Condition            | ✓ |  |   |
| Wheel cover                           | ✓ | Antenna  | ✓ |
| Grill Condition                       | ✓ | Monogram   | ✓ |

|                  |  |       |  |
|------------------|--|-------|--|
| Window Glass     |  | Wiper |  |
| Panel Condition  |  |       |  |
| Rear Trunk Panel |  |       |  |

## Engine & Transmission

### Engine

|  |  |                    |  |
|--|--|--------------------|--|
| Engine Body  |  | Engine Performance |  |
| Engine Oil (Condition & Level)<br>minor imperfection |  | Exhaust System     |  |
| Radiator Condition                                   |  | Radiator Coolant   |  |
| Battery  |  |                    |  |
| Battery Terminal & Tightness                         |  |                    |  |
| Fuel System  |  |                    |  |
| Fuel Tank  |  |                    |  |
| Transmission Operation                               |  |                    |  |
| Gear Shifting  |  | Drive Axle         |  |
| 4*4 Condition (If Applicable)                        |  | Transmission Fluid |  |

## Steering, Suspension & Brakes

### Steering

|                        |  |                       |  |
|------------------------|--|-----------------------|--|
| Steering wheel         |  |                       |  |
| Brake System           |  |                       |  |
| Parking Brake          |  | Brake Master Cylinder |  |
| Brake Disc & Brake Pad |  | Brake Fluid           |  |
| Pedals                 |  |                       |  |
| Suspension             |  |                       |  |
| Shock Absorbers        |  |                       |  |

## Electricals, Controls & Lights

Keys

|                      |   |                              |   |
|----------------------|---|------------------------------|---|
| Master Key           | ✓ |                              |   |
| Door Locks           |   |                              |   |
| Child Safety Locking | ✓ |                              |   |
| Dashboard            |   |                              |   |
| Instrument Panel     | ✓ |                              |   |
| Airbags              |   |                              |   |
| Airbags              | ✓ |                              |   |
| Controls             | ✓ | Cruise Control               | ✓ |
| Infotainment Display | ✓ | Engine Sensors               | ✓ |
| OBD Connector        | ✓ | Music System                 | ✓ |
| Sunroof Operation    |   |                              |   |
| Sunroof              | ✓ |                              |   |
| Lights               |   |                              |   |
| Headlight            | ✓ | Interior Lights              | ✓ |
| Tail Light Cluster   | ✓ | License Plate Light          | ✓ |
| Fog Lights           | ✓ |                              |   |
| Air Conditioning     |   |                              |   |
| AC Cooling           | ✓ | AC Switch                    | ✓ |
| AC System Leaks      | ✓ | Center AC Vent               | ✓ |
| Front Right AC Vent  | ✓ | Heater<br>Heater Not Working | ! |
| Parking Sensors      | ✓ | Rear Defogger                | ✓ |
| USB Charging Port    | ✓ | Power/ Manual Windows        | ✓ |

## Interiors & Luggage

|                                |   |  |   |
|--------------------------------|---|--|---|
| Dashboard And Instrument Panel | ✓ | Central Console<br>Gear Shift Knob: Knob Fair Use Wear | ! |
| Cup Holder                     | ✓ | Glove Box  | ✓ |

|                        |   |                      |   |
|------------------------|---|----------------------|---|
| Steering Wheel         | ✓ | Sunvisor             | ✓ |
| Seat Upholstery        | ✓ | Manual Seat Movement | ✓ |
| Seat Belts             | ✓ | Head Rest            | ✓ |
| Door Controls And Trim | ✓ | Grab Handle          | ✓ |
| Carpet                 | ✓ | Headliner            | ✓ |
| Rear View Mirror       | ✓ | Toolkit              | ✓ |

## Tyres

### Tyres Condition

|                            |   |                           |   |
|----------------------------|---|---------------------------|---|
| Left Hand Side Front Tyre  | ✓ | Left Hand Side Rear Tyre  | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre                 | ✓ |                           |   |

### Tyres Depth (Remaining)

|                |      |               |      |
|----------------|------|---------------|------|
| LHS Front Tyre | <85% | LHS Rear Tyre | <85% |
| RHS Front Tyre | <85% | RHS Rear Tyre | <85% |
| Spare Tyre     | <65% |               |      |



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE