



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2016 MERCEDES BENZ C 200

AVANTGARDE | 106,264 KM

VIN: WDDWF4CB5GR142630

Car highlights



Panoramic Roof

This car has a panoramic roof



Cruise control

Cruise control to drive with ease & comfort



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort











Power driver seat

Basic Details

 Kilometers	106264	 Specs	Yes
 Engine	2.0L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Rear Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Silver
 Interior Trim	Leather Trim	 Number of Airbags	9 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	WDDWF4CB5GR142630		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Climate Control AC		Cruise Control	
Rear Armrest with cupholder		Steering Mounted Audio Controls	
Rear Defogger		Central Armrest	
Automatic Headlights		Steering Column Adjuster	
 Safety & Security			

Navigation	✓	Parking Sensors Front	✓
Parking Sensors Rear	✓	Reverse Camera	✓
Traction Control	✓	Airbag Curtain Shield	✓
Airbag Knees	✓	Airbag Driver Front	✓
ABS	✓	Central Locking	✓
Child Safety Locking	✓		
 Performance			
Paddle Shift	✓		
 Exteriors			
Running Lights	✓	Halogen Headlights	✓
 Entertainment			
Bluetooth Player	✓	Infotainment System	✓
USB player	✓		

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door		Front right door	
		Panel: Paint Chip-off < 5mm	

Rear left door		Rear right door	
		Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm	

Fenders Condition

Left Fender		Right Fender	
		Right Fender: Scratch < 50mm	

Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
		Condition: Scratch < 50mm	


Front Bumper Condition

Front Bumper	
--------------	---

Rear Bumper Condition

Rear Bumper	
Rear Bumper: Chip< 8mm, Light Scuffing < 80mm	

Hood Condition

Hood	
Bonnet: Paint Chip-off < 5mm	

Trunk Condition

Trunk	
-------	---

Trunk conditon

Trunk	
-------	---

Roof Condition

Roof	
------	---

Pillars Condition

Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim		Left Rear Alloy/ Rim	
Rim: Alloy Face/ Scuff > 50mm, Alloy Edge/ Scuff < 80mm	!	Rim: Alloy Face/ Scuff < 50mm, Alloy Edge/ Scuff < 80mm	!
Right Front Alloy/ Rim		Right Rear Alloy/ Rim	
Rim: Alloy Face/ Scuff < 50mm, Alloy Edge/ Scuff < 80mm	!	Rim: Alloy Face/ Scuff < 50mm	!
Spare Alloy/ Rim Condition	✓		

Grill Condition	⚠	Monogram	✓
Light Scuffing < 50mm			
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel	✓		

🔧 Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Gear shift	✓
Drive Axle	✓	Transmission Fluid	✓

🚗 Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			
Shock Absorbers	✓		



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Navigation System



Music System



Sunroof Operation

Sunroof



Camera



Lights

Headlight



Interior Lights



Tail Light Cluster



Daylight Running Lights



License Plate Light



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch



Rear Defogger



USB Charging Port



Power/ Manual Windows



Interiors & Luggage

Dashboard And Instrument Panel



Central Console



Cup Holder



Glove Box



Steering Wheel



Sunvisor



Steering Wheel Fair Use Wear

Seat Upholstery



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim



Grab Handle



Carpet



Headliner



Rear View Mirror



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<55%

LHS Rear Tyre

<85%

RHS Front Tyre

<55%

RHS Rear Tyre

<85%

Spare Tyre

No spare

tyre



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE