



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 6 Months Warranty

This car comes with 6 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2023 MG ZS**

**STD | 23,996 KM**

VIN: LSJW74U33PZ034973

## Car highlights



### **Manufacturer warranty**

Till 03/10/2027 or 2,00,000 km (Verified)



### **Cruise control**

Cruise control to drive with ease & comfort



### **Apple play**















Enjoy your drive with apple play



### **Amazing Comfort**










Power driver seat

## Basic Details

|  |                          |   |                              |
|--|--------------------------|---|------------------------------|
|  Kilometers       | <b>23996</b>             |  Specs             | <b>Yes</b>                   |
|  Engine           | <b>1.5L</b>              |  Option Type       | <b>Basic</b>                 |
|  Transmission     | <b>Automatic</b>         |  Drive             | <b>Front Wheel Drive</b>     |
|  Body Type        | <b>SUV</b>               | Fuel Efficiency   | <b>17.2 km/L mileage</b>     |
|  Wheel Type       | <b>Alloy Wheels</b>      |  Exterior Color    | <b>Exterior Color Silver</b> |
|  Interior Trim    | <b>Fabric Trim</b>       |  Number of Airbags | <b>2 Airbags</b>             |
|  Seating Capacity | <b>5 Seats</b>           |  Number of keys    | <b>2 Keys</b>                |
|  VIN number      | <b>LSJW74U33PZ034973</b> |   |                              |

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|  <b>Comfort &amp; Convenience</b> |   |
|--|---|
| Cruise Control                    | Steering Mounted Audio Controls  |
| Rear Defogger                     | Central Armrest                  |
| Steering Column Adjuster          |   |
|  <b>Safety &amp; Security</b>     |   |
| Parking Sensors Rear              | Reverse Camera                   |

|  |   |                     |   |
|--|---|---------------------|---|
| Traction Control   | ✓ | Airbag Driver Front | ✓ |
| ABS  | ✓ | Central Locking     | ✓ |
| Child Safety Locking   | ✓ |                     |   |
|  <b>Exteriors</b>     |   |                     |   |
| Roof Rails   | ✓ | Running Lights      | ✓ |
| LED Headlights   | ✓ |                     |   |
|  <b>Performance</b>   |   |                     |   |
| Hill Descent Control   | ✓ |                     |   |
|  <b>Entertainment</b> |   |                     |   |
| Bluetooth Player   | ✓ | Apple Play          | ✓ |
| Android Auto Play  | ✓ | USB Charging Port   | ✓ |
| Infotainment System  | ✓ | USB player          | ✓ |





# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

|                 |   |  |   |
|-----------------|---|--|---|
| Front left door |  | Front right door<br>Panel: Light Scuffing < 50mm |  |
| Rear left door  |  | Rear right door<br>Panel: Light Scuffing < 50mm  |  |

### Fenders Condition

|             |   |              |   |
|-------------|---|--------------|---|
| Left Fender |  | Right Fender |  |
|-------------|---|--------------|---|

### Quarter Panels Condition

|                    |   |  |   |
|--------------------|---|--|---|
| Left Quarter Panel |  | Right Quarter Panel<br>Condition: Light Scuffing |  |
|--------------------|---|--|---|

### Front Bumper Condition

|              |   |
|--------------|---|
| Front Bumper |  |
|--------------|---|

### Rear Bumper Condition

|   |   |
|---|---|
| Rear Bumper<br>Rear Bumper: Light Scuffing < 80mm |  |
|---|---|

### Hood Condition

|      |   |
|------|---|
| Hood |  |
|------|---|

### Trunk Condition

|       |   |
|-------|---|
| Trunk |  |
|-------|---|





### Trunk condition

|       |   |
|-------|---|
| Trunk |  |
|-------|---|

### Roof Condition

|      |   |
|------|---|
| Roof |  |
|------|---|

### Pillars Condition

|                            |   |                             |   |
|----------------------------|---|-----------------------------|---|
| Left A Pillar              |  | Right A Pillar              |  |
| Left A to B Pillar Beading |  | Right A to B Pillar Beading |  |

|                             |   |                              |   |
|-----------------------------|---|------------------------------|---|
|                             |   | Beading Crack/ Tear < 5mm    |   |
| Right A to B Pillar         | ✓ | Left B Pillar                | ✓ |
| Left B Pillar Trim          | ✓ | Left B to C Pillar Beading   | ✓ |
| Right C Pillar Trim         | ✓ | Right B to C Pillar          | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar                | ✓ |
| Running Board Condition     |   |                              |   |
| Left Running Board          | ✓ | Right Running Board          | ✓ |
| Windshield Condition        |   |                              |   |
| Front Windshield            | ✓ | Rear Windshield              | ✓ |
| Structural Assessment       |   |                              |   |
| Chassis Condition           | ✓ | Apron                        | ✓ |
| Boot Floor                  | ✓ | Firewall Condition           | ✓ |
| Cowl Top                    | ✓ | Head Light Support Condition | ✓ |
| Cowl Top                    |   |                              |   |
| Cowl Top                    | ✓ |                              |   |
| Rear View Mirror Condition  |   |                              |   |
| Left Hand Side Mirror       | ✓ | Left Side Mirror             | ✓ |
| Right Side Mirror           | ✓ |                              |   |
| Alloy Wheel/ Rim            |   |                              |   |
| Left Front Alloy/ Rim       | ✓ | Left Rear Alloy/ Rim         | ✓ |
| Right Front Alloy/ Rim      | ✓ | Right Rear Alloy/ Rim        | ✓ |
| Spare Alloy/ Rim Condition  | ✓ |                              |   |
| Wheel cover                 | ✓ | Antenna                      | ✓ |
| Grill Condition             |   | Monogram                     | ✓ |
| Light Scuffing < 50mm       | ! |                              |   |
| Window Glass                | ✓ | Wiper                        | ✓ |
| Panel Condition             |   |                              |   |
| Rear Trunk Panel            | ✓ |                              |   |

## Engine & Transmission

### Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



### Fuel System

Fuel Tank



### Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



## Steering, Suspension & Brakes

### Steering

Steering wheel



### Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



### Suspension

Shock Absorbers



## Electricals, Controls & Lights

### Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



|                      |   |                         |   |
|----------------------|---|-------------------------|---|
| Controls             | ✓ | Cruise Control          | ✓ |
| Infotainment Display | ✓ | OBD Connector           | ✓ |
| Music System         | ✓ | Camera                  | ✓ |
| Lights               |   |                         |   |
| Headlight            | ✓ | Interior Lights         | ✓ |
| Tail Light Cluster   | ✓ | Daylight Running Lights | ✓ |
| License Plate Light  | ✓ |                         |   |
| Air Conditioning     |   |                         |   |
| AC Cooling           | ✓ | AC Switch               | ✓ |
| AC System Leaks      | ✓ | Center AC Vent          | ✓ |
| Front Right AC Vent  | ✓ | Heater                  | ✓ |
| Rear Blower Switch   | ✓ |                         |   |
| Parking Sensors      | ✓ | Rear Defogger           | ✓ |
| USB Charging Port    | ✓ | Power/ Manual Windows   | ✓ |

---

 **Interiors & Luggage**

|                                |   |                        |   |
|--------------------------------|---|------------------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console        | ✓ |
| Glove Box                      | ✓ | Steering Wheel         | ✓ |
| Sunvisor                       | ✓ | Seat Upholstery        | ✓ |
| Manual Seat Movement           | ✓ | Seat Belts             | ✓ |
| Head Rest                      | ✓ | Door Controls And Trim | ✓ |
| Grab Handle                    | ✓ | Carpet                 | ✓ |
| Headliner                      | ✓ | Rear View Mirror       | ✓ |
| Toolkit                        | ✓ |                        |   |

## Tyres

### Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



### Life remaining

LHS Front Tyre

<55%

LHS Rear Tyre

<65%

RHS Front Tyre

<55%

RHS Rear Tyre

<65%

Spare Tyre

<75%



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE