



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2018 MITSUBISHI PAJERO**

**GLS HIGHLINE | 73,306 KM**

VIN: JE4NR62R1JJ710990

## **Car highlights**



### **Four wheel drive**

This car has a Four wheel drive



### **Cruise control**

Cruise control to drive with ease & comfort



### **Bluetooth**
















Enjoy your drive with bluetooth



### **Amazing Comfort**












Power driver seat





Basic Details

|  |                   |   |                      |
|--|-------------------|---|----------------------|
|  Kilometers       | 73306             |  Specs             | Yes                  |
|  Engine           | 3.8L              |  Option Type       | Fully Loaded         |
|  Transmission     | Automatic         |  Drive             | Four Wheel Drive     |
|  Body Type        | SUV               |  Fuel              | Petrol               |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color White |
|  Interior Trim    | Leather Trim      |  Number of Airbags | 8 Airbags            |
|  Seating Capacity | 7 Seats           |  Number of keys    | 2 Keys               |
|  VIN number     | JE4NR62R1JJ710990 |   |                      |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|  Safety & Security     |  |   |  |
|---|--|---|--|
| 360 degree Camera      |  | Navigation           |  |
| Parking Sensors Rear   |  | Reverse Camera       |  |
| Blind Spot Monitor     |  | Traction Control     |  |
| Front Camera           |  | Side Camera          |  |
| Airbag Curtain Shield  |  | Airbag Driver Front  |  |

|  |   |                                 |   |
|--|---|---------------------------------|---|
| ABS  | ✓ | Central Locking                 | ✓ |
| Child Safety Locking   | ✓ |                                 |   |
|  <b>Comfort &amp; Convenience</b> |   |                                 |   |
| Climate Control AC   | ✓ | Cruise Control                  | ✓ |
| Rear Armrest with cupholder  | ✓ | Steering Mounted Audio Controls | ✓ |
| Power Folding Mirrors  | ✓ | Rear Defogger                   | ✓ |
| Central Armrest  | ✓ | Steering Column Adjuster        | ✓ |
|  <b>Exteriors</b>                 |   |                                 |   |
| Fog Light Front  | ✓ | Roof Rails                      | ✓ |
| Running Lights   | ✓ | Rear Bumper Spoiler             | ✓ |
| Halogen Headlights   | ✓ | HID Headlights                  | ✓ |
|  <b>Entertainment</b>           |   |                                 |   |
| Rear Seat Entertainment  | ✓ | Bluetooth Player                | ✓ |
| Infotainment System  | ✓ | USB player                      | ✓ |
|  <b>Performance</b>             |   |                                 |   |
| Differential Locks   | ✓ |                                 |   |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

|                 |   |   |   |
|-----------------|---|---|---|
| Front left door |  | Front right door                                      |  |
|                 |   | Moulding: Light Scuffing < 50mm, Paint Chip-off < 5mm |   |

|                |   |                               |   |
|----------------|---|-------------------------------|---|
| Rear left door |  | Rear right door               |  |
|                |   | Panel: Low Visual Dent < 30mm |   |

### Fenders Condition

|                           |   |              |   |
|---------------------------|---|--------------|---|
| Left Fender               |  | Right Fender |  |
| Condition: Scratch < 50mm |   |              |   |


### Quarter Panels Condition

|                    |   |  |   |
|--------------------|---|--|---|
| Left Quarter Panel |  | Right Quarter Panel                    |  |
|                    |   | Condition: Dent < 30mm, Scratch < 50mm |   |

### Front Bumper Condition

|              |   |
|--------------|---|
| Front Bumper |  |
|--------------|---|

### Rear Bumper Condition

|   |   |
|---|---|
| Rear Bumper                                   |  |
| Rear Bumper: Light Scuffing < 80mm, Chip< 8mm |   |

### Hood Condition

|      |   |
|------|---|
| Hood |  |
|------|---|

### Trunk Condition

|       |   |
|-------|---|
| Trunk |  |
|-------|---|

### Trunk conditon

|       |   |
|-------|---|
| Trunk |  |
|-------|---|

### Roof Condition

|      |   |
|------|---|
| Roof |  |
|------|---|

### Pillars Condition

|  |   |                               |   |
|--|---|-------------------------------|---|
| Left A Pillar                                  | ✓ | Right A Pillar                | ✓ |
| Left A to B Pillar Beading                     | ✓ | Right A to B Pillar Beading   | ✓ |
| Right A to B Pillar                            | ✓ | Left B Pillar                 | ✓ |
| Left B Pillar Trim                             | ✓ | Left B to C Pillar Beading    | ✓ |
| Right C Pillar Trim                            | ✓ | Right B to C Pillar           | ✓ |
| Right B to C Pillar Beading                    | ✓ | Left C Pillar                 | ✓ |
| Running Board Condition                        |   |                               |   |
| Left Running Board                             | ✓ | Right Running Board           | ✓ |
| Sunroof Glass Condition (If Equipped)          |   |                               |   |
| Sun Roof Glass                                 | ✓ |                               |   |
| Windshield Condition                           |   |                               |   |
| Front Windshield                               |   |                               |   |
| Beading: Mouldings Crack/ Fair Use Wear < 50mm | ! | Rear Windshield               | ✓ |
| Structural Assessment                          |   |                               |   |
| Chassis Condition                              | ✓ | Radiator Support              | ✓ |
| Apron  | ✓ | Boot Floor                    | ✓ |
| Firewall Condition                             | ✓ | Cowl Top                      | ✓ |
| Head Light Support Condition                   | ✓ |                               |   |
| Cowl Top                                       |   |                               |   |
| Cowl Top                                       | ✓ |                               |   |
| Rear View Mirror Condition                     |   |                               |   |
| Left Hand Side Mirror                          | ✓ | Left Side Mirror              | ✓ |
| Right Side Mirror                              | ✓ |                               |   |
| Alloy Wheel/ Rim                               |   |                               |   |
| Left Front Alloy/ Rim                          | ! | Left Rear Alloy/ Rim          | ✓ |
| Rim: Alloy Face/ Scuff < 50mm                  |   |                               |   |
| Right Front Alloy/ Rim                         | ! | Right Rear Alloy/ Rim         | ! |
| Rim: Alloy Edge/ Scuff < 80mm                  |   | Rim: Alloy Edge/ Scuff < 80mm |   |
| Spare Alloy/ Rim Condition                     | ✓ |                               |   |

|                  |   |  |   |
|------------------|---|--|---|
| Antenna          | ✓ | Grill Condition<br>Light Scuffing < 50mm | ⚠ |
| Monogram         | ✓ | Window Glass                             | ✓ |
| Wiper            | ✓ |  |   |
| Panel Condition  |   |  |   |
| Rear Trunk Panel | ✓ |  |   |

## 🔧 Engine & Transmission

|                                |   |                    |   |
|--------------------------------|---|--------------------|---|
| Engine                         |   |                    |   |
| Engine Body                    | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System     | ✓ |
| Radiator Condition             | ✓ | Radiator Coolant   | ✓ |
| Battery                        |   |                    |   |
| Battery Terminal & Tightness   | ✓ |                    |   |
| Fuel System                    |   |                    |   |
| Fuel Tank                      | ✓ |                    |   |
| Transmission Operation         |   |                    |   |
| Gear Shifting                  | ✓ | Drive Axle         | ✓ |
| 4*4 Condition (If Applicable)  | ✓ | Transmission Fluid | ✓ |

## 🚗 Steering, Suspension & Brakes

|                        |   |                       |   |
|------------------------|---|-----------------------|---|
| Steering               |   |                       |   |
| Steering wheel         | ✓ |                       |   |
| Brake System           |   |                       |   |
| Parking Brake          | ✓ | Brake Master Cylinder | ✓ |
| Brake Disc & Brake Pad | ✓ | Brake Fluid           | ✓ |
| Pedals                 | ✓ |                       |   |
| Suspension             |   |                       |   |
| Shock Absorbers        | ✓ |                       |   |



## Electricals, Controls & Lights

### Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Music System

Steering Mounted Audio Controls: Not Working Properly



Sunroof Operation

Sunroof



### Lights

Headlight



Interior Lights



Tail Light Cluster



Daylight Running Lights



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch



Rear Left AC Vent



Parking Sensors



Rear Defogger



USB Charging Port



Rear Entertainment





Power/ Manual Windows



## Interiors & Luggage

Dashboard And Instrument Panel

Dashboard Trim: Light Scuffing/Disfiguration



Central Console



Cup Holder



Glove Box



Steering Wheel



Sunvisor



Seat Upholstery

Passenger Seat: Minor Smudge/Cracks



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim



Grab Handle



Carpet



Headliner



Rear View Mirror



Toolkit



## Tyres

Tyres Condition

Left Hand Side Front Tyre



Right Hand Side Front Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<75%

LHS Rear Tyre

<75%

RHS Front Tyre

<75%

RHS Rear Tyre

<75%

Spare Tyre

<65%



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE