



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2017 HYUNDAI ACCENT

GL | 127,059 KM

VIN: KMHCT41B5HU158894

Car highlights



Bluetooth

Enjoy your drive with bluetooth



Music System

Enjoy your drive with music system



Amazing Comfort
















Power driver seat



Airbag safety










Airbag Driver Front

Basic Details

 Kilometers	127059	 Specs	Yes
 Engine	1.4L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Steel Wheels	 Exterior Color	Exterior Color Black
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	KMHCT41B5HU158894		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

<div> Exteriors</div>				
Fog Light Front		<div></div>	Halogen Headlights	<div></div>
<div> Safety & Security</div>				
Traction Control		<div></div>	Airbag Driver Front	<div></div>
ABS		<div></div>	Central Locking	<div></div>
Child Safety Locking		<div></div>		



Comfort & Convenience

Steering Mounted Audio
Controls



Entertainment

Bluetooth Player



Infotainment System



USB player







150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



Passed 

Exterior



Doors condition

Front left door		Front right door	
		Handle: Paint Chip-off < 5mm	
Rear left door		Rear right door	
Panel: Scratch < 50mm, Paint Chip-off < 5mm, Dent < 30mm		Handle: Paint Chip-off < 5mm	

Fenders Condition

Left Fender		Right Fender	
Condition: Paint Chip-off < 5mm, Scratch < 50mm		Right Fender: Paint Chip-off < 5mm, Dent < 30mm, Scratch < 50mm	


Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
Condition: Scratch < 50mm, Dent < 30mm, Paint Chip-off < 5mm		Condition: Dent < 30mm, Paint Chip-off < 5mm, Scratch < 50mm	

Front Bumper Condition

Front Bumper 

Rear Bumper Condition

Rear Bumper
Rear Bumper: Light Scuffing < 80mm, Chip< 8mm 

Hood Condition

Hood
Bonnet: Paint Chip-off < 5mm, Light Scuffing < 50mm, Low Visibility Dent < 30mm 

Trunk Condition

Trunk 

Trunk conditon

Trunk 

Roof Condition

Roof	✓		
Pillars Condition			
Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar Low Visual Dent < 50mm	!
Right B to C Pillar Beading	✓	Left C Pillar Scratch < 50mm	!
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield			
Condition: Driver Side/Stone Chip Mark<5mm, Passenger Side/Stone Chip Mark<8mm	!	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Wheel cover Front Right: Face/ Scuffs < 50mm	!

Antenna	✓	Grill Condition Light Scuffing < 50mm	⚠
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel	✓		

🔧 Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

🚗 Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			
Shock Absorbers	✓		



Electricals, Controls & Lights

Keys

Master Key



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Infotainment Display



Engine Sensors



OBD Connector



Music System

Steering Mounted Audio Controls: Button(s)



Faded

Lights

Headlight



Tail Light Cluster

Left Tail Lamp: Crack / Fair Use Wear < 5mm



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



USB Charging Port



Power/ Manual Windows



Interiors & Luggage

Dashboard And Instrument Panel



Central Console



Cup Holder



Glove Box



Steering Wheel



Sunvisor



Color Faded

Seat Upholstery Driver Seat: Minor Smudge/ Cracks	ⓘ	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
Carpet	✓	Headliner Front Left: Light Smudge/Disfiguration	ⓘ
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<55%	LHS Rear Tyre	<55%
RHS Front Tyre	<55%	RHS Rear Tyre	<55%
Spare Tyre	<75%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE