



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2016 CHEVROLET CRUZE

LT | 65,417 KM

VIN: KL1PM6D51GK301443

Car highlights



Sunroof

This car has a sunroof



Cruise control

Cruise control to drive with ease & comfort



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	65417	 Specs	Yes
 Engine	1.8L	 Option Type	Fully Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	HATCHBACK	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Silver
 Interior Trim	Leather Trim	 Number of Airbags	4 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	KL1PM6D51GK301443		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience	
Climate Control AC	
Rear Armrest with cupholder	
Rear Defogger	
 Exteriors	
Fog Light Front	
	
Running Lights	

Halogen Headlights



Safety & Security

Parking Sensors Rear



Reverse Camera



Blind Spot Monitor



Airbag Driver Front



ABS



Central Locking



Child Safety Locking



Entertainment

Bluetooth Player



USB Charging Port



Infotainment System



USB player



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front left door



Front right door

Panel: Low Visibility Dent < 30mm, Light



Scuffing < 50mm

Rear left door



Rear right door

Panel: Dent < 30mm, Scratch < 50mm

Panel: Low Visual Dent < 30mm, Light



Scuffing < 50mm

Fenders Condition

Left Fender



Right Fender

Condition: Dent < 30mm, Scratch < 50mm



Right Fender: Scratch < 50mm

Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel

Condition: Dent < 30mm, Scratch < 50mm



Condition: Dent < 30mm, Scratch < 50mm

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm, Crack/



Misaligned

Hood Condition

Hood

Bonnet: Low Visibility Dent < 30mm, Paint



Chip-off < 5mm

Trunk Condition

Trunk



Trunk conditon

Trunk

Lock: Switch Fair Use Wear/ Not Working



Roof Condition

Roof		
Pillars Condition		
Left A Pillar		Right A Pillar
Left A to B Pillar Beading		Right A to B Pillar Beading
Right A to B Pillar		Left B Pillar
Left B Pillar Trim		Left B to C Pillar Beading
Right C Pillar Trim		Right B to C Pillar
Right B to C Pillar Beading		Left C Pillar
Running Board Condition		
Left Running Board		Right Running Board Condition: Light Scuffing < 80mm
Sunroof Glass Condition (If Equipped)		
Sun Roof Glass		
Windshield Condition		
Front Windshield		Rear Windshield
Structural Assessment		
Chassis Condition		
VIN Plate: Vin Sticker Not Available		Radiator Support
Apron		Boot Floor
Firewall Condition		Cowl Top
Head Light Support Condition		
Cowl Top		
Cowl Top		
Minor Color Dullness		
Rear View Mirror Condition		
Left Hand Side Mirror		Left Side Mirror
Right Side Mirror		Right Hand Side Mirror
Alloy Wheel/ Rim		
Left Front Alloy/ Rim		Left Rear Alloy/ Rim Rim: Alloy Face/ Scuff < 50mm
Right Front Alloy/ Rim		Right Rear Alloy/ Rim

Rim: Alloy Edge/ Scuff < 80mm

Rim: Alloy Edge/ Scuff < 80mm

Spare Alloy/ Rim Condition



Antenna



Grill Condition



Light Scuffing < 50mm

Monogram



Window Glass



Wiper



Panel Condition

Rear Trunk Panel



Scratch < 50mm

Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Dash Light Operation: Not Working

Airbags

Airbags



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Radar (If Equipped)



Music System



Sunroof Operation

Sunroof



Camera



Lights

Headlight



Left: Low Brightness lamps

Interior Lights



Tail Light Cluster



Turn Signal Lights



Daylight Running Lights



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Temperature: Temp in Idling/Drive < 14°C

AC Switch



AC System Leaks	!	Center AC Vent	✓
Temp In Running < 14°C			
Front Right AC Vent	✓	Heater	✓
Rear Defogger	✓	USB Charging Port	✓
Power/ Manual Windows	✓		

Interiors & Luggage

Dashboard And Instrument Panel			
Dashboard Upholstery: Minor Scuffing/ Crack/	!	Central Console	✓
Fair Use Wear			
Cup Holder	✓	Glove Box	✓
Steering Wheel	!	Sunvisor	✓
Steering Wheel Fair Use Wear			
Seat Upholstery			
Driver Seat: Minor Leather/ Fabric Fair Use	!	Manual Seat Movement	✓
Wear/ Tears			
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
Carpet			
Front Left Floor Mat: Smudge/Burn/Crack	!	Headliner	✓
Rear View Mirror	!	Toolkit	✓
De Silvered Mirror<10%			

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<90%	LHS Rear Tyre	<90%
RHS Front Tyre	<90%	RHS Rear Tyre	<90%

Spare Tyre

<55%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE