



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2018 AUDI Q5 45 TFSI QUATTRO | 112,453 KM

VIN: WA1ZZZFY6J2202890

Car highlights



Supercharger/turbocharger

This car has a Supercharger/turbocharger



Cruise control

Cruise control to drive with ease & comfort



Bluetooth


Enjoy your drive with bluetooth



Amazing Comfort


Power driver seat

Basic Details



Specs and features


The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.




Performance			
Paddle Shift	✓	Hill Descent Control	✓
🖔 Safety & Security			
Parking Sensors Front	✓	Parking Sensors Rear	✓
Reverse Camera	✓	Traction Control	✓
Airbag Curtain Shield	•	Airbag Driver Front	•
ABS	•	Central Locking	•
Child Safety Locking	~		
Exteriors			
Roof Rails	✓	Running Lights	•
Rear Bumper Spoiler	•	HID Headlights	•
¶ு Entertainment			
Bluetooth Player	✓	Infotainment System	✓
USB player			

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



Left A to B Pillar Beading	~	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	(!)	Left Rear Alloy/ Rim	(!)
Rim: Alloy Edge/ Scuff > 80mm		Rim: Alloy Edge/ Scuff > 80mm Right Rear Alloy/ Rim	
Right Front Alloy/ Rim	✓	Rim: Alloy Edge/ Scuff > 80mm, Alloy Face/ Scuff < 50mm	!
Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Wheel cover	✓
Grill Condition	(!)	Monogram	✓
Light Scuffing < 50mm			



Electricals, Controls & Lights Keys Master Key Spare Key(s) Door Locks Child Safety Locking Dashboard Instrument Panel Airbags Airbags Controls Cruise Control Infotainment Display **Engine Sensors OBD** Connector Music System Camera Lights Headlight Interior Lights Tail Light Cluster Turn Signal Lights Daylight Running Lights License Plate Light Air Conditioning AC Cooling AC Switch Center AC Vent AC System Leaks Front Right AC Vent Heater Rear Blower Switch Rear Defogger **USB Charging Port** Power/ Manual Windows

Dashboard And Instrument Panel	✓	Central Console	•
Cup Holder Rear Central: Broken/Fair Use Wear	!	Glove Box	•
Steering Wheel Color Faded	!	Sunvisor	•
Seat Upholstery Driver Seat: Minor Cigarette Burn	!	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim Rear Left Door: Scuffing/Disfiguration	!	Grab Handle	•
Carpet	✓	Headliner Front Left: Crack/Fair Use Wear	(!)
Rear View Mirror	✓	Toolkit	✓
Rear View Mirror Tyres	•	Toolkit	•
	✓	Toolkit	
Tyres	•	Toolkit Left Hand Side Rear Tyre	
Tyres Condition	⋄		
Tyres Tyres Condition Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Tyres Tyres Condition Left Hand Side Front Tyre Right Hand Side Front Tyre		Left Hand Side Rear Tyre	
Tyres Tyres Condition Left Hand Side Front Tyre Right Hand Side Front Tyre Spare Tyre	<65%	Left Hand Side Rear Tyre	<85%
Tyres Tyres Condition Left Hand Side Front Tyre Right Hand Side Front Tyre Spare Tyre Tyres Depth (Remaining)	<65% <85%	Left Hand Side Rear Tyre Right Hand Side Rear Tyre	<85% <90%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE