



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2017 FORD FOCUS

ST | 124,054 KM

VIN: WF0FC9KH3HLG21526

Car highlights



Supercharger/turbocharger

This car has a Supercharger/turbocharger



Cruise control

Cruise control to drive with ease & comfort



Apple play
















Enjoy your drive with apple play



Amazing Comfort










Power driver seat



Basic Details

| | | | |
|--|-------------------|---|---------------------|
|  Kilometers | 124054 |  Specs | Yes |
|  Engine | 2.0L |  Option Type | Fully Loaded |
|  Transmission | Manual |  Drive | Front Wheel Drive |
|  Body Type | HATCHBACK |  Fuel | Petrol |
|  Wheel Type | Alloy Wheels |  Exterior Color | Exterior Color Grey |
|  Interior Trim | Leather Trim |  Number of Airbags | 6 Airbags |
|  Seating Capacity | 5 Seats |  Number of keys | 2 Keys |
|  VIN number | WF0FC9KH3HLG21526 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | | |
|--|---|----------------------|---|
|  Comfort & Convenience | | | |
| Climate Control AC |  | Cruise Control |  |
| Steering Mounted Audio Controls |  | Rear Defogger |  |
| Central Armrest |  | Automatic Headlights |  |
| Steering Column Adjuster |  | | |
|  Exteriors | | | |

| | | | |
|--|---|---------------------|---|
| Fog Light Front | ✓ | Rear Bumper Spoiler | ✓ |
| Halogen Headlights | ✓ | | |
|  Safety & Security | | | |
| Parking Sensors Rear | ✓ | Traction Control | ✓ |
| Airbag Curtain Shield | ✓ | Airbag Driver Front | ✓ |
| ABS | ✓ | Central Locking | ✓ |
| Child Safety Locking | ✓ | | |
|  Entertainment | | | |
| Bluetooth Player | ✓ | Apple Play | ✓ |
| Android Auto Play | ✓ | Infotainment System | ✓ |
| USB player | ✓ | | |

150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

| | | | |
|-----------------|---|------------------------------|---|
| Front left door |  | Front right door |  |
| | | Handle: Paint Chip-off < 5mm | |

| | | | |
|----------------|---|-------------------------------|---|
| Rear left door |  | Rear right door |  |
| | | Panel: Low Visual Dent < 30mm | |

Fenders Condition

| | | | |
|-------------|---|------------------------------|---|
| Left Fender |  | Right Fender |  |
| | | Right Fender: Scratch < 50mm | |


Quarter Panels Condition

| | | | |
|--------------------|--|------------------------|--|
| Left Quarter Panel |  | Right Quarter Panel |  |
| | | Condition: Dent < 30mm | |

Front Bumper Condition

| | |
|--------------|---|
| Front Bumper |  |
|--------------|---|

Rear Bumper Condition

| | |
|---|---|
| Rear Bumper | |
| Rear Bumper: Light Scuffing < 80mm, Dent < 50mm |  |

Hood Condition

| | |
|--|---|
| Hood | |
| Bonnet: Light Scuffing < 50mm, Acid Marks/ Bird Dropping < 5mm |  |

Trunk Condition

| | |
|-------|---|
| Trunk |  |
|-------|---|

Trunk conditon

| | |
|-------|---|
| Trunk |  |
|-------|---|

Roof Condition

| | |
|---|---|
| Roof | |
| Roof Moulding Condition: Minor Rubber Beading Fair Use Wear |  |

Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar



Left B Pillar



Left B Pillar Trim



Left B to C Pillar Beading



Right C Pillar Trim



Right B to C Pillar



Light Scuffing

Light Scuffing < 80mm

Right B to C Pillar Beading



Left C Pillar



Running Board Condition

Left Running Board



Right Running Board

Condition: Low Visual Dent < 50mm, Light Scuffing < 80mm



Sunroof Glass Condition (If Equipped)

Sun Roof Glass



Windshield Condition

Front Windshield

Beading: Mouldings Crack/ Fair Use Wear < 50mm



Rear Windshield



Structural Assessment

Chassis Condition



Radiator Support



Apron



Boot Floor



Firewall Condition



Cowl Top



Head Light Support Condition



Cowl Top

Cowl Top



Rear View Mirror Condition

Left Hand Side Mirror



Left Side Mirror



Right Side Mirror



Alloy Wheel/ Rim

Left Front Alloy/ Rim



Left Rear Alloy/ Rim



Rim: Alloy Edge/ Scuff < 80mm

Rim: Alloy Edge/ Scuff < 80mm

Right Front Alloy/ Rim
Rim: Alloy Edge/ Scuff < 80mm



Right Rear Alloy/ Rim
Rim: Alloy Edge/ Scuff < 80mm



Spare Alloy/ Rim Condition



Grill Condition
Light Scuffing < 50mm



Monogram



Window Glass



Wiper



Panel Condition

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Turbocharger/ Supercharger



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Navigation System



Music System



Sunroof Operation

Sunroof



Lights

Headlight

Left: Light Scuff Marks < 50mm



Interior Lights



Tail Light Cluster



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Parking Sensors



Rear Defogger



Extensive Wear Of Strip

USB Charging Port



Power/ Manual Windows



Interiors & Luggage

Dashboard And Instrument Panel

Dashboard And Instrument Panel: Light
Scuffing/Crack



Central Console

Box: Minor Crack/Fair Use Wear/ Scuffing



Cup Holder



Glove Box



Steering Wheel

Steering Wheel Fair Use Wear



Sunvisor



Seat Upholstery

Driver Seat: Minor Leather/ Fabric Fair Use
Wear/ Tears



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim

Front Left Door: Light Scuffing/ Disfiguration



Grab Handle



Carpet



Headliner

Front Left: Light Smudge/Disfiguration, Light
Scuffing



Rear View Mirror



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<65%

LHS Rear Tyre

<75%

RHS Front Tyre

<65%

RHS Rear Tyre

<75%

Spare Tyre

<65%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE