



RTA Standards

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

1 Months Warranty

Enjoy peace of mind for your car purchase

Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.





2015 HYUNDAI SANTA FE

GLS | 166,842 KM

VIN: KMHST81C8FU379494

Car highlights



Panoramic Roof

This car has a panoramic roof



Cruise control

Cruise control to drive with ease & comfort



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	166842	 Specs	Yes
 Engine	2.4L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Four Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Brown
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	7 Seats	 Number of keys	2 Keys
 VIN number	KMHST81C8FU379494		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Exteriors			
Fog Light Front		Roof Rails	
Rear Bumper Spoiler		Halogen Headlights	
 Comfort & Convenience			
Cruise Control		Rear Armrest with cupholder	
Steering Mounted Audio Controls		Rear Defogger	

Central Armrest



Safety & Security

Parking Sensors Rear



Airbag Driver Front



ABS



Central Locking



Child Safety Locking



Performance

Differential Locks



Entertainment

Bluetooth Player



Infotainment System



USB player



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front left door



Front right door

Panel: Light Scuffing < 50mm, Low Visibility



Dent < 30mm

Rear left door



Rear right door

Panel: Scratch < 50mm, Dent < 30mm

Panel: Low Visual Dent < 30mm, Light



Scuffing < 50mm

Fenders Condition

Left Fender



Right Fender

Condition: Dent < 30mm, Scratch < 50mm



Right Fender: Dent < 30mm, Scratch < 50mm

Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel

Condition: Dent < 30mm, Scratch < 50mm



Condition: Dent < 30mm, Scratch < 50mm

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Light Scuffing < 80mm

Hood Condition

Hood



Bonnet: Paint Chip-off < 5mm

Trunk Condition

Trunk



Door Trim: Light Scuffing < 50mm, Scuff/

Disfiguration < 50mm

Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar		Right A Pillar	
Left A to B Pillar Beading		Right A to B Pillar Beading	
Right A to B Pillar		Left B Pillar	
Left B Pillar Trim		Left B to C Pillar Beading	
Right C Pillar Trim		Right B to C Pillar	
Right B to C Pillar Beading		Left C Pillar	

Running Board Condition

Left Running Board		Right Running Board	
--------------------	--	---------------------	--

Sunroof Glass Condition (If Equipped)

Sun Roof Glass	
----------------	--

Windshield Condition

Front Windshield		Rear Windshield	
------------------	--	-----------------	--

Structural Assessment

Chassis Condition		Radiator Support	
Apron		Boot Floor	
Firewall Condition		Cowl Top	
Head Light Support Condition			

Cowl Top

Cowl Top	
----------	--

Rear View Mirror Condition

Left Hand Side Mirror		Left Side Mirror	
Right Side Mirror			

Alloy Wheel/ Rim

Left Front Alloy/ Rim		Left Rear Alloy/ Rim	
Right Front Alloy/ Rim		Right Rear Alloy/ Rim	

Spare Alloy/ Rim Condition



Wheel cover		Antenna	
Grill Condition		Monogram	
Light Scuffing < 50mm			
Window Glass		Wiper	
Panel Condition			
Rear Trunk Panel			

Engine & Transmission

Engine			
Engine Body		Engine Performance	
Engine Oil (Condition & Level)		Exhaust System	
Radiator Condition		Radiator Coolant	
Battery			
Battery Terminal & Tightness			
Fuel System			
Fuel Cap		Fuel Tank	
Transmission Operation			
Gear Shifting		Drive Axle	
4*4 Condition (If Applicable)		Transmission Fluid	

Steering, Suspension & Brakes

Steering			
Steering wheel			
Brake System			
Brake Master Cylinder		Brake Disc & Brake Pad	
Brake Fluid			
Pedals			
Suspension			
Shock Absorbers			

Electricals, Controls & Lights

Keys

Master Key 

Spare Key(s) 

Door Locks

Child Safety Locking 

Dashboard

Instrument Panel 

Airbags

Airbags 

Controls

Cruise Control 

Infotainment Display 

Engine Sensors 

OBD Connector 

Music System 

Sunroof Operation

Sunroof 

Lights

Headlight



Left: Light Scuff Marks < 50mm

Interior Lights 

Tail Light Cluster 

License Plate Light 

Fog Lights 

Air Conditioning

AC Cooling 

AC Switch 

AC System Leaks 

Center AC Vent 

Front Right AC Vent



Crack/Fair Use Wear

Heater 

Heater Not Working RHS

Rear Blower Switch 

Rear Defogger 

Extensive Wear Of Strip

USB Charging Port 

Power/ Manual Windows 

Interiors & Luggage

Dashboard And Instrument Panel

Dashboard Upholstery: Minor Scuffing/ Crack/ Fair Use Wear 

Central Console

Box: Minor Crack/Fair Use Wear/ Scuffing 

Cup Holder



Glove Box

Glove Box: Minor Scuffing/Crack/Fair Use Wear 

Steering Wheel



Sunvisor



Seat Upholstery

Driver Seat: Minor Cigarette Burn, Minor Fair Wear/Fade off 

Manual Seat Movement



Seat Belts

Rear Center Seat Belt: Fair Use Wear 

Head Rest



Door Controls And Trim

Front Left Door: Light Scuffing 

Grab Handle



Carpet

Front Left Floor Mat: Smudge/Burn/Crack 

Headliner

Rear Left: Smudge/Disfiguration 

Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre 

Left Hand Side Rear Tyre 

Right Hand Side Front Tyre 

Right Hand Side Rear Tyre 

Spare Tyre 

Tyres Depth (Remaining)

LHS Front Tyre <75% LHS Rear Tyre <65% 

RHS Front Tyre <65% RHS Rear Tyre <75% 

Spare Tyre <55% 



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE