



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2016 HYUNDAI TUCSON

GL | 101,216 KM

VIN: KMHJT81E8GU086919

### Car highlights



#### Bluetooth

Enjoy your drive with bluetooth



#### Music System

Enjoy your drive with music system



#### Amazing Comfort

Power driver seat



#### Airbag safety

Airbag Driver Front

## Basic Details

 Kilometers	<b>101216</b>	 Specs	<b>Yes</b>
 Engine	<b>2.0L</b>	 Option Type	<b>Basic</b>
 Transmission	<b>Automatic</b>	 Drive	<b>All Wheel Drive</b>
 Body Type	<b>SUV</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color Grey</b>
 Interior Trim	<b>Fabric Trim</b>	 Number of Airbags	<b>2 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>2 Keys</b>
 VIN number	<b>KMHJT81E8GU086919</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Exteriors</b>			
Fog Light Front		Roof Rails	
Rear Bumper Spoiler		Halogen Headlights	
 <b>Comfort &amp; Convenience</b>			
Rear Armrest with cupholder		Steering Mounted Audio Controls	
Rear Defogger		Central Armrest	



### Performance

Differential Locks



### Entertainment

Bluetooth Player



USB Charging Port



Infotainment System



USB player



### Safety & Security

Airbag Driver Front



ABS



Central Locking



Child Safety Locking



# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## 🚗 Exterior

Doors condition

Front left door



Inner Handle: minor imperfection

Front right door



Handle: Scuffing > 50mm, Paint Chip-off < 5mm

Rear left door



Panel: Dent < 30mm, Paint Chip-off < 5mm, Scratch < 50mm

Rear right door



Inner Handle: minor imperfection

Fenders Condition

Left Fender



Condition: Low Visual Dent < 30mm, Light

Right Fender



Scuffing < 50 mm

Condition: Low Visual Dent < 30mm, Light

Scuffing < 50mm

Quarter Panels Condition

Left Quarter Panel



Condition: Dent < 30mm, Paint Chip-off < 5mm

Right Quarter Panel



Condition: Low Visual Dent < 30mm, Chip<5mm

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Scuffing > 80mm, Dent < 50mm, Chip< 8mm

Hood Condition

Hood



Bonnet: Low Visibility Dent < 30mm, Light Scuffing < 50mm

Trunk Condition

Trunk



Trunk conditon

Trunk



## Roof Condition

### Roof

Roof Moulding Condition: Colour fade



## Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar



Left B Pillar



Left B Pillar Trim



Left B to C Pillar Beading



Right C Pillar Trim



Right B to C Pillar



Right B to C Pillar Beading



Left C Pillar



## Running Board Condition

Left Running Board



Right Running Board



Rear Left Sill Trim: Scratch < 80mm

## Windshield Condition

Front Windshield

Beading: Mouldings Crack/ Fair Use Wear <



Rear Windshield



50mm

## Structural Assessment

Chassis Condition



Radiator Support



Apron



Boot Floor



Firewall Condition



Cowl Top



Head Light Support Condition



Cowl Top



## Rear View Mirror Condition

Left Hand Side Mirror



Left Side Mirror



Body: Paint Faded

Right Side Mirror



Right Hand Side Mirror



Body: Scratch < 50mm

## Alloy Wheel/ Rim

Left Front Alloy/ Rim



Left Rear Alloy/ Rim



Rim: Alloy Face/ Scuff < 50mm

Rim: Alloy Edge/ Scuff < 80mm

Right Front Alloy/ Rim	!	Right Rear Alloy/ Rim	✓
Rim: Alloy Edge/ Scuff < 80mm			
Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Antenna	✓
Grill Condition	!	Monogram	✓
Light Scuffing < 50mm			
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel	!		
Scratch < 50mm			

## Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

## Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓

Pedals 

Suspension

Shock Absorbers 

---

## Electricals, Controls & Lights

Keys

Master Key  Spare Key(s) 

Door Locks

Child Safety Locking 

Dashboard

Instrument Panel 

Airbags

Airbags 

Controls  Infotainment Display   
Infotainment Display: Display Low Brightness

Engine Sensors  OBD Connector 

Music System 

Condition: Button(s) Faded

Lights

Headlight  Interior Lights   
Left: Light Scuff Marks < 50mm

Tail Light Cluster  Turn Signal Lights 

License Plate Light  Fog Lights 

Air Conditioning

AC Cooling  AC Switch 

AC System Leaks  Center AC Vent 

Front Right AC Vent  Heater 

Rear Blower Switch 

USB Charging Port  Power/ Manual Windows 

## **Interiors & Luggage**

### Dashboard And Instrument Panel

Dashboard Upholstery: Minor Scuffing/ Crack/	<span>!</span>	Central Console	
Fair Use Wear			
Cup Holder		Glove Box	
Steering Wheel	<span>!</span>	Sunvisor	
Color Faded			
Seat Upholstery	<span>!</span>	Manual Seat Movement	
Driver Seat: Minor Fair Wear/Fade off			
Seat Belts		Head Rest	
Door Controls And Trim		Grab Handle	
Carpet	<span>!</span>	Headliner	
Front Left Floor Mat: Smudge/Burn/Crack		Front Left: Light Smudge/Disfiguration	<span>!</span>
Rear View Mirror	<span>!</span>	Toolkit	
minor imperfection			

## **Tyres**

### Tyres Condition

Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			

### Tyres Depth (Remaining)

LHS Front Tyre	<75%	LHS Rear Tyre	<85%
RHS Front Tyre	<75%	RHS Rear Tyre	<85%
Spare Tyre	<75%		



**A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE