



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2021 NISSAN X TRAIL

S | 91,482 KM

VIN: JN1BT2MU0MW021770

## Car highlights



### Great condition

Car has low imperfections



### Cruise control

Cruise control to drive with ease & comfort



### Bluetooth

Enjoy your drive with bluetooth



### Amazing Comfort

Power driver seat

## Basic Details

 Kilometers	<b>91482</b>	 Specs	<b>Yes</b>
 Engine	<b>2.5L</b>	 Option Type	<b>Basic</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Front Wheel Drive</b>
 Body Type	<b>SUV</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color White</b>
 Interior Trim	<b>Fabric Trim</b>	 Number of Airbags	<b>2 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>2 Keys</b>
 VIN number	<b>JN1BT2MU0MW021770</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Cruise Control		Rear Armrest with cupholder	
Steering Mounted Audio Controls		Rear Defogger	
Central Armrest		Steering Column Adjuster	
 <b>Safety &amp; Security</b>			
Parking Sensors Rear		Reverse Camera	

Traction Control		Airbag Driver Front	
ABS		Central Locking	
Child Safety Locking			
 <b>Exteriors</b>			
Running Lights		Halogen Headlights	
 <b>Entertainment</b>			
Bluetooth Player		Infotainment System	
USB player			

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## 🚗 Exterior

Doors condition

Front left door



Front right door



Rear left door



Rear right door



Panel: Low Visual Dent < 30mm

Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood



Bonnet: Paint Chip-off < 5mm

Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Antenna	✓
Grill Condition	✓	Monogram	✓
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel	✓		

## Engine & Transmission

### Engine

Engine Body  Engine Performance 

Engine Oil (Condition & Level)  Exhaust System 

Radiator Condition  Radiator Coolant 

### Battery

Battery Terminal & Tightness 

### Fuel System

Fuel Tank 

### Transmission Operation

Gear Shifting  Drive Axle 

Transmission Fluid 

## Steering, Suspension & Brakes

### Steering

Steering wheel 

### Brake System

Parking Brake  Brake Master Cylinder 

Brake Disc & Brake Pad  Brake Fluid 

Pedals 

### Suspension

Shock Absorbers 

## Electricals, Controls & Lights

### Keys

Master Key  Spare Key(s) 

### Door Locks

Child Safety Locking 

### Dashboard

Instrument Panel		
Airbags		
Airbags		
Controls		Cruise Control
Infotainment Display		Engine Sensors
OBD Connector		Navigation System Condition: Available - Google Map Only
Music System		Camera
Lights		
Headlight		Interior Lights
Tail Light Cluster		Daylight Running Lights
License Plate Light		
Air Conditioning		
AC Cooling		AC Switch
AC Temperature: Temp in Idling/Drive < 14°C		
AC System Leaks		Center AC Vent
Front Right AC Vent		Heater
Rear Blower Switch		
Parking Sensors		Rear Defogger
USB Charging Port		Power/ Manual Windows

## **Interiors & Luggage**

Dashboard And Instrument Panel		Central Console
Cup Holder		Glove Box
Steering Wheel		Sunvisor
Seat Upholstery		Manual Seat Movement

Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

## Tyres

### Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	<65%		



**A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE