



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2014 NISSAN PATROL**

**SE T1 | 110,080 KM**

VIN: JN8AY2NY4E9082989

## **Car highlights**



### **Power packed**

Engine size of 5.6 Litres & 8.0 cylinders



### **Cruise control**

Cruise control to drive with ease & comfort



### **Bluetooth**
















Enjoy your drive with bluetooth



### **Amazing Comfort**












Power driver seat





Basic Details

 Kilometers	110080	 Specs	Yes
 Engine	5.6L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Four Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Gold
 Interior Trim	Leather Trim	 Number of Airbags	2 Airbags
 Seating Capacity	8 Seats	 Number of keys	2 Keys
 VIN number	JN8AY2NY4E9082989		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Climate Control AC		Cruise Control	
Rear Armrest with cupholder		Steering Mounted Audio Controls	
Power Folding Mirrors		Power Tailgate/ Power Trunk	
Cool Box		Rear Defogger	
Central Armrest		Remote Engine Start	

Automatic Headlights		✓		
<div> Exteriors</div>				
Fog Light Front		✓	Roof Rails	✓
Running Lights		✓	Rear Bumper Spoiler	✓
Trailer Hook / Coupling		✓	HID Headlights	✓
<div> Safety &amp; Security</div>				
Parking Sensors Front		✓	Parking Sensors Rear	✓
Reverse Camera		✓	Traction Control	✓
Airbag Driver Front		✓	ABS	✓
Central Locking		✓	Child Safety Locking	✓
<div> Performance</div>				
Hill Descent Control		✓	Differential Locks	✓
<div> Entertainment</div>				
Bluetooth Player		✓	Infotainment System	✓
USB player		✓		

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

Front left door  
Frame Extension Cover: Scratch < 50mm



Front right door  
Panel: Light Scuffing < 50mm, Low Visibility  
Dent < 30mm



Rear left door



Rear right door  
Panel: Light Scuffing < 50mm, Paint Chip-off  
< 5mm



### Fenders Condition

Left Fender  
Condition: Light Scuffing < 50 mm



Right Fender



### Quarter Panels Condition

Left Quarter Panel  
Condition: Scratch < 50mm



Right Quarter Panel



### Front Bumper Condition

Front Bumper



### Rear Bumper Condition

Rear Bumper  
Rear Bumper: Light Scuffing < 80mm



### Hood Condition

Hood  
Bonnet: Light Scuffing < 50mm



### Trunk Condition

Trunk  
Door Trim: Light Scuffing < 50mm



### Trunk conditon

Trunk



### Roof Condition

Roof  
Roof Moulding Condition: Mounting Cap  
Unavailable



## Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar



Left B Pillar



Low Visual Dent < 30mm

Condition: Scratch < 50mm

Left B Pillar Trim



Left B to C Pillar Beading



Right C Pillar Trim



Right B to C Pillar



Right B to C Pillar Beading



Left C Pillar



Scratch < 50mm

## Running Board Condition

Left Running Board



Right Running Board



Front Left Floor Trim: Light Scuffing < 80mm

Front Right Floor Trim: Light Scuffing < 80mm

## Sunroof Glass Condition (If Equipped)

Sun Roof Glass



## Windshield Condition

Front Windshield



Rear Windshield



## Structural Assessment

Chassis Condition



Radiator Support



Apron



Boot Floor



Firewall Condition



Cowl Top



Beading: Crack/Fair Use Wear<50mm

Head Light Support Condition



Cowl Top

Cowl Top



## Rear View Mirror Condition

Left Hand Side Mirror



Left Side Mirror



Right Side Mirror



Right Hand Side Mirror



## Alloy Wheel/ Rim

Left Front Alloy/ Rim



Left Rear Alloy/ Rim



Right Front Alloy/ Rim



Right Rear Alloy/ Rim



Rim: Alloy Face Light Scuffing < 50mm

Rim: Alloy Edge/Scuffing<80mm

Spare Alloy/ Rim Condition	✓		
Antenna	✓	Grill Condition Light Scuffing < 50mm	!
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel Scratch < 50mm	!		

## Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Gear shift	✓
Drive Axle	✓	4*4 Condition (If Applicable)	✓
Transmission Fluid	✓		

## Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓

Pedals	✓	
Suspension		
Shock Absorbers	✓	

## Electricals, Controls & Lights

Keys		
Master Key	!	Spare Key(s) ✓
Button Faded		
Door Locks		
Child Safety Locking	✓	
Dashboard		
Instrument Panel	✓	
Airbags		
Airbags	✓	
Controls	✓	Cruise Control ✓
Infotainment Display	✓	Engine Sensors ✓
OBD Connector	✓	Music System Front Left Speakers: minor imperfection !
Sunroof Operation		
Sunroof	✓	
Lights		
Headlight	!	Interior Lights ✓
Left: Light Scuff Marks < 50mm		
Tail Light Cluster	!	Turn Signal Lights ✓
Left Tail Lamp: Light Scuffing < 50mm		
Daylight Running Lights	✓	License Plate Light ✓
Fog Lights	✓	
Air Conditioning		
AC Cooling	✓	AC Switch ✓
AC System Leaks	✓	Center AC Vent ✓



Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓	Rear Left AC Vent	✓
Parking Sensors	✓	Rear Defogger	✓
USB Charging Port	✓	Power/ Manual Windows	✓



## Interiors & Luggage

### Dashboard And Instrument Panel

Dashboard Upholstery: Minor Scuffing/  
Disfiguration/ Melted, Minor Scuffing/ Crack/  
Fair Use Wear, Scuffing/Crack/ Fair Use  
Wear



### Central Console

Condition: minor imperfection



Cup Holder



Glove Box



Steering Wheel

Steering Wheel Fair Use Wear



Sunvisor



Seat Upholstery

Driver Seat: Minor Smudge/ Cracks, Minor  
Leather/ Fabric Fair Use Wear/ Tears



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim

Front Left Door: Light Scuffing



Grab Handle



Carpet

Front Left Floor Mat: Smudge/Burn/Crack



Headliner

Front Left: Light Smudge/Disfiguration



Rear View Mirror

Damaged Mirror Casing



Toolkit



## Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<85%

LHS Rear Tyre

<90%

RHS Front Tyre	<90%	RHS Rear Tyre	<85%
Spare Tyre	<85%		



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE