



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2017 MITSUBISHI MONTERO SPORT

GLS PREMIUM | 42,372 KM

Car highlights



Low Mileage

This car has been driven less than 15,000 km
a year



Adaptive cruise control

Adaptive cruise control to drive with ease &
comfort



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	42372	 Specs	Yes
 Engine	3.0L	 Option Type	Fully Loaded
 Transmission	Automatic	 Drive	Four Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Maroon
 Interior Trim	Leather Trim	 Number of Airbags	7 Airbags
 Seating Capacity	7 Seats	 Number of keys	2 Keys
 VIN number	MMEMC71X6HH002410		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Safety & Security			
Adaptive cruise control		Parking Sensors Front	
Parking Sensors Rear		Reverse Camera	
Blind Spot Monitor		Collision Warning System	
Traction Control		Airbag Curtain Shield	
Airbag Knees		Airbag Driver Front	

ABS		Central Locking	
Child Safety Locking			
Comfort & Convenience			
Climate Control AC		Cruise Control	
Rear Armrest with cupholder		Steering Mounted Audio Controls	
Power Folding Mirrors		Rear Defogger	
Central Armrest		Steering Column Adjuster	
Exteriors			
Fog Light Front		Roof Rails	
Running Lights		Rear Bumper Spoiler	
LED Headlights			
Performance			
Paddle Shift		Hill Descent Control	
Differential Locks		Crawl Function	
Entertainment			
Bluetooth Player		Infotainment System	
USB player			

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front left door



Front right door

Panel: Light Scuffing < 50mm, Low Visibility



Dent < 30mm

Rear left door



Rear right door

Panel: Light Scuffing < 50mm



Fenders Condition

Left Fender



Right Fender

Right Fender: Light Scuffing, Low Visual Dent



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel

Condition: Light Scuffing, Low Visual Dent



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper

Rear Bumper: Replaced, Fully Repainted,



Colour Mismatch/ Low Brightness, Light

Scuffing < 80mm, Dent < 50mm, Chip< 8mm

Hood Condition

Hood

Bonnet: Light Scuffing < 50mm, Paint Chip-off



< 5mm, Acid Marks/ Bird Dropping < 5mm

Trunk Condition

Trunk



Door Trim: Light Scuffing < 50mm

Trunk conditon

Trunk



Roof Condition

Roof			
Pillars Condition			
Left A Pillar		Right A Pillar	
Left A to B Pillar Beading		Right A to B Pillar Beading	
Right A to B Pillar		Left B Pillar	
Left B Pillar Trim		Left B to C Pillar Beading	
Right C Pillar Trim		Right B to C Pillar	
Right B to C Pillar Beading		Left C Pillar	
Running Board Condition			
Left Running Board		Right Running Board	
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass			
Windshield Condition			
Front Windshield		Rear Windshield	
Structural Assessment			
Chassis Condition		Apron	
Boot Floor		Firewall Condition	
Cowl Top		Head Light Support Condition	
Cowl Top			
Cowl Top			
Rear View Mirror Condition			
Left Hand Side Mirror		Left Side Mirror	
Right Side Mirror			
Alloy Wheel/ Rim			
Left Front Alloy/ Rim		Left Rear Alloy/ Rim	
Right Front Alloy/ Rim		Right Rear Alloy/ Rim	
Spare Alloy/ Rim Condition			
Monogram		Window Glass	

Wiper



Panel Condition

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Gear shift



Drive Axle



4*4 Condition (If Applicable)



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



OBD Connector



Radar (If Equipped)



Music System



Sunroof Operation

Sunroof



Lights

Headlight



Left: Light Scuff Marks < 50mm

Interior Lights



Tail Light Cluster



Daylight Running Lights



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch



Rear Left AC Vent



Parking Sensors



Rear Defogger



USB Charging Port



Power/ Manual Windows



Interiors & Luggage

Dashboard And Instrument Panel

Dashboard Upholstery: Minor Scuffing/ Crack/



Central Console



Fair Use Wear

Cup Holder



Glove Box



Steering Wheel



Color Faded

Sunvisor



Seat Upholstery

Driver Seat: Minor Leather/ Fabric Fair Use



Wear/ Tears

Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim



Grab Handle



Carpet



Headliner

Front Left: Light Smudge/Disfiguration



Rear View Mirror



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<85%

LHS Rear Tyre

<85%

RHS Front Tyre

<85%

RHS Rear Tyre

<85%

Spare Tyre

<75%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE