



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2017 MITSUBISHI ASX**

**GLX MID | 112,836 KM**

**VIN: JE4LP21U3HZ704616**

## **Car highlights**

### **Service History**

Service history available



### **Cruise control**

Cruise control to drive with ease & comfort



### **Bluetooth**

Enjoy your drive with bluetooth



### **Amazing Comfort**

Power driver seat

## Basic Details

 Kilometers	<b>112836</b>	 Specs	<b>Yes</b>
 Engine	<b>2.0L</b>	 Option Type	<b>Semi Loaded</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Front Wheel Drive</b>
 Body Type	<b>SUV</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color Black</b>
 Interior Trim	<b>Fabric Trim</b>	 Number of Airbags	<b>2 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>1 Keys</b>
 VIN number	<b>JE4LP21U3HZ704616</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>	
Climate Control AC	
Rear Armrest with cupholder	
Rear Defogger	
 <b>Exteriors</b>	
Fog Light Front	
	
Roof Rails	

Running Lights		Rear Bumper Spoiler	
Halogen Headlights			
<b>Safety &amp; Security</b>			
Parking Sensors Rear		Reverse Camera	
Traction Control		Airbag Driver Front	
ABS		Central Locking	
Child Safety Locking			
<b>Entertainment</b>			
Bluetooth Player		USB Charging Port	
Infotainment System		USB player	

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## 🚗 Exterior

Doors condition

Front left door



Front right door



Rear left door



Panel: Dent < 30mm, Paint Chip-off < 5mm

Rear right door



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Condition: Light Scuffing < 50mm

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Light Scuffing < 80mm, Dent < 50mm

Hood Condition

Hood



Bonnet: Low Visibility Dent < 30mm

Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading		Right A to B Pillar Beading	
Right A to B Pillar		Left B Pillar	
Left B Pillar Trim		Left B to C Pillar Beading	
Right C Pillar Trim		Right B to C Pillar	
Low Visual Dent < 50mm			
Right B to C Pillar Beading		Left C Pillar	
Running Board Condition			
Left Running Board		Right Running Board	
Windshield Condition			
Front Windshield		Rear Windshield	
Structural Assessment			
Chassis Condition		Radiator Support	
Apron		Boot Floor	
Firewall Condition		Cowl Top	
Head Light Support Condition			
Cowl Top			
Cowl Top			
Rear View Mirror Condition			
Left Hand Side Mirror		Left Side Mirror	
Right Side Mirror		Right Hand Side Mirror	
Alloy Wheel/ Rim			
Left Front Alloy/ Rim		Left Rear Alloy/ Rim	
Right Front Alloy/ Rim		Right Rear Alloy/ Rim	
Spare Alloy/ Rim Condition			
Wheel Arch		Wheel cover	
Antenna		Grill Condition	
Light Scuffing < 50mm			
Monogram		Window Glass	

Wiper



Panel Condition

Rear Trunk Panel



Dent < 30mm

## Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Cap



Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



## Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



Front Left Link Rod: minor imperfection

## Electricals, Controls & Lights

Keys

Master Key			
Door Locks			
Child Safety Locking			
Dashboard			
Instrument Panel			
Airbags			
Airbags			
Controls		Cruise Control	
Infotainment Display		Engine Sensors	
OBD Connector		Music System	
Camera			
Lights			
Headlight		Interior Lights	
Tail Light Cluster		Daylight Running Lights	
License Plate Light		Fog Lights	
Air Conditioning			
AC Cooling		AC Switch	
AC System Leaks		Center AC Vent	
Front Right AC Vent		Heater	
Rear Defogger		USB Charging Port	
Power/ Manual Windows			

## **Interiors & Luggage**

Dashboard And Instrument Panel		Central Console Box: minor imperfection	
Cup Holder		Glove Box	

Steering Wheel		Sunvisor	
Seat Upholstery		Manual Seat Movement	
Seat Belts		Head Rest	
Door Controls And Trim			
Rear Left Door: Light Scuffing		Grab Handle	
Carpet			
Front Left Floor Mat: Floor Mat Lock Damage		Headliner	
Rear View Mirror		Toolkit	

## Tyres

### Tyres Condition

Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
minor imperfection			
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			

### Tyres Depth (Remaining)

LHS Front Tyre	<75%	LHS Rear Tyre	<85%
RHS Front Tyre	<75%	RHS Rear Tyre	<85%
Spare Tyre	<75%		



**A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE