



### **Exceeding RTA standards**

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### **3 Months Warranty**

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

#### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



# 2019 RENAULT DUSTER SE | 58,861 KM

VIN: VF1HSRSC6KA524919

## **Car highlights**



### Four wheel drive

This car has a Four wheel drive



### **Cruise control**

Cruise control to drive with ease & comfort



#### **Bluetooth**


Enjoy your drive with bluetooth



## **Amazing Comfort**


Power driver seat

### **Basic Details**



## **Specs and features**

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.



Running Lights	<b>✓</b>	Halogen Headlights	<b>✓</b>
Safety & Security			
Parking Sensors Rear	<b>✓</b>	Traction Control	<b>~</b>
Airbag Driver Front	<b>~</b>	ABS	<b>✓</b>
Central Locking	<b>✓</b>	Child Safety Locking	<b>✓</b>
Performance			
Hill Descent Control	<b>~</b>		
୍ଦ୍ର Entertainment			
Bluetooth Player	<b>✓</b>	Infotainment System	•
USB player			

## **150 Point Detailed Inspection Report**

Roof

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



## Pillars Condition Left A Pillar Right A Pillar Left A to B Pillar Beading Right A to B Pillar Beading Right A to B Pillar Left B Pillar Left B Pillar Trim Left B to C Pillar Beading Right C Pillar Trim Right B to C Pillar Left C Pillar Right B to C Pillar Beading **Running Board Condition** Left Running Board Right Running Board Windshield Condition Rear Windshield Front Windshield Tint Fair Use Wear < 30mm Structural Assessment **Chassis Condition** Radiator Support Apron **Boot Floor** Firewall Condition Cowl Top Head Light Support Condition Cowl Top Cowl Top Rear View Mirror Condition Left Hand Side Mirror Left Side Mirror Body: Paint Chip-off < 5mm Right Side Mirror Right Hand Side Mirror Alloy Wheel/ Rim Left Front Alloy/ Rim Left Rear Alloy/ Rim Right Front Alloy/ Rim Right Rear Alloy/ Rim Rim: Alloy Face/ Scuff < 50mm Spare Alloy/ Rim Condition Wheel Arch Wheel cover

Antenna	<b>✓</b>	Grill Condition  Light Scuffing < 50mm	!
Monogram	<b>✓</b>	Window Glass	<b>✓</b>
Wiper	<b>✓</b>		
Panel Condition			
Rear Trunk Panel	<b>✓</b>		
Engine & Transmission			
Engine			
Engine Body	<b>✓</b>	Engine Performance	<b>✓</b>
Engine Oil (Condition & Level)	<b>✓</b>	Exhaust System	<b>✓</b>
Radiator Condition	<b>✓</b>	Radiator Coolant	<b>✓</b>
Battery			
Battery Terminal & Tightness	<b>✓</b>		
Fuel System			
Fuel Tank	<b>✓</b>		
Transmission Operation			
Gear Shifting	<b>✓</b>	Drive Axle	<b>✓</b>
4*4 Condition (If Applicable)	<b>✓</b>	Transmission Fluid	<b>✓</b>
Steering, Suspension & Brakes			
Steering			
Steering wheel	<b>✓</b>		
Brake System			
Parking Brake	<b>✓</b>	Brake Master Cylinder	<b>✓</b>
Brake Disc & Brake Pad	<b>✓</b>	Brake Fluid	<b>✓</b>
Pedals	<b>✓</b>		
Suspension			
Shock Absorbers	•		

# **Electricals, Controls & Lights** Keys Master Key Door Locks Child Safety Locking Dashboard Instrument Panel Airbags Airbags Controls Cruise Control Infotainment Display **Engine Sensors OBD** Connector Music System Lights Headlight Interior Lights Tail Light Cluster Daylight Running Lights Left Tail Lamp: Light Scuffing < 50mm Right DRL: Low Brightness License Plate Light Fog Lights Air Conditioning AC Switch AC Cooling AC System Leaks Center AC Vent Front Right AC Vent Heater Parking Sensors Rear Defogger **USB Charging Port** Power/ Manual Windows Interiors & Luggage Central Console Dashboard And Instrument Panel Glove Box Cup Holder Glove Box: Minor Scuffing/Crack/Fair Use

#### Wear

Steering Wheel	•	Sunvisor	<b>✓</b>
Seat Upholstery	•	Manual Seat Movement	<b>~</b>
Seat Belts	<b>✓</b>	Head Rest	<b>✓</b>
Door Controls And Trim Front Right Door: Light Scuffing	!	Grab Handle	<b>✓</b>
Carpet	•	Headliner	•
Rear View Mirror	•	Toolkit	<b>✓</b>
Tyres			
Tyres Condition			
	<b>✓</b>	Left Hand Side Rear Tyre	•
Tyres Condition	<ul><li>✓</li><li>✓</li></ul>	Left Hand Side Rear Tyre Right Hand Side Rear Tyre	<ul><li></li><li></li></ul>
Tyres Condition  Left Hand Side Front Tyre	<ul><li></li><li></li><li></li></ul>		<b>✓</b>
Tyres Condition  Left Hand Side Front Tyre  Right Hand Side Front Tyre	<ul><li></li><li></li><li></li></ul>		<ul><li>✓</li><li>✓</li></ul>
Tyres Condition  Left Hand Side Front Tyre  Right Hand Side Front Tyre  Spare Tyre	<75%		<85%
Tyres Condition  Left Hand Side Front Tyre  Right Hand Side Front Tyre  Spare Tyre  Tyres Depth (Remaining)	<75% <75%	Right Hand Side Rear Tyre	<85% <65%



# A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE