



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2018 TOYOTA LAND CRUISER

EXR+ | 95,033 KM

VIN: JTMHY05J4J5026652

## Car highlights



### Power packed

Engine size of 5.7 Litres & 8.0 cylinders



### Cruise control

Cruise control to drive with ease & comfort



### Bluetooth

Enjoy your drive with bluetooth



### Amazing Comfort

Power driver seat

## Basic Details

 Kilometers	<b>95033</b>	 Specs	<b>Yes</b>
 Engine	<b>5.7L</b>	 Option Type	<b>Basic</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Four Wheel Drive</b>
 Body Type	<b>SUV</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color Silver</b>
 Interior Trim	<b>Fabric Trim</b>	 Number of Airbags	<b>12 Airbags</b>
 Seating Capacity	<b>8 Seats</b>	 Number of keys	<b>2 Keys</b>
 VIN number	<b>JTMHY05J4J5026652</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>	
Climate Control AC	
Rear Armrest with cupholder	
Power Folding Mirrors	
Rear Defogger	
Remote Engine Start	
Cruise Control	
Steering Mounted Audio Controls	
Cool Box	
Central Armrest	
Automatic Headlights	



## Exteriors

Fog Light Front	✓	Roof Rails	✓
Running Lights	✓	Trailer Hook / Coupling	✓
LED Headlights	✓		



## Safety & Security

Navigation	✓	Parking Sensors Front	✓
Parking Sensors Rear	✓	Reverse Camera	✓
Traction Control	✓	Airbag Curtain Shield	✓
Airbag Knees	✓	Airbag Driver Front	✓
ABS	✓	Central Locking	✓
Child Safety Locking	✓		



## Performance

Hydraulic Suspensions	✓	Differential Locks	✓
Crawl Function	✓		



## Entertainment

Bluetooth Player	✓	USB Charging Port	✓
Infotainment System	✓	USB player	✓

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## 🚗 Exterior

Doors condition

Front left door

Handle: Scratch < 50mm, Paint Chip-off < 5mm



Front right door

Handle: Paint Chip-off < 5mm



Rear left door



Rear right door

Handle: Paint Chip-off < 5mm



Fenders Condition

Left Fender

Condition: Paint Chip-off < 5mm, Scratch < 50mm



Right Fender



Quarter Panels Condition

Left Quarter Panel

Condition: Scratch < 50mm, Paint Chip-off < 5mm



Right Quarter Panel



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood

Bonnet: Paint Chip-off < 5mm



Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	!	Left B Pillar	!
Light Scuffing < 50mm		Condition: Scratch < 50mm	
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	!	Left Side Mirror	✓
Body: Paint Chip-off < 5mm			
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Wheel cover	✓
Antenna	✓	Grill Condition	!
		Light Scuffing < 50mm	

Monogram



Window Glass



Wiper



Panel Condition

Rear Trunk Panel



## Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



4\*4 Condition (If Applicable)



Transmission Fluid



## Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



## Electricals, Controls & Lights

## Keys

Master Key		Spare Key(s)	
<b>Door Locks</b>			
Child Safety Locking			
<b>Dashboard</b>			
Instrument Panel			
<b>Airbags</b>			
Airbags			
Controls		Cruise Control	
Infotainment Display		Engine Sensors	
OBD Connector		Navigation System	
Music System		Camera	
<b>Lights</b>			
Headlight		Interior Lights	
Tail Light Cluster		Turn Signal Lights	
Daylight Running Lights		License Plate Light	
Fog Lights			
<b>Air Conditioning</b>			
AC Cooling		AC Switch	
AC System Leaks		Center AC Vent	
Front Right AC Vent		Heater	
Rear Blower Switch		Rear Left AC Vent	
Parking Sensors		Rear Defogger	
USB Charging Port		Power/ Manual Windows	



## Interiors & Luggage

## Dashboard And Instrument Panel

Dashboard Upholstery: Minor Scuffing/ Crack/ !

Fair Use Wear

Central Console



Cup Holder



Glove Box



Steering Wheel



Steering Wheel Fair Use Wear

Sunvisor



Seat Upholstery



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim



Grab Handle



Carpet



Front Right Floor Mat: Smudge/Burn/Crack

Headliner



Rear View Mirror



Toolkit



## Tyres

### Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



### Tyres Depth (Remaining)

LHS Front Tyre

<75%

LHS Rear Tyre

<85%

RHS Front Tyre

<75%

RHS Rear Tyre

<85%

Spare Tyre

<75%



**A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE