

RTA Standards

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

1 Months Warranty

Enjoy peace of mind for your car purchase

Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.



2014 HONDA CR V

LX | 157,389 KM

VIN: 5J6RM4830EL700232

Car highlights

Cruise control

Cruise control to drive with ease & comfort

Great Parking Assistance

Parking Sensors Rear

Music System

Enjoy your drive with music system

Amazing Comfort

Power driver seat

Basic Details

Kilometers	157389	Specs	Yes
Engine	2.4L	Option Type	Basic
Transmission	Automatic	Drive	All Wheel Drive
Body Type	SUV	Fuel	Petrol
Wheel Type	Alloy Wheels	Exterior Color	Exterior Color White
Interior Trim	Fabric Trim	Number of Airbags	2 Airbags
Seating Capacity	5 Seats	Number of keys	2 Keys
VIN number	5J6RM4830EL700232		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Comfort & Convenience			
Cruise Control	✓	Rear Armrest with cupholder	✓
Steering Mounted Audio Controls	✓	Rear Defogger	✓
Central Armrest	✓		
Safety & Security			
Parking Sensors Rear	✓	Traction Control	✓

Airbag Driver Front	✓	ABS	✓
Central Locking	✓	Child Safety Locking	✓
Exteriors			
Halogen Headlights	✓		
Entertainment			
Infotainment System	✓	USB player	✓

150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed

Exterior

Doors condition

Front left door
Handle: Paint Chip-off < 5mm

Front right door
Handle: Paint Chip-off < 5mm

Rear left door
Panel: Dent < 30mm, Scratch < 50mm, Paint Chip-off < 5mm

Rear right door
Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm

Fenders Condition

Left Fender
Condition: Light Scuffing < 50 mm, Paint Chip-off < 5mm

Right Fender
Condition: Light Scuffing < 50mm, Low Visual Dent < 30mm, Paint Chip-off < 5mm

Quarter Panels Condition

Left Quarter Panel
Condition: Paint Chip-off < 5mm, Scratch < 50mm

Right Quarter Panel
Condition: Light Scuffing<50mm, Chip<5mm

Front Bumper Condition

Front Bumper

Rear Bumper Condition

Rear Bumper
Rear Bumper: Light Scuffing < 80mm, Crack/ Misaligned

Hood Condition

Hood
Bonnet: Acid Marks/ Bird Dropping < 5mm, Paint Chip-off < 5mm, Low Visibility Dent < 30mm

Trunk Condition

Trunk
Door Trim: Light Scuffing < 50mm

Trunk conditon

Trunk

Roof Condition

Roof
Roof Moulding Condition: Minor Rubber Beading Fair Use Wear

Pillars Condition

Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar Light Scuffing < 50mm	!	Left B Pillar Condition: Scratch < 50mm	!
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓

Running Board Condition

Left Running Board Rear Left Sill Trim: Scratch < 80mm	!	Right Running Board Front Right Sill Trim: Light Scuffing < 80mm	!

Windshield Condition

Front Windshield	✓	Rear Windshield	✓

Structural Assessment

Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top Beading: Crack/Fair Use Wear>50mm	!
Head Light Support Condition	✓		

Cowl Top

Cowl Top	✓

Rear View Mirror Condition

Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror Body: Scratch < 50mm	!	Right Hand Side Mirror	✓

Alloy Wheel/ Rim

Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim Rim: Alloy Edge/ Scuff < 80mm	!

Spare Alloy/ Rim Condition

Wheel Arch

Wheel cover

Antenna

Grill Condition
Light Scuffing < 50mm

Monogram

Window Glass

Wiper

Panel Condition
Rear Trunk Panel
Acid Marks/ Bird Dropping > 5mm

Engine & Transmission

Engine

Engine Body

Engine Performance

Engine Oil (Condition & Level)

Exhaust System

Radiator Condition

Radiator Coolant

Battery

Battery Terminal & Tightness

Fuel System

Fuel Cap

Fuel Tank

Transmission Operation

Gear Shifting

Drive Axle

4*4 Condition (If Applicable)

Transmission Fluid

Steering, Suspension & Brakes

Steering

Steering wheel

Brake System

Brake Master Cylinder

Brake Disc & Brake Pad

Brake Fluid

Pedals

Suspension

Shock Absorbers

Electricals, Controls & Lights

Keys

Master Key

Spare Key(s)
Buttons Faded

Door Locks

Child Safety Locking

Dashboard

Instrument Panel

Airbags

Airbags

Controls

Cruise Control
Cruise Control Switch: Buttons Faded

Infotainment Display

Engine Sensors

OBD Connector

Music System
Steering Mounted Audio Controls: Button(s) Faded

Lights

Headlight
Left: Light Scuff Marks < 50mm

Interior Lights

Tail Light Cluster
Hazard Lights: minor imperfection

Turn Signal Lights

License Plate Light

Air Conditioning

AC Cooling

AC Switch

AC System Leaks

Center AC Vent

Front Right AC Vent

Heater

Rear Blower Switch

Parking Sensors Rear Sensors: minor imperfection	!	Rear Defogger Extensive Wear Of Strip	!
USB Charging Port	✓	Power/ Manual Windows	✓

Interiors & Luggage

Dashboard And Instrument Panel Dashboard And Instrument Panel: Color Faded	!	Central Console Box: Minor Disfiguration	!
Cup Holder	✓	Glove Box	✓
Steering Wheel Steering Wheel Fair Use Wear	!	Sunvisor	✓
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim Front Right Door: Light Scuffing	!	Grab Handle	✓
Carpet Trunk Floor Carpet: Wear & Tear < 80mm	!	Headliner Front Left: Light Smudge/Disfiguration	!
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		

Tyres Depth (Remaining)

LHS Front Tyre	<85%	LHS Rear Tyre	<55%
RHS Front Tyre	<85%	RHS Rear Tyre	<55%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE