



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2022 CHEVROLET GROOVE

PREMIER | 101,090 KM

VIN: LZWADAGAXNG022242

Car highlights



Great condition

Car has low imperfections



Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Apple play

Enjoy your drive with apple play



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	101090	 Specs	Yes
 Engine	1.5L	 Option Type	Fully Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	Fuel Efficiency	16.4 km/L mileage
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Grey
 Interior Trim	Fabric Trim	 Number of Airbags	4 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	LZWADAGAXNG022242		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Climate Control AC		Cruise Control	
Steering Mounted Audio Controls		Power Folding Mirrors	
Rear Defogger		Central Armrest	
Steering Column Adjuster			
 Safety & Security			

Parking Sensors Rear	✓	Reverse Camera	✓
Traction Control	✓	Airbag Driver Front	✓
ABS	✓	Central Locking	✓
Child Safety Locking	✓		
 Exteriors			
Roof Rails	✓	Running Lights	✓
Rear Bumper Spoiler	✓	LED Headlights	✓
 Entertainment			
Bluetooth Player	✓	Apple Play	✓
Android Auto Play	✓	USB Charging Port	✓
Infotainment System	✓	USB player	✓

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

 Exterior

Doors condition

Front left door

Front right door

Rear left door

Rear right door

Fenders Condition

Left Fender

Right Fender

Quarter Panels Condition

Left Quarter Panel

Right Quarter Panel

Front Bumper Condition

Front Bumper

Rear Bumper Condition

Rear Bumper

Hood Condition

Hood

Trunk Condition

Trunk

Trunk conditon

Trunk

Roof Condition

Roof

Pillars Condition

Left A Pillar

Right A Pillar

Left A to B Pillar Beading

Right A to B Pillar Beading

Right A to B Pillar

Left B Pillar

Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Antenna	✓	Grill Condition	✓
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel	✓		



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls	✓	Cruise Control	✓
Infotainment Display	✓	OBD Connector	✓
Music System	✓		
Sunroof Operation			
Sunroof	✓		
Camera	✓		
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Daylight Running Lights	✓
License Plate Light	✓		
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Defogger	✓	USB Charging Port	✓
Power/ Manual Windows	✓		



Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Glove Box	✓	Steering Wheel	✓
Sunvisor	✓	Seat Upholstery	✓
Manual Seat Movement	✓	Seat Belts	✓
Head Rest	✓	Door Controls And Trim	✓
Grab Handle	✓	Carpet	✓

Headliner	✓	Rear View Mirror	✓
Toolkit	✓		

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Life remaining			
LHS Front Tyre	<65%	LHS Rear Tyre	<65%
RHS Front Tyre	<55%	RHS Rear Tyre	<90%
Spare Tyre	<75%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE