



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2014 FORD EDGE

SEL | 118,593 KM

VIN: 2FMDK4JC5EBB78225

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Reverse Camera, Parking Sensors Rear



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort











Power driver seat

Basic Details

 Kilometers	118593	 Specs	Yes
 Engine	3.5L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	All Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Red
 Interior Trim	Partial Leather Trim	 Number of Airbags	6 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	2FMDK4JC5EBB78225		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience				
Climate Control AC			Cruise Control	
Rear Armrest with cupholder			Steering Mounted Audio Controls	
Power Tailgate/ Power Trunk			Rear Defogger	
Central Armrest			Remote Engine Start	
Automatic Headlights				



Safety & Security

Parking Sensors Rear



Reverse Camera



Traction Control



Airbag Curtain Shield



Airbag Driver Front



ABS



Central Locking



Child Safety Locking



Exteriors

Roof Rails



Rear Bumper Spoiler



Trailer Hook / Coupling



Halogen Headlights



Entertainment

Bluetooth Player



Infotainment System



USB player







150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door		Front right door	
		Handle: Light Scuffing < 50mm	
Rear left door		Rear right door	
Handle: Scratch < 50mm		Handle: Scratch < 50mm	

Fenders Condition

Left Fender		Right Fender	
Condition: Paint Chip-off < 5mm		Condition: Low Visual Dent < 30mm, Paint Chip-off < 5mm	


Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
Condition: Scratch < 50mm, Paint Chip-off < 5mm			

Front Bumper Condition

Front Bumper	
--------------	---

Rear Bumper Condition

Rear Bumper	
Rear Bumper: Light Scuffing < 80mm, Chip< 8mm	

Hood Condition

Hood	
Bonnet: Light Scuffing < 50mm, Paint Chip-off < 5mm	

Trunk Condition

Trunk	
Door Trim: Light Scuffing < 50mm	

Trunk conditon

Trunk	
-------	---

Roof Condition

Roof	✓		
Pillars Condition			
Left A Pillar	!	Right A Pillar	✓
Inner Condition: Fair Use Wear			
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	!
		Scratch < 50mm	
Running Board Condition			
Left Running Board	✓	Right Running Board	!
		Front Right Sill Trim: Light Scuffing < 80mm	
Windshield Condition			
Front Windshield			
Condition: Driver Side/Stone Chip	!	Rear Windshield	✓
Mark<5mm, Passenger Side/Stone Chip			
Mark<8mm			
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	!
		Beading: Crack/Fair Use Wear<50mm	
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim		Left Rear Alloy/ Rim	
Rim: Alloy Face/ Scuff < 50mm, Alloy Edge/	!	Rim: Alloy Face/ Scuff < 50mm, Alloy Edge/	!
Scuff < 80mm		Scuff < 80mm	

Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim Rim: Alloy Face/ Scuff < 50mm, Alloy Edge/ Scuff < 80mm	ⓘ
Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Wheel cover	✓
Antenna	✓	Grill Condition Light Scuffing < 50mm	ⓘ
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel	✓		

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant Hoses: minor imperfection	ⓘ
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
4*4 Condition (If Applicable)	✓	Transmission Fluid	✓

Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓

Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			
Shock Absorbers	✓		

Electricals, Controls & Lights

Keys			
Master Key	✓		
Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	Engine Sensors	✓
OBD Connector	✓	Music System	✓
Camera	✓		
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	License Plate Light	✓
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent Crack/Fair Use Wear	!
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓		
Rear Defogger	!	USB Charging Port	✓

Extensive Wear Of Strip

Power/ Manual Windows



Seat Heaters



Interiors & Luggage

Dashboard And Instrument Panel



Central Console

Cigarette Lighter: Cigarette Lighter Missing



Cup Holder



Glove Box

Glove Box: Glove Box Retainer Faulty



Steering Wheel

Steering Wheel Fair Use Wear



Sunvisor



Seat Upholstery



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim



Grab Handle



Carpet

Front Left Floor Mat: Floor Mat Lock Damage, Smudge/Burn/Crack



Headliner



Rear View Mirror



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<85%

LHS Rear Tyre

<85%

RHS Front Tyre

<85%

RHS Rear Tyre

<85%

Spare Tyre

<45%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE