



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2016 HYUNDAI VELOSTER

GLS | 129,175 KM

VIN: KMHTC61C5GU247402

## Car highlights



### 2 door style

Stylish car design having 2 doors



### Cruise control

Cruise control to drive with ease & comfort



### Bluetooth

Enjoy your drive with bluetooth



### Amazing Comfort

Power driver seat

## Basic Details

 Kilometers	<b>129175</b>	 Specs	<b>Yes</b>
 Engine	<b>1.6L</b>	 Option Type	<b>Semi Loaded</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Front Wheel Drive</b>
 Body Type	<b>HATCHBACK</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color Orange</b>
 Interior Trim	<b>Leather Trim</b>	 Number of Airbags	<b>2 Airbags</b>
 Seating Capacity	<b>4 Seats</b>	 Number of keys	<b>2 Keys</b>
 VIN number	<b>KMHTC61C5GU247402</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Exteriors			
Fog Light Front		Rear Bumper Spoiler	
Halogen Headlights			
 Comfort & Convenience			
Cruise Control		Steering Mounted Audio Controls	
Power Folding Mirrors		Rear Defogger	

Central Armrest



### Safety & Security

Parking Sensors Rear



Airbag Driver Front



ABS



Central Locking



Child Safety Locking



### Entertainment

Bluetooth Player



Infotainment System



USB player



# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## 🚗 Exterior

Doors condition

Front left door



Front right door



Panel: Low Visibility Dent < 30mm, Light

Scuffing < 50mm

Rear right door

Panel: Low Visual Dent < 30mm, Light



Scuffing < 50mm

Fenders Condition

Left Fender



Right Fender



Right Fender: Paint Chip-off < 5mm

Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Condition: Dent < 30mm, Scratch < 50mm

Condition: Scratch < 50mm, Dent < 30mm

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood



Trunk Condition

Trunk



Door Trim: Light Scuffing < 50mm

Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Right C Pillar Trim	✓
Right B to C Pillar	✓	Right B to C Pillar Beading	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield			
Condition: Driver Side/Stone Chip			
Mark<5mm, Passenger Side/Stone Chip	!	Rear Windshield	✓
Mark<8mm			
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror			
Body: Paint Chip-off < 5mm	!	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim		Left Rear Alloy/ Rim	
Rim: Alloy Face/ Scuff > 50mm, Alloy Edge/	!	Rim: Alloy Face/ Scuff > 50mm, Alloy Edge/	!
Scuff > 80mm		Scuff > 80mm	
Right Front Alloy/ Rim		Right Rear Alloy/ Rim	
Rim: Alloy Edge/ Scuff > 80mm, Alloy Face/	!	Rim: Alloy Face/ Scuff > 50mm, Alloy Edge/	!
Scuff > 50mm		Scuff > 80mm	
Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Wheel cover	✓

Antenna		Grill Condition Light Scuffing < 50mm	
Monogram		Window Glass	
Wiper			
Panel Condition			
Rear Trunk Panel			
Scratch < 50mm			

## Engine & Transmission

Engine			
Engine Body		Engine Performance	
Engine Oil (Condition & Level)		Exhaust System	
Radiator Condition		Radiator Coolant	
Battery			
Battery Terminal & Tightness			
Fuel System			
Fuel Cap		Fuel Tank	
Transmission Operation			
Gear Shifting		Drive Axle	
Transmission Fluid			

## Steering, Suspension & Brakes

Steering			
Steering wheel			
Brake System			
Parking Brake		Brake Master Cylinder	
Brake Disc & Brake Pad		Brake Fluid	
Pedals			
Suspension			
Shock Absorbers			

## Electricals, Controls & Lights

### Keys

Master Key		Spare Key(s)	
		Buttons Faded	

### Door Locks

Child Safety Locking	
----------------------	---

### Dashboard

Instrument Panel	
------------------	---

### Airbags

Airbags	
---------	---

Controls		Cruise Control	
----------	---	----------------	---

Infotainment Display		Engine Sensors	
----------------------	---	----------------	---

OBD Connector		Music System	
---------------	---	--------------	---

### Lights

Headlight		Interior Lights	
Left: Light Scuff Marks < 50mm			

Tail Light Cluster		Turn Signal Lights	
Rear Windscreen Brake Lamp: Light Scuffing < 30mm			

License Plate Light		Fog Lights	
---------------------	---	------------	---

Air Conditioning		AC Switch	
------------------	--	-----------	---

AC System Leaks		Center AC Vent	
-----------------	---	----------------	---

Front Right AC Vent		Heater	
---------------------	---	--------	---

Parking Sensors		Rear Defogger	
		Extensive Wear Of Strip	

USB Charging Port		Power/ Manual Windows	
-------------------	---	-----------------------	---

## Interiors & Luggage

Dashboard And Instrument Panel		Central Console	
--------------------------------	---	-----------------	---

Dashboard And Instrument Panel: Dullness,  
Light Scuffing/Crack

Gear Shift Knob: Knob Fair Use Wear

Cup Holder



Steering Wheel

Steering Wheel Fair Use Wear



Seat Upholstery

Driver Seat: Minor Fair Wear/Fade off



Seat Belts



Door Controls And Trim



Carpet



Rear View Mirror



Glove Box

Glove Box: Minor Scuffing/Crack/Fair Use Wear



Sunvisor

Left: Sunvisor LHS Minor Crack/Fair Use Wear, Sunvisor RHS Minor Crack/Damage



Manual Seat Movement



Head Rest



Grab Handle



Headliner



Toolkit



## Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<75%

LHS Rear Tyre

<55%

RHS Front Tyre

<75%

RHS Rear Tyre

<45%

Spare Tyre

<55%



**A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE