



### RTA Standards

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

### 1 Months Warranty

Enjoy peace of mind for your car purchase

### Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.





**2014 HYUNDAI TUCSON**

**GL | 153,366 KM**

VIN: KMHJT81B4EU758106

## **Car highlights**



### **Four wheel drive**

This car has a Four wheel drive



### **Great Parking Assistance**

Reverse Camera



### **Bluetooth**
















Enjoy your drive with bluetooth



### **Amazing Comfort**











Power driver seat




Basic Details

|  |                   |   |                    |
|--|-------------------|---|--------------------|
|  Kilometers       | 153366            |  Specs             | Yes                |
|  Engine           | 2.0L              |  Option Type       | Basic              |
|  Transmission     | Automatic         |  Drive             | Four Wheel Drive   |
|  Body Type        | SUV               |  Fuel              | Petrol             |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color Red |
|  Interior Trim    | Fabric Trim       |  Number of Airbags | 1 Airbags          |
|  Seating Capacity | 5 Seats           |  Number of keys    | 1 Keys             |
|  VIN number     | KMHJT81B4EU758106 |   |                    |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|  |  |  |                    |  |  |
|--|--|--|--------------------|--|--|
| <div> Exteriors</div>             |  |  |                    |  |  |
| Fog Light Front  |  | <div></div> | Roof Rails         |  | <div></div> |
| Rear Bumper Spoiler  |  | <div></div> | Halogen Headlights |  | <div></div> |
| <div> Safety &amp; Security</div> |  |  |                    |  |  |
| Navigation   |  | <div></div> | Reverse Camera     |  | <div></div> |
| Airbag Driver Front  |  | <div></div> | ABS                |  | <div></div> |

|  |   |                                 |   |
|--|---|---------------------------------|---|
| Central Locking  | ✓ | Child Safety Locking            | ✓ |
|  <b>Comfort &amp; Convenience</b> |   |                                 |   |
| Rear Armrest with cupholder  | ✓ | Steering Mounted Audio Controls | ✓ |
| Rear Defogger  | ✓ | Central Armrest                 | ✓ |
| Automatic Headlights   | ✓ | Steering Column Adjuster        | ✓ |
|  <b>Performance</b>               |   |                                 |   |
| Differential Locks   | ✓ |                                 |   |
|  <b>Entertainment</b>             |   |                                 |   |
| Bluetooth Player   | ✓ | Infotainment System             | ✓ |
| USB player   | ✓ |                                 |   |





# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality


Passed 

## Exterior

### Doors condition

|                 |   |   |   |
|-----------------|---|---|---|
| Front left door |  | Front right door<br>Handle: Paint Chip-off < 5mm  |  |
| Rear left door  |  | Rear right door<br>Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm |  |

### Fenders Condition

|   |   |  |   |
|---|---|--|---|
| Left Fender<br>Condition: Dent < 30mm, Scratch < 50mm, Paint Chip-off < 5mm |  | Right Fender<br>Right Fender: Scratch < 50mm, Paint Chip-off < 5mm |  |
|---|---|--|---|


### Quarter Panels Condition

|   |   |   |   |
|---|---|---|---|
| Left Quarter Panel<br>Trim: Light Scuffing<80mm |  | Right Quarter Panel<br>Condition: Dent < 30mm, Scratch < 50mm, Paint Chip-off < 5mm |  |
|---|---|---|---|

### Front Bumper Condition

|              |   |
|--------------|---|
| Front Bumper |  |
|--------------|---|


### Rear Bumper Condition

|   |   |
|---|---|
| Rear Bumper<br>Rear Bumper: Light Scuffing < 80mm |  |
|---|---|

### Hood Condition

|                                      |   |
|--------------------------------------|---|
| Hood<br>Bonnet: Paint Chip-off < 5mm |  |
|--------------------------------------|---|

### Trunk Condition

|   |   |
|---|---|
| Trunk<br>Door Trim: Scuff/ Disfiguration< 50mm, Light Scuffing < 50mm |  |
|---|---|

### Trunk conditon

|       |   |
|-------|---|
| Trunk |  |
|-------|---|

### Roof Condition

|                                     |   |   |   |
|-------------------------------------|---|---|---|
| Roof                                | ✓ |   |   |
| Pillars Condition                   |   |   |   |
| Left A Pillar                       | ! | Right A Pillar                              | ✓ |
| Inner Condition: Fair Use Wear      |   |   |   |
| Left A to B Pillar Beading          | ✓ | Right A to B Pillar Beading                 | ✓ |
| Right A to B Pillar                 | ✓ | Left B Pillar                               | ✓ |
| Left B Pillar Trim                  | ✓ | Left B to C Pillar Beading                  | ✓ |
| Right C Pillar Trim                 | ✓ | Right B to C Pillar                         | ✓ |
| Right B to C Pillar Beading         | ✓ | Left C Pillar                               | ✓ |
| Running Board Condition             |   |   |   |
| Left Running Board                  | ✓ | Right Running Board                         | ! |
|                                     |   | Rear Right Sill Trim: Light Scuffing < 80mm |   |
| Windshield Condition                |   |   |   |
| Front Windshield                    |   |   |   |
| Condition: Driver Side/Stone Chip   | ! | Rear Windshield                             | ✓ |
| Mark<5mm, Passenger Side/Stone Chip |   |   |   |
| Mark<8mm                            |   |   |   |
| Structural Assessment               |   |   |   |
| Chassis Condition                   | ✓ | Radiator Support                            | ✓ |
| Apron                               | ✓ | Boot Floor                                  | ✓ |
| Firewall Condition                  | ✓ | Cowl Top                                    | ✓ |
| Head Light Support Condition        | ✓ |   |   |
| Cowl Top                            |   |   |   |
| Cowl Top                            | ✓ |   |   |
| Rear View Mirror Condition          |   |   |   |
| Left Hand Side Mirror               | ✓ | Left Side Mirror                            | ✓ |
| Right Side Mirror                   | ✓ |   |   |
| Alloy Wheel/ Rim                    |   |   |   |
| Left Front Alloy/ Rim               | ✓ | Left Rear Alloy/ Rim                        | ✓ |
| Right Front Alloy/ Rim              | ✓ | Right Rear Alloy/ Rim                       | ✓ |
| Spare Alloy/ Rim Condition          | ✓ |   |   |

|                  |   |                                    |   |
|------------------|---|------------------------------------|---|
| Wheel Arch       | ✓ | Wheel cover                        | ✓ |
| Antenna          | ✓ | Grill Condition<br>Scuffing > 50mm | ! |
| Monogram         | ✓ | Window Glass                       | ✓ |
| Wiper            | ✓ |                                    |   |
| Panel Condition  |   |                                    |   |
| Rear Trunk Panel | ✓ |                                    |   |

## Engine & Transmission

|                                |   |                    |   |
|--------------------------------|---|--------------------|---|
| Engine                         |   |                    |   |
| Engine Body                    | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System     | ✓ |
| Radiator Condition             | ✓ | Radiator Coolant   | ✓ |
| Battery                        |   |                    |   |
| Battery Terminal & Tightness   | ✓ |                    |   |
| Fuel System                    |   |                    |   |
| Fuel Tank                      | ✓ |                    |   |
| Transmission Operation         |   |                    |   |
| Gear Shifting                  | ✓ | Drive Axle         | ✓ |
| 4*4 Condition (If Applicable)  | ✓ | Transmission Fluid | ✓ |

## Steering, Suspension & Brakes

|                        |   |                       |   |
|------------------------|---|-----------------------|---|
| Steering               |   |                       |   |
| Steering wheel         | ✓ |                       |   |
| Brake System           |   |                       |   |
| Parking Brake          | ✓ | Brake Master Cylinder | ✓ |
| Brake Disc & Brake Pad | ✓ | Brake Fluid           | ✓ |
| Pedals                 | ✓ |                       |   |
| Suspension             |   |                       |   |

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Infotainment Display



Engine Sensors



OBD Connector



Music System



Camera



Lights

Headlight



Interior Lights



Tail Light Cluster

Right Tail Lamp: Crack / Fair Use Wear > 5mm



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater  
Heater Not Working RHS



Rear Defogger



USB Charging Port



Power/ Manual Windows



## Interiors & Luggage



Dashboard And Instrument Panel  
Dashboard Trim: Light Scuffing/Disfiguration



Central Console

Box: Minor Color Low Brightness, Minor  
Crack/Fair Use Wear/ Scuffing



Cup Holder



Glove Box



Steering Wheel

Steering Wheel Fair Use Wear



Sunvisor



Seat Upholstery

Driver Seat: Minor Smudge/ Cracks, Minor  
Leather/ Fabric Fair Use Wear/ Tears



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim

Rear Left Door: Light Scuffing,  
Scuffing/Disfiguration



Grab Handle

Rear Left: Crack/Fair Use Wear, Light  
Scuffing



Carpet

Front Left Floor Mat: Smudge/Burn/Crack



Headliner

Rear Left: Light Scuffing,  
Smudge/Disfiguration



Rear View Mirror



Toolkit



## Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<55%

LHS Rear Tyre

<55%

RHS Front Tyre

<55%

RHS Rear Tyre

<55%

Spare Tyre

<55%



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE