



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2017 TOYOTA YARIS

SE / E | 91,228 KM

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Parking Sensors Rear



Amazing Comfort

Power driver seat



Airbag safety

Airbag Driver Front

Basic Details

 Kilometers	91228	 Specs	Yes
 Engine	1.5L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Steel Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	MHFB29F31H2020884		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience	
Cruise Control	
 Safety & Security	
Parking Sensors Rear	
Airbag Driver Front	
Central Locking	
Traction Control	
ABS	
Child Safety Locking	



Exteriors

Halogen Headlights



Entertainment

USB player



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front left door



Handle: Scratch < 50mm

Front right door



Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm

Rear left door



Handle: Scratch < 50mm

Rear right door



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel

Right Quarter Panel

Condition: Scratch < 50mm, Paint Chip-off <



5mm

Condition: Scratch < 50mm, Paint Chip-off <



5mm

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood



Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading		Right A to B Pillar Beading	
Right A to B Pillar		Left B Pillar	
Left B Pillar Trim		Left B to C Pillar Beading	
Right C Pillar Trim		Right B to C Pillar	
Right B to C Pillar Beading		Left C Pillar	
		Scratch < 50mm	
Running Board Condition			
Left Running Board		Right Running Board	
Windshield Condition			
Front Windshield		Rear Windshield	
Structural Assessment			
Chassis Condition		Radiator Support	
Apron		Boot Floor	
Firewall Condition		Cowl Top	
Head Light Support Condition			
Cowl Top			
Cowl Top			
Rear View Mirror Condition			
Left Hand Side Mirror		Left Side Mirror	
Right Side Mirror		Right Hand Side Mirror	
Alloy Wheel/ Rim			
Spare Alloy/ Rim Condition			
Wheel Arch		Wheel cover	
Antenna		Grill Condition	
Monogram		Window Glass	
		Front Right: Light Scuffing < 50mm	
Wiper			
Panel Condition			

Rear Trunk Panel



Dent < 30mm

Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Cap



Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Music System



Lights

Headlight

Right: Light Scuff Marks < 50mm



Interior Lights



Tail Light Cluster



License Plate Light



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Parking Sensors



Rear Defogger



Extensive Wear Of Strip

USB Charging Port



Power/ Manual Windows



Interiors & Luggage

Dashboard And Instrument Panel



Central Console



Glove Box



Steering Wheel



Steering Wheel Fair Use Wear

Sunvisor



Seat Upholstery



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim



Rear Left Door: Light Scuffing

Grab Handle



Carpet



Front Left Floor Mat: Smudge/Burn/Crack

Headliner



Rear Left: Smudge/Disfiguration

Rear View Mirror



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<55%

LHS Rear Tyre

<75%

RHS Front Tyre

<55%

RHS Rear Tyre

<55%

Spare Tyre

No spare

tyre



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE