



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2015 NISSAN SENTRA**

**SL | 79,910 KM**

## **Car highlights**



### **Great Parking Assistance**

Parking Sensors Rear



### **Bluetooth**

Enjoy your drive with bluetooth



### **Music System**
















Enjoy your drive with music system



### **Amazing Comfort**










Power driver seat

Basic Details

|  |                   |   |                     |
|--|-------------------|---|---------------------|
|  Kilometers       | 79910             |  Specs             | Yes                 |
|  Engine           | 1.8L              |  Option Type       | Fully Loaded        |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive   |
|  Body Type        | SEDAN             |  Fuel              | Petrol              |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color Grey |
|  Interior Trim    | Fabric Trim       |  Number of Airbags | 2 Airbags           |
|  Seating Capacity | 5 Seats           |  Number of keys    | 2 Keys              |
|  VIN number     | MNTAB7A94F6006046 |   |                     |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|  |  |  |                                 |  |
|--|--|--|---------------------------------|--|
| <div> Exteriors</div>                 |  |  |                                 |  |
| Fog Light Front  |  | <div></div> | Rear Bumper Spoiler             | <div></div> |
| Halogen Headlights   |  | <div></div> |                                 |  |
| <div> Comfort &amp; Convenience</div> |  |  |                                 |  |
| Rear Armrest with cupholder  |  | <div></div> | Steering Mounted Audio Controls | <div></div> |
| Power Folding Mirrors  |  | <div></div> | Rear Defogger                   | <div></div> |

|  |   |                          |   |
|--|---|--------------------------|---|
| Central Armrest  | ✓ | Steering Column Adjuster | ✓ |
|  <b>Safety &amp; Security</b> |   |                          |   |
| Parking Sensors Rear   | ✓ | Airbag Driver Front      | ✓ |
| ABS  | ✓ | Central Locking          | ✓ |
| Child Safety Locking   | ✓ |                          |   |
|  <b>Entertainment</b>         |   |                          |   |
| Bluetooth Player   | ✓ | Infotainment System      | ✓ |
| USB player   | ✓ |                          |   |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition



|                 |   |  |   |
|-----------------|---|--|---|
| Front left door |  | Front right door                             |  |
|                 |   | Panel: Light Scuffing < 50mm, Low Visibility |   |
|                 |   | Dent < 30mm, Paint Chip-off < 5mm            |   |

|                |   |                                       |   |
|----------------|---|---------------------------------------|---|
| Rear left door |  | Rear right door                       |  |
|                |   | Panel: Low Visual Dent < 30mm, Light  |   |
|                |   | Scuffing < 50mm, Paint Chip-off < 5mm |   |

### Fenders Condition

|  |   |                              |   |
|--|---|------------------------------|---|
| Left Fender                            |  | Right Fender                 |  |
| Condition: Dent < 30mm, Scratch < 50mm |   | Right Fender: Scratch < 50mm |   |

### Quarter Panels Condition

|                    |   |   |   |
|--------------------|---|---|---|
| Left Quarter Panel |  | Right Quarter Panel                     |  |
|                    |   | Condition: Dent < 30mm, Scratch < 50mm, |   |
|                    |   | Acid Marks/ Bird Dropping < 5mm         |   |

### Front Bumper Condition

|              |   |
|--------------|---|
| Front Bumper |  |
|--------------|---|

### Rear Bumper Condition

|  |   |
|--|---|
| Rear Bumper  |  |
| Rear Bumper: Dent < 50mm, Light Scuffing < 80mm, Chip< 8mm |   |

### Hood Condition

|  |   |
|--|---|
| Hood   |  |
| Bonnet: Low Visibility Dent < 30mm, Acid Marks/ Bird Dropping < 5mm, Light Scuffing < 50mm |   |

### Trunk Condition

|       |   |
|-------|---|
| Trunk |  |
|-------|---|

### Trunk conditon

|       |   |
|-------|---|
| Trunk |  |
|-------|---|

## Roof Condition

Roof



## Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar



Left B Pillar



Left B Pillar Trim



Crack/Fair Use Wear

Left B to C Pillar Beading



Right C Pillar Trim



Right B to C Pillar

Low Visual Dent < 50mm



Right B to C Pillar Beading



Left C Pillar



## Running Board Condition

Left Running Board



Right Running Board

Condition: Light Scuffing < 80mm



## Windshield Condition

Front Windshield

Condition: Passenger Side/Light  
Scuffing<50mm



Rear Windshield



## Structural Assessment

Chassis Condition



Radiator Support



Apron



Boot Floor



Firewall Condition



Cowl Top



Head Light Support Condition



Cowl Top

Cowl Top



## Rear View Mirror Condition

Left Hand Side Mirror



Left Side Mirror



Right Side Mirror



## Alloy Wheel/ Rim

Left Front Alloy/ Rim

Rim: Alloy Edge/ Scuff < 80mm



Left Rear Alloy/ Rim

Rim: Alloy Edge/ Scuff < 80mm



Right Front Alloy/ Rim



Right Rear Alloy/ Rim

Rim: Alloy Edge/ Scuff < 80mm



|                            |   |  |   |
|----------------------------|---|--|---|
| Spare Alloy/ Rim Condition | ✓ |  |   |
| Wheel Arch                 | ✓ | Wheel cover                              | ✓ |
| Antenna                    | ✓ | Grill Condition<br>Light Scuffing < 50mm | ! |
| Monogram                   | ✓ | Window Glass                             | ✓ |
| Wiper                      | ✓ |  |   |
| Panel Condition            |   |  |   |
| Rear Trunk Panel           | ✓ |  |   |

## Engine & Transmission

|                                |   |                    |   |
|--------------------------------|---|--------------------|---|
| Engine                         |   |                    |   |
| Engine Body                    | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System     | ✓ |
| Radiator Condition             | ✓ | Radiator Coolant   | ✓ |
| Battery                        |   |                    |   |
| Battery Terminal & Tightness   | ✓ |                    |   |
| Fuel System                    |   |                    |   |
| Fuel Tank                      | ✓ |                    |   |
| Transmission Operation         |   |                    |   |
| Gear Shifting                  | ✓ | Drive Axle         | ✓ |
| Transmission Fluid             | ✓ |                    |   |

## Steering, Suspension & Brakes

|                        |   |                       |   |
|------------------------|---|-----------------------|---|
| Steering               |   |                       |   |
| Steering wheel         | ✓ |                       |   |
| Brake System           |   |                       |   |
| Parking Brake          | ✓ | Brake Master Cylinder | ✓ |
| Brake Disc & Brake Pad | ✓ | Brake Fluid           | ✓ |
| Pedals                 | ✓ |                       |   |

Suspension

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Infotainment Display



Engine Sensors



OBD Connector



Music System

Condition: Button(s) Faded



Lights

Headlight

Left: Light Scuff Marks < 50mm



Interior Lights



Tail Light Cluster



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch



Rear Defogger



USB Charging Port



Power/ Manual Windows








## Interiors & Luggage

### Dashboard And Instrument Panel

Dashboard Upholstery: Minor Scuffing/ Crack/ Fair Use Wear 

Central Console



Cup Holder



Glove Box



Steering Wheel


Steering Wheel Fair Use Wear



Sunvisor



### Seat Upholstery

Driver Seat: Minor Leather/ Fabric Fair Use Wear/ Tears, Minor Smudge/ Cracks 

Manual Seat Movement




Seat Belts



Head Rest




### Door Controls And Trim

Front Left Door: Light Scuffing/ Disfiguration, Light Scuffing 


Grab Handle



Carpet

Front Left Floor Mat: Smudge/Burn/Crack 

Headliner

Front Left: Light Smudge/Disfiguration, Light Scuffing 

Rear View Mirror



Toolkit



## Tyres

### Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



### Life remaining

LHS Front Tyre

<75%

LHS Rear Tyre

<75%

RHS Front Tyre

<75%

RHS Rear Tyre

<65%

Spare Tyre

<65%



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE