



#### **Exceeding RTA standards**

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

#### **3 Months Warranty**

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

#### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



# 2020 KIA GRAND CARNIVAL LX | 73,436 KM

VIN: KNAMB8121L6645829

# **Car highlights**



## **Good Tyre Condition**

Tyre age less than 2 years



#### **Cruise control**

Cruise control to drive with ease & comfort



#### **Bluetooth**


Enjoy your drive with bluetooth



### **Amazing Comfort**


Power driver seat

#### **Basic Details**



## **Specs and features**


The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.




Airbag Driver Front	<b>✓</b>	ABS	<b>✓</b>
Central Locking	<b>✓</b>	Child Safety Locking	~
Exteriors			
Roof Rails	•	Rear Bumper Spoiler	•
Halogen Headlights	<b>~</b>		
୍ଦ୍ର Entertainment			
Bluetooth Player	<b>~</b>	USB Charging Port	•
USB player	<b>✓</b>		


### **150 Point Detailed Inspection Report**

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



Left A Pillar	<b>✓</b>	Right A Pillar	<b>✓</b>
Left A to B Pillar Beading	<b>✓</b>	Right A to B Pillar Beading	<b>✓</b>
Right A to B Pillar	<b>✓</b>	Left B Pillar	<b>✓</b>
Left B Pillar Trim Light Scuffing	(!)	Left B to C Pillar Beading	<b>~</b>
Right C Pillar Trim Light Scuffing	(!)	Right B to C Pillar	<b>✓</b>
Right B to C Pillar Beading	<b>✓</b>	Left C Pillar	<b>✓</b>
Running Board Condition  Left Running Board  Condition: Light Scuffing < 80mm  Windshield Condition	•	Right Running Board	<b>✓</b>
Front Windshield	<b>✓</b>	Rear Windshield	~
Structural Assessment			
Chassis Condition	<b>✓</b>	Radiator Support	<b>✓</b>
Apron	•	Boot Floor Condition: Light Scuffing < 80mm	!
Firewall Condition	<b>✓</b>	Cowl Top	<b>✓</b>
Firewall Condition  Head Light Support Condition	<ul><li></li><li></li></ul>	Cowl Top	<b>✓</b>
	<ul><li></li><li></li></ul>	Cowl Top	•
Head Light Support Condition	<ul><li></li><li></li><li></li></ul>	Cowl Top	•
Head Light Support Condition  Cowl Top	<ul><li>*</li><li>*</li></ul>	Cowl Top	•
Head Light Support Condition  Cowl Top  Cowl Top	<ul><li>&gt;</li><li>&gt;</li></ul>	Cowl Top  Left Side Mirror	
Head Light Support Condition  Cowl Top  Cowl Top  Rear View Mirror Condition	<ul><li>&gt;</li><li>&gt;</li><li>&gt;</li></ul>		<ul> <li></li> <li></li> <li></li> </ul>
Head Light Support Condition  Cowl Top  Cowl Top  Rear View Mirror Condition  Left Hand Side Mirror	<ul><li>&gt;</li><li>&gt;</li><li>&gt;</li></ul>	Left Side Mirror	
Head Light Support Condition  Cowl Top  Cowl Top  Rear View Mirror Condition  Left Hand Side Mirror  Right Side Mirror		Left Side Mirror	
Head Light Support Condition  Cowl Top  Cowl Top  Rear View Mirror Condition  Left Hand Side Mirror  Right Side Mirror  Alloy Wheel/ Rim		Left Side Mirror Right Hand Side Mirror	
Head Light Support Condition  Cowl Top  Cowl Top  Rear View Mirror Condition  Left Hand Side Mirror  Right Side Mirror  Alloy Wheel/ Rim  Left Front Alloy/ Rim		Left Side Mirror Right Hand Side Mirror  Left Rear Alloy/ Rim	
Head Light Support Condition  Cowl Top  Cowl Top  Rear View Mirror Condition  Left Hand Side Mirror  Right Side Mirror  Alloy Wheel/ Rim  Left Front Alloy/ Rim  Right Front Alloy/ Rim		Left Side Mirror Right Hand Side Mirror  Left Rear Alloy/ Rim	





Glove Box: Minor Scuffing/Crack/Fair Use

Wear

Steering Wheel	<b>✓</b>	Sunvisor	<b>✓</b>
Seat Upholstery Driver Seat: Minor Smudge/ Cracks	(!)	Manual Seat Movement	•
Seat Belts Rear Center Seat Belt: Smudge	(!)	Head Rest	•
Door Controls And Trim Front Right Door: Light Scuffing	(!)	Grab Handle	<b>✓</b>
Carpet Trunk Floor Carpet: Smudge < 80mm, Fair Use Wear < 80mm	(!)	Headliner Rear Left: Smudge/Disfiguration	(!)
Rear View Mirror	<b>✓</b>	Toolkit	<b>✓</b>
Tyres			
Tyres Condition			
•	<b>✓</b>	Left Hand Side Rear Tyre	<b>✓</b>
Tyres Condition	<b>⋄</b>	Left Hand Side Rear Tyre Right Hand Side Rear Tyre	✓
Tyres Condition  Left Hand Side Front Tyre	<ul><li></li><li></li><li></li></ul>		<b>✓</b>
Tyres Condition  Left Hand Side Front Tyre  Right Hand Side Front Tyre	<ul><li></li><li></li><li></li></ul>		<ul><li>✓</li><li>✓</li></ul>
Tyres Condition  Left Hand Side Front Tyre  Right Hand Side Front Tyre  Spare Tyre	<85%		<85%
Tyres Condition  Left Hand Side Front Tyre  Right Hand Side Front Tyre  Spare Tyre  Tyres Depth (Remaining)	<85% <85%	Right Hand Side Rear Tyre	<85% <85%



# A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE