



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2017 MITSUBISHI PAJERO

GLS LOWLINE | 122,916 KM

VIN: JE4MR62N3HJ709066

Car highlights



Four wheel drive

This car has a Four wheel drive



Cruise control

Cruise control to drive with ease & comfort



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	122916	 Specs	Yes
 Engine	3.5L	 Option Type	Basic
 Transmission	Automatic	 Drive	Four Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Grey
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	7 Seats	 Number of keys	2 Keys
 VIN number	JE4MR62N3HJ709066		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience	
Climate Control AC	
Rear Armrest with cupholder	
Power Folding Mirrors	
Steering Column Adjuster	
 Exteriors	

Fog Light Front		Running Lights	
HID Headlights			
Safety & Security			
Parking Sensors Rear		Reverse Camera	
Traction Control		Airbag Driver Front	
ABS		Central Locking	
Child Safety Locking			
Performance			
Differential Locks			
Entertainment			
Bluetooth Player		Infotainment System	
USB player			

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front left door



Front right door

Moulding: Light Scuffing < 50mm, Paint Chip-off < 5mm



Rear left door



Rear right door

Moulding: Paint Chip-off < 5mm



Fenders Condition

Left Fender

Condition: Scratch < 50mm, Paint Chip-off < 5mm



Right Fender

Right Fender: Dent < 30mm, Scratch < 50mm



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel

Condition: Paint Chip-off < 5mm, Dent < 30mm



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper

Rear Bumper: Chip < 8mm, Light Scuffing < 80mm, Dent < 50mm



Hood Condition

Hood

Bonnet: Light Scuffing < 50mm, Acid Marks/ Bird Dropping < 5mm, Paint Chip-off < 5mm



Trunk Condition

Trunk



Trunk condition

Trunk



Roof Condition

Roof		
Pillars Condition		
Left A Pillar		Right A Pillar
Left A to B Pillar Beading		Right A to B Pillar Beading
Right A to B Pillar		Left B Pillar
Left B Pillar Trim		Left B to C Pillar Beading
Right C Pillar Trim		Right B to C Pillar
Right B to C Pillar Beading		Left C Pillar
Running Board Condition		
Left Running Board		Right Running Board
		Right Foot Board: Light Scuffing < 80mm, Light Scuffing < 80mm
Windshield Condition		
Front Windshield		
Condition: Driver Side/Stone Chip		
Mark<5mm, Passenger Side/Stone Chip		Rear Windshield
Mark<8mm, Passenger Side/Light		
Scuffing<50mm		
Structural Assessment		
Chassis Condition		Radiator Support
		Boot Floor
Apron		Door Skirting: Light Scuffing < 50mm, Paint Chip-off < 5mm
Firewall Condition		Cowl Top
Head Light Support Condition		
Cowl Top		
Cowl Top		
Rear View Mirror Condition		
Left Hand Side Mirror		Left Side Mirror
Right Side Mirror		
Alloy Wheel/ Rim		
Left Front Alloy/ Rim		Left Rear Alloy/ Rim

Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Wheel cover	✓
Antenna	✓	Grill Condition	!
Monogram	!	Light Scuffing < 50mm	
Chrome Low Brightness/ Fair Use Wear		Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel	✓		

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
4*4 Condition (If Applicable)	✓	Transmission Fluid	✓

Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓

Brake Disc & Brake Pad		Brake Fluid	
Pedals			
Suspension			
Shock Absorbers			

Electricals, Controls & Lights

Keys			
Master Key		Spare Key(s)	
Door Locks			
Child Safety Locking			
Dashboard			
Instrument Panel			
Airbags			
Airbags			
Controls		Cruise Control	
Infotainment Display		Engine Sensors	
OBD Connector		Music System	
Camera			
Lights			
Headlight		Interior Lights	
Tail Light Cluster			
Right Tail Lamp: Light Scuffing < 50mm, Crack / Fair Use Wear < 5mm		Daylight Running Lights	
License Plate Light		Fog Lights	
Air Conditioning			
AC Cooling		AC Switch	
AC System Leaks		Center AC Vent	
Front Right AC Vent		Heater	

Rear Blower Switch	✓	Rear Left AC Vent	✓
Rear Defogger	!	USB Charging Port	✓
Not Working			
Power/ Manual Windows	✓		

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	!
		Box: Minor Crack/Fair Use Wear/ Scuffing	
Cup Holder	✓	Glove Box	✓
Steering Wheel	!	Sunvisor	✓
Steering Wheel Fair Use Wear			
Seat Upholstery			
Driver Seat: Minor Leather/ Fabric Fair Use Wear/ Tears	!	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	!	Grab Handle	✓
Front Left Door: Light Scuffing			
Carpet	✓	Headliner	!
		Front Left: Light Smudge/Disfiguration	
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	<85%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE