



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





## 2017 DODGE CHARGER

RALLYE | 144,435 KM

VIN: 2C3CDXHG6HH595461

### Car highlights



#### **Cruise control**

Cruise control to drive with ease & comfort



#### **Great Parking Assistance**

Reverse Camera, Parking Sensors Rear



#### **Bluetooth**

Enjoy your drive with bluetooth



#### **Amazing Comfort**

Power driver seat

Basic Details

|                                                                                                    |                   |                                                                                                     |                      |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|----------------------|
|  Kilometers       | 144435            |  Specs             | Yes                  |
|  Engine           | 3.6L              |  Option Type       | Semi Loaded          |
|  Transmission     | Automatic         |  Drive             | Rear Wheel Drive     |
|  Body Type        | SEDAN             |  Fuel              | Petrol               |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color Black |
|  Interior Trim    | Fabric Trim       |  Number of Airbags | 7 Airbags            |
|  Seating Capacity | 5 Seats           |  Number of keys    | 2 Keys               |
|  VIN number      | 2C3CDXHG6HH595461 |                                                                                                     |                      |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                                      |                                                                                     |                                 |                                                                                       |
|----------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|---------------------------------|---------------------------------------------------------------------------------------|
|  <b>Comfort &amp; Convenience</b> |                                                                                     |                                 |                                                                                       |
| Climate Control AC                                                                                                   |  | Cruise Control                  |  |
| Rear Armrest with cupholder                                                                                          |  | Steering Mounted Audio Controls |  |
| Rear Defogger                                                                                                        |  | Central Armrest                 |  |
| Remote Engine Start                                                                                                  |  | Automatic Headlights            |  |
|  <b>Exteriors</b>                 |                                                                                     |                                 |                                                                                       |

|                                                                                                                |   |                      |   |
|----------------------------------------------------------------------------------------------------------------|---|----------------------|---|
| Fog Light Front                                                                                                | ✓ | Running Lights       | ✓ |
| Rear Bumper Spoiler                                                                                            | ✓ | HID Headlights       | ✓ |
|  <b>Safety &amp; Security</b> |   |                      |   |
| Navigation                                                                                                     | ✓ | Parking Sensors Rear | ✓ |
| Reverse Camera                                                                                                 | ✓ | Traction Control     | ✓ |
| Airbag Curtain Shield                                                                                          | ✓ | Airbag Knees         | ✓ |
| Airbag Driver Front                                                                                            | ✓ | ABS                  | ✓ |
| Central Locking                                                                                                | ✓ | Child Safety Locking | ✓ |
|  <b>Performance</b>           |   |                      |   |
| Paddle Shift                                                                                                   | ✓ |                      |   |
|  <b>Entertainment</b>       |   |                      |   |
| Bluetooth Player                                                                                               | ✓ | Infotainment System  | ✓ |
| USB player                                                                                                     | ✓ |                      |   |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

|                 |                                                                                   |                  |                                                                                     |
|-----------------|-----------------------------------------------------------------------------------|------------------|-------------------------------------------------------------------------------------|
| Front left door |  | Front right door |  |
|-----------------|-----------------------------------------------------------------------------------|------------------|-------------------------------------------------------------------------------------|

|                |                                                                                   |                       |                                                                                     |
|----------------|-----------------------------------------------------------------------------------|-----------------------|-------------------------------------------------------------------------------------|
| Rear left door |  | Rear right door       |  |
|                |                                                                                   | Panel: Original Paint |                                                                                     |

### Fenders Condition

|                                   |                                                                                   |              |                                                                                     |
|-----------------------------------|-----------------------------------------------------------------------------------|--------------|-------------------------------------------------------------------------------------|
| Left Fender                       |  | Right Fender |  |
| Condition: Low Visual Dent < 30mm |                                                                                   |              |                                                                                     |

### Quarter Panels Condition

|                    |                                                                                   |                     |                                                                                     |
|--------------------|-----------------------------------------------------------------------------------|---------------------|-------------------------------------------------------------------------------------|
| Left Quarter Panel |  | Right Quarter Panel |  |
|--------------------|-----------------------------------------------------------------------------------|---------------------|-------------------------------------------------------------------------------------|

### Front Bumper Condition

|              |                                                                                     |
|--------------|-------------------------------------------------------------------------------------|
| Front Bumper |  |
|--------------|-------------------------------------------------------------------------------------|

### Rear Bumper Condition

|             |                                                                                     |
|-------------|-------------------------------------------------------------------------------------|
| Rear Bumper |  |
|-------------|-------------------------------------------------------------------------------------|

### Hood Condition

|                                          |                                                                                     |
|------------------------------------------|-------------------------------------------------------------------------------------|
| Hood                                     |                                                                                     |
| Bonnet: Acid Marks/ Bird Dropping < 5mm, |  |
| Light Scuffing < 50mm                    |                                                                                     |

### Trunk Condition

|       |                                                                                     |
|-------|-------------------------------------------------------------------------------------|
| Trunk |  |
|-------|-------------------------------------------------------------------------------------|

### Trunk conditon

|       |                                                                                     |
|-------|-------------------------------------------------------------------------------------|
| Trunk |  |
|-------|-------------------------------------------------------------------------------------|

### Pillars Condition

|               |                                                                                     |                |                                                                                       |
|---------------|-------------------------------------------------------------------------------------|----------------|---------------------------------------------------------------------------------------|
| Left A Pillar |  | Right A Pillar |  |
|---------------|-------------------------------------------------------------------------------------|----------------|---------------------------------------------------------------------------------------|

|                            |                                                                                     |                             |                                                                                       |
|----------------------------|-------------------------------------------------------------------------------------|-----------------------------|---------------------------------------------------------------------------------------|
| Left A to B Pillar Beading |  | Right A to B Pillar Beading |  |
|----------------------------|-------------------------------------------------------------------------------------|-----------------------------|---------------------------------------------------------------------------------------|

|                     |                                                                                     |               |                                                                                       |
|---------------------|-------------------------------------------------------------------------------------|---------------|---------------------------------------------------------------------------------------|
| Right A to B Pillar |  | Left B Pillar |  |
|---------------------|-------------------------------------------------------------------------------------|---------------|---------------------------------------------------------------------------------------|

|                                               |   |                                   |   |
|-----------------------------------------------|---|-----------------------------------|---|
| Left B Pillar Trim                            | ✓ | Left B to C Pillar Beading        | ✓ |
| Right C Pillar Trim                           | ✓ | Right B to C Pillar               | ✓ |
| Right B to C Pillar Beading                   | ✓ | Left C Pillar                     | ✓ |
| Running Board Condition                       |   |                                   |   |
| Left Running Board                            | ✓ | Right Running Board               | ✓ |
| Windshield Condition                          |   |                                   |   |
| Front Windshield                              |   |                                   |   |
| Condition: Passenger Side/Light Scuffing<50mm | ! | Rear Windshield                   | ✓ |
| Structural Assessment                         |   |                                   |   |
| Chassis Condition                             | ✓ | Radiator Support                  | ✓ |
| Apron                                         | ✓ | Boot Floor                        | ✓ |
| Firewall Condition                            | ✓ | Cowl Top                          | ! |
|                                               |   | Beading: Crack/Fair Use Wear<50mm |   |
| Head Light Support Condition                  | ✓ |                                   |   |
| Cowl Top                                      |   |                                   |   |
| Cowl Top                                      | ✓ |                                   |   |
| Rear View Mirror Condition                    |   |                                   |   |
| Left Hand Side Mirror                         | ✓ | Left Side Mirror                  | ✓ |
| Right Side Mirror                             | ✓ | Right Hand Side Mirror            | ✓ |
| Alloy Wheel/ Rim                              |   |                                   |   |
| Left Front Alloy/ Rim                         | ! | Left Rear Alloy/ Rim              | ! |
| Rim: Alloy Edge Scuffing > 50mm               |   | Rim: Alloy Edge Scuffing > 50mm   |   |
| Right Front Alloy/ Rim                        | ! | Right Rear Alloy/ Rim             | ! |
| Rim: Alloy Edge Scuffing < 80mm               |   | Rim: Alloy Edge/Scuffing<80mm     |   |
| Spare Alloy/ Rim Condition                    | ✓ |                                   |   |
| Wheel cover                                   | ✓ | Antenna                           | ✓ |
| Grill Condition                               | ✓ | Monogram                          | ✓ |
| Window Glass                                  | ✓ | Wiper                             | ✓ |
| Panel Condition                               |   |                                   |   |

Rear Trunk Panel



## Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Cap



Fuel Tank



Transmission Operation

Gear Shifting



Gear shift

Paddle Shift: Not Working / Fair Use Wear



Drive Axle



Transmission Fluid



## Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



## Dashboard

### Instrument Panel

Dash Light Operation: minor imperfection



## Airbags

Airbags



## Controls



Cruise Control



## Infotainment Display



Engine Sensors



## OBD Connector



Navigation System



## Music System



Camera



## Lights

Headlight



Interior Lights



Tail Light Cluster



Daylight Running Lights



License Plate Light



Fog Lights



## Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch



Fair Use Wear

Parking Sensors



Rear Defogger



USB Charging Port



Power/ Manual Windows



Seat Heaters



## Interiors & Luggage

Dashboard And Instrument Panel



Central Console



Cup Holder



Glove Box



Steering Wheel



Sunvisor



Color Faded

Seat Upholstery



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim



Grab Handle



Carpet



Headliner



Rear View Mirror



Toolkit



## Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<65%

LHS Rear Tyre

<65%

RHS Front Tyre

<65%

RHS Rear Tyre

<65%

Spare Tyre

<45%



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE